

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19019503/AGVF3E2

Date: 20/05/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29088463

Claimant Vehicle No : SMM9349M

Insured Vehicle No : SLN5616A

Date of Loss: 31/10/2019

Nature of Claim: TP Claim No: 610463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM9349M**

Make & Model: MERCEDES-BENZ C180, 1.6 (A)

Engine No: 27491030174566

Reg. Date: 03/09/2014 (Man. Year: 2014)

Chassis No: WDD2043312G327707

Colour: Grey

Odometer: 54033 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,374.07	8,861.13	9,512.94	51.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,440.00	2,740.00	65.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,554.07	10,301.13	12,252.94	54.33
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	22,554.07	8,200.00	14,354.07	63.64

INSPECTION

Date of Assignment: 04/11/2019

Date Inspected: 05/11/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley
Biz Centre
Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9349M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,391.00 FL	*1,391.00 FL
2	1		*FRONT BUMPER SIDE BRACKET LH & RH	O/S Cracked	260.00 FL	*135.00 FL
3	1		*FRONT BUMPER LOWER BRACKET RH	Bent	110.00 FL	*110.00 FL
4	1		*FRONT BUMPER LOWER GARNISH (INNER)	Deformed	286.00 FL	*286.00 FL
5	1		*FRONT BUMPER FOGLAMP GARNISH RH	Cracked	155.00 FL	*155.00 FL
6	1		*FRONT BUMPER LOWER LAMP RH	Cracked	325.00 FL	*325.00 FL
7	1		*FRONT BUMPER LOWER CHROME	Cracked	210.00 FL	*210.00 FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	110.00 FL	*- FL
9	1		*FRONT BUMPER LOWER LAMP CHROME RH	Not Necessary	195.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	855.00 FL	*678.00 FL
11	1		*FRONT HEADLAMP RH	Cracked	3,345.10 FL	*1,610.00 FL
12	2		*FRONT HEADLAMP CONTROL UNIT LH & RH	Not Necessary	1,143.00 FL	*- FL
13	1		*FRONT BONNET	Repair	1,999.27 FL	*- FL
14	1		*FRONT RADIATOR GRILLE STAR HOLDER	Not Necessary	75.60 FL	*- FL
15	1		*FRONT RADIATOR GRILLE TRIM	Not Necessary	198.00 FL	*- FL
16	1		*FRONT RADIATOR GRILLE	Cracked	658.00 FL	*658.00 FL
17	1		*FRONT RADIATOR GRILLE MERCEDES STAR	Necessary	138.00 FL	*138.00 FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	740.10 FL	*- FL
19	1		*FRONT FENDER LH & RH	O/S Deformed	1,851.20 FL	*925.60 FL
20	1		*FRONT FENDER INNER SHIELD LH & RH	O/S Deformed	250.00 FL	*125.00 FL
21	1		*FRONT CROSS MEMBER	Not Necessary	436.50 FL	*- FL
22	1		*FRONT SHOCK ABSORBER RH	Bent	355.00 FL	*355.00 FL
23	2		*FRONT KNUCKLE ARM RH	Bent	342.00 FL	*342.00 FL
24	1		*FRONT WHEEL HUB LH & RH	O/S Damaged	590.20 FL	*295.10 FL
25	1		*FRONT WHEEL HUB BEARING LH & RH	O/S Necessary	442.00 FL	*221.00 FL
26	1		*FRONT CONTROL ARM LH & RH	O/S Bent	332.00 FL	*166.00 FL
27	1		*FRONT UNDERCARRIAGE COVER	Torn	185.00 FL	*185.00 FL
28	1		*FRONT LOWER ARM RH	Bent	135.00 FL	*135.00 FL
29	1		*FRONT COOLANT TANK	Not Necessary	125.00 FL	*- FL
30	1		*FRONT TIE ROD ARM RH	Not Necessary	250.00 FL	*- FL
31	1		*FRONT BAR LINKAGE RH	Not Necessary	246.00 FL	*- FL
32	1		*FRONT ABS SENSOR	Not Necessary	155.00 FL	*- FL
33	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	70.00 FS	*30.00 FS
34	1		*FRONT RIM RH	Cut	1,674.00 FS	*1,200.00 FS
35	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
36	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	1		*SET FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,162.97 9,705.70

- List Item Discount on L Items 10.00/10.00% (\$\$) 1,788.90 844.57

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	18,374.07
						8,861.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	600.00
2	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
3	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
4	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	200.00	0.00
5	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT	New	120.00	80.00
6	TO REMOVE AND REPLACE FRONT HEADLAMP BEAM	New	80.00	30.00
7	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET MERCEDES SPECIFICATION	New	250.00	100.00
8	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	600.00
Gross Labour Cost (S\$)			4,180.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >