

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19019515/UBA3Q2

**Date:** 06/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

### Claimant

**Vehicle No :** SDL9000E

**Insured Vehicle No :** SGG221J

Date of Loss: 02/11/2019

Nature of Claim: TP

Claim No: 7576264442SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDL9000E**

Make & Model: TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)

Engine No: 2ARJ071492

Reg. Date: 05/10/2018 (Man. Year: 2018)

Chassis No: AGH300184418

Colour: White

Odometer: 19018 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Toyo 7 mm

Rear Left Side:

Toyo 7 mm

Front Right Side: Toyo 7 mm

Rear Right Side:

Toyo 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,795.59	3,489.24	3,306.35	48.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,540.00	2,190.00	58.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,525.59</b>	<b>5,029.24</b>	<b>5,496.35</b>	<b>52.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,525.59</b>	<b>4,000.00</b>	<b>6,525.59</b>	<b>62.00</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		750.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>4,786.45</b>		

### INSPECTION

Date of Assignment: 04/11/2019

Date Inspected: 05/11/2019 Inspected At:

BLK 15 KAKI BUKIT BROAD

4 ,BARTLEY BIZ #01-53

Repairer: Zoom Autowerks Pte Ltd

(HQ)

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Necessary	85.00 FL	*85.00 FL
2	1		*REAR TAILGATE	Dented / Warped	1,593.98 FL	*1,593.98 FL
3	1		*REAR TAILGATE LOCK	Not Necessary	350.90 FL	*- FL
4	1		*REAR TAILGATE RUBBER	Not Necessary	300.40 FL	*- FL
5	1		*REAR TAILGATE VELLFIRE EMBLEM	Necessary	75.76 FL	*75.76 FL
6	1		*REAR END PANEL	Repair	755.60 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH SIDE	Twisted	265.90 FL	*265.90 FL
8	1		*REAR BUMPER	Distorted	1,575.88 FL	*1,575.88 FL
9	1		*REAR BUMPER SIDE O/S	Deformed / Torn	685.00 FL	*685.00 FL
10	1		*REAR BUMPER BRACKET O/S	Dented	120.10 FL	*120.10 FL
11	1		*REAR BUMPER REFLECTOR	Cracked	85.70 FL	*85.70 FL
12	1		*REAR BUMPER SIDE RETAINER	Serviceable	115.33 FL	*- FL
13	2		*REAR BUMPER PDC SENSORS	Serviceable	1,040.60 FL	*- FL
14	1		*REAR BUMPER TOW HOOK COVER	Torn	45.00 FL	*45.00 FL
15	1		*REAR SMART KEYLESS KEYLESS SENSOR	Not Necessary	235.00 FL	*- FL
16	1		*REAR FENDER	Repair	1,557.30 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,017.45</b>	<b>4,622.32</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,221.86	1,133.08
<b>Total Parts (\$)</b>	<b>6,795.59</b>	<b>3,489.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	150.00	30.00
7	PANEL BEATING	New	1,500.00	500.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	680.00
<b>Gross Labour Cost (S\$)</b>			<b>3,730.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >