

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119019518/ETF3E2

Date: 05/05/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30841219033

Claimant Vehicle  
No : SGV5800BInsured  
Vehicle No : SKK3752E

Date of Loss: 25/10/2019

Nature of  
Claim: TPClaim  
No: SNM19D205110-  
SKK3752E/TKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV5800B**

Make &amp; Model: HONDA FIT, 1.3 L (A)

Engine No: L13A2311392

Reg. Date: 20/06/2007 (Man. Year: 2007)

Chassis No: GD12388757

Colour: Black

Odometer: 219216 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,330.00	1,172.00	158.00	11.88
Miscellaneous Items	405.00	280.00	125.00	30.86
Paintwork Materials	234.18	234.18	0.00	0.00
Labour	436.80	407.40	29.40	6.73
Paintwork Labour	541.80	541.80	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,947.78</b>	<b>2,635.38</b>	<b>312.40</b>	<b>10.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>(S\$)</b>	2,947.78	2,100.00	847.78	28.76
<b>+ GST 7.00/7.00% (S\$)</b>	206.34	147.00	59.34	28.76
<b>Nett Amount (S\$)</b>	<b>3,154.12</b>	<b>2,247.00</b>	<b>907.12</b>	<b>28.76</b>

### INSPECTION

Date of Assignment:	05/11/2019 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	07/11/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)

Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Estimated Period of Repair: 5.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2020)
<b>Parts:</b>	144	HONDA FIT 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGV5800B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		1,330.00 F	*1,172.00 F
						F=Franchise part.
<b>Total Parts (S\$)</b>					<b>1,330.00</b>	<b>1,172.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b><u>Materials</u></b>				
1	1	TOTAL PAINTS / MATERIAL	234.18	234.18
<b><u>Miscellaneous Items</u></b>				
2	1	SPARE PARTS SPECIAL NETT	405.00	280.00
<b>Sub Total (\$\$)</b>			<b>639.18</b>	<b>514.18</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	TOTAL PAINTWORK	New	541.80	541.80
<b><u>Labour Items</u></b>				
2	TOTAL PANEL / MECHANICAL	New	436.80	407.40
<b>Gross Labour Cost (\$\$)</b>			<b>978.60</b>	<b>949.20</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >