

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date : 01/11/2019

Reference: CHEVROLET

Make: ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLM8287B
CHASSIS NO.: KL1YA7589HK614556
ENGINE NO.: B14NET170180095

Name of insured : GOH KENG SIANG

Date of accident.: 26/10/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT FENDER LH <i>Dented</i>	\$ 1,243.00
2	1	FRT FENDER BRACKET LH <i>new</i>	\$ 128.00
3	1	FRT FENDER INNERSHIELD LH <i>new</i>	\$ 268.00
4	1	FRT FENDER TOP GARNISH LH <i>new</i>	\$ 88.00
5	1	FRT FENDER WHEELARCH GARNISH LH <i>Dented</i>	\$ 152.00
6	1	FRT BUMPER <i>new</i>	\$ 1,406.00
7	1	FRT BUMPER LOWER <i>new</i>	\$ 516.00
8	1	FRT BUMPER SIDE RETAINER LH, SUPPORT	\$ 133.00
9	1	FRT BUMPER SIDE RETAINER RH, SUPPORT	\$ 133.00
10	1	FRT BUMPER BRACKET LH, GUIDE	\$ 111.00
11	1	FRT BUMPER BRACKET RH, GUIDE	\$ 111.00
12	1	FRT BUMPER SPONGE	\$ 263.00
13	1	FRT BUMPER LOGO	\$ 158.00
14	1	FRT BUMPER FOG LAMP COVER LH <i>new</i>	\$ 113.00
15	1	FRT BUMPER FOG LAMP LH	\$ 330.00
16	1	LH HEADLAMP	\$ 983.00
17	1	FRT WIPER WASHER TANK <i>new</i>	\$ 249.00
18	1	FRT HORN LH	\$ 264.00
19	1	FRT KNUCKLE ARM LH	\$ 417.00
20	1	FRT WHEEL BEARING LH	\$ 587.00
21	1	FRT LOW ARM LH	\$ 928.00
22	1	FRT SHOCK ABSORBER LH	\$ 443.00
23	1	FRT STABILIZER LINK LH	\$ 142.00
24	1	Frt LH Door <i>Dented</i>	\$ 1,700.00
25	1	Frt LH Door Black Sticker <i>new</i>	\$ 196.00
26	1	Frt LH Door Protector <i>Dented</i>	\$ 151.00
27	1	Frt LH Door Weatherstrip <i>new</i>	\$ 253.00
28	1	Frt LH Door Glass Outer Moulding <i>new</i>	\$ 247.00
29	1	Frt LH Door Checker <i>new</i>	\$ 107.00
30	1	Frt LH Wing Mirror Assy <i>new</i>	\$ 1,081.00

1030

3229
2906.10

Parts Total: \$ 12,901.00
Less 10%: \$ 1,290.10
Total: \$ 11,610.90

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT FENDER LH, FRT DOOR LH, FRT BONNET, LH WING MIRROR	\$ 1,200.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
4	To conduct anti rust of under carriage tuff coat	\$ 100.00
5	To remove and replace LHF under carriage parts	\$ 300.00
6	To conduct 4 wheel alignment	\$ 180.00
7	To refocus headlamp	\$ 80.00
8	To conduct transfer front door mechanism to new door panel	\$ 200.00

600
600
30
+
+
80
+
80

1390

Labour Total: \$ 3,380.00

Others

No.	Other Description	Price (SGD)
1	10 FRT BUMPER CLIP	\$ 40.00
2	10 FRT FENDER INNER SHIELD CLIP	\$ 40.00
3	10 FRT WHEELARCH CLIP	\$ 40.00
4	1 FRT TYRE LH	\$ 300.00
5	1 FRT RIM LH	\$ 350.00

30
+
20
+
✓

400

Other Total: 770.00

TOTAL: 15,760.90

GRAND TOTAL: 15,760.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Eric Tan
HP: 8266 1132

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
P/P 04/11/19
05 Days
total: 4696.10 (P/P)