

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19019527/BGA3Q2**Date:** 08/04/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033019
Claimant
Vehicle No : SGG6609K **Insured Vehicle No :** SLX5901Z
Date of Loss: 02/11/2019 Nature of Claim: TP Claim No: 8911841979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG6609K**
Make & Model: HONDA EDIX, 1.7 (A) Engine No: BE11102023
Reg. Date: 19/05/2006 (Man. Year: 2006) Chassis No: D17A4052278
Colour: Red Odometer: 146994 km
Engine Capacity: 1668 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Greenways 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Greenways 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 7,046.32 | 3,430.08 | 3,616.24 | 51.32 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,090.00 | 1,910.00 | 2,180.00 | 53.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,136.32 | 5,340.08 | 5,796.24 | 52.05 |
| Approved Total (Overridden) (S\$) | | 4,250.00 | | |
| Nett Amount (S\$) | 11,136.32 | 4,250.00 | 6,886.32 | 61.84 |
| + Car Rental (8.0 x S\$120.00/day) (S\$) | | 960.00 | | |
| | | 5,210.00 | | |

INSPECTION

Date of Assignment: 04/11/2019
Date Inspected: 05/11/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|----------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Dented | 1,168.90 FL | *1,168.90 FL |
| 2 | 1 | | *TAILGATE INNER LOCK | Not Damaged | 288.60 FL | *- FL |
| 3 | 1 | | *TAILGATE STIKER | Not Damaged | 48.90 FL | *- FL |
| 4 | 1 | | *TAILGATE WEATHERSTRIP | Torn | 165.60 FL | *147.00 FL |
| 5 | 1 | | *TAILGATE INNER TRIM BOARD | Not Damaged | 296.30 FL | *- FL |
| 6 | 1 | | *TAILGATE INNER HANDLE | Not Damaged | 36.00 FL | *- FL |
| 7 | 1 | | *TAILGATE OUTER CHROME GARNISH | Not Damaged | 198.00 FL | *- FL |
| 8 | 2 | | *TAILGATE NO PLATE LAMP | Not Damaged | 177.00 FL | *- FL |
| 9 | 1 | | *TAILGATE WINDSCREEN MOULDING | Necessary | 90.50 FL | *90.50 FL |
| 10 | 1 | | *REAR BUMPER | Broken | 680.90 FL | *680.90 FL |
| 11 | 2 | | *REAR BUMPER SIDE RETAINER | Necessary | 97.20 FL | *97.20 FL |
| 12 | 2 | | *REAR BUMPER BRACKET | Bent | 79.20 FL | *79.20 FL |
| 13 | 1 | | *REAR END PANEL | Dented | 525.60 FL | *525.60 FL |
| 14 | 1 | | *REAR END PANEL TOP GARNISH | Dislodged | 124.80 FL | *124.80 FL |
| 15 | 1 | | *TAILLAMP RH | Broken | 386.00 FL | *386.00 FL |
| 16 | 1 | | *TAILLAMP LOWER BRACKET RH | Not Damaged | 48.40 FL | *- FL |
| 17 | 1 | | *TAILLAMP BASE PANEL RH | Not Damaged | 138.00 FL | *- FL |
| 18 | 1 | | *TAILLAMP LH | Not Damaged | 386.00 FL | *- FL |
| 19 | 1 | | *TAILLAMP BRACKET LH | Not Damaged | 48.40 FL | *- FL |
| 20 | 1 | | *TAILLAMP PANEL LH | Not Damaged | 138.00 FL | *- FL |
| 21 | 1 | | *EXHAUST PIPE | Not Damaged | 728.20 FL | *- FL |
| 22 | 2 | | *EXHAUST PIPE MOUNTING | Not Damaged | 76.40 FL | *- FL |
| 23 | 1 | | *EXHAUST PIPE HEAT SHIELD | Not Damaged | 156.00 FL | *- FL |
| 24 | 1 | | *SUNDRIES | Not Applicable | 60.00 FS | *- FS |
| 25 | 1 | | *REAR BUMPER CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 26 | 1 | | *REAR END PANEL TOP GARNISH CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 27 | 1 | | *TAILGATE INNER TRIM BOARD CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 28 | 1 | | *TAILGATE OUTER GARNISH CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 29 | 1 | | *TAILGATE WINDSCREEN CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 30 | 1 | | *TAILGATE PRIMER AND CLEANER | Not Necessary | 80.00 FS | *- FS |
| 31 | 1 | | *TAILGATE WINDSCREEN SEALANT | Necessary | 100.00 FS | *50.00 FS |
| 32 | 1 | | *REAR NO PLATE WITH COVER | Not Damaged | 80.00 FS | *- FS |
| 33 | 2 | | *REAR BUMPER REVERSE SENSOR | Cut | 400.00 FS | *200.00 FS |
| 34 | 1 | | *REAR END PANEL SEALANT | Necessary | 100.00 FS | *60.00 FS |
| 35 | 1 | | *WRAP | Necessary | 800.00 FS | *300.00 FS |
| 36 | 1 | | *TAILLAMP CLIPS | Necessary | 50.00 FS | *30.00 FS |
| 37 | 2 | | *TAILLAMP INNER SEAL | Not Necessary | 160.00 FS | *- FS |
| 38 | 1 | | *SPARE TYRE PANEL SEALANT | Not Necessary | 100.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 8,262.90 | 4,090.10 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 1,216.58 | 660.02 |
| Total Parts (\$) | 7,046.32 | 3,430.08 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | R&R TAILGATE COMPONENT | New | 100.00 | 50.00 |
| 2 | R&R REAR WINDSCREEN | New | 250.00 | 120.00 |
| 3 | R&R UPHOLSTERY | New | 180.00 | 0.00 |
| 4 | R&R EXHAUST PIPE ASSY | New | 250.00 | 0.00 |
| 5 | R&R REVERSE SENSOR | New | 80.00 | 60.00 |
| 6 | DISCONNECT WIRE HARNESS TO FACILITATE REPAIR ,RECONNECT AND CHECK FUNCTION | New | 80.00 | 30.00 |
| 7 | PANEL BEAT | New | 1,500.00 | 800.00 |
| 8 | RUST PROOFING | New | 150.00 | 50.00 |
| 9 | SPRAY PAINTING | New | 1,500.00 | 800.00 |
| Gross Labour Cost (S\$) | | | 4,090.00 | 1,910.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >