

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019529/BKA3Q2

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKM6725D

Insured Vehicle No : SFV90C

Date of Loss: 04/11/2019

Nature of Claim: TP

Claim No: 8586092100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM6725D**

Make & Model: HONDA STREAM, 1.8 L RSZ (A)

Engine No: R18A13850436

Reg. Date: 30/03/2010 (Man. Year: 2009)

Chassis No: JHMRN68809C200436

Colour: Black

Odometer: 230582 km

Engine Capacity: 1799 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,463.20	4,407.68	4,055.52	47.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,470.00	1,990.00	57.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,923.20	5,877.68	6,045.52	50.70
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	11,923.20	4,700.00	7,223.20	60.58
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,296.45		
Global Sum Settlement (S\$)		5,290.00		

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin

Ming (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,460.00 FL	*903.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*48.00 FL
3	1		*TAILGATE EMBLEM STREAM	Necessary	98.00 FL	*31.60 FL
4	1		*TAILGATE EMBLEM RSZ	Necessary	78.00 FL	*38.80 FL
5	1		*TAILGATE INNER TRIM BOARD	Broken	489.00 FL	*489.00 FL
6	1		*TAILGATE WEATHERSTRIP	Cut	188.00 FL	*188.00 FL
7	1		*TAILGATE LOCK CATCH	Not Damaged	86.00 FL	*- FL
8	1		*TAILGATE OUTER GARNISH	Dislodged	187.00 FL	*187.00 FL
9	1		*TAILGATE OUTER HANDLE	Not Damaged	89.00 FL	*- FL
10	1		*TAILGATE WIPER MOTOR ASSY	Not Damaged	428.00 FL	*- FL
11	2		*TAILGATE DAMPER	Not Damaged	572.00 FL	*- FL
12	2		*TAILGATE HINGES	Not Damaged	332.00 FL	*- FL
13	1		*REAR TAILLAMP RH	Broken	688.00 FL	*581.90 FL
14	10		*REAR TAILLAMP CLIPS RH	Necessary	50.00 FL	*30.00 FL
15	1		*REAR END PANEL	Dented	785.00 FL	*630.00 FL
16	1		*REAR END PANEL TOP GARNISH	Dented	188.00 FL	*188.00 FL
17	1		*REAR BUMPER ASSY	Broken	1,385.00 FL	*665.40 FL
18	2		*REAR BUMPER BRACKET	Bent (1 PCS ONLY)	216.00 FL	*108.00 FL
19	1		*REAR BUMPER TOWING COVER	Not Damaged	88.00 FL	*- FL
20	2		*REAR BUMPER RETAINER	Necessary	152.00 FL	*97.00 FL
21	1		*SPARE TYRE BRACKET	Not Damaged	286.50 FL	*- FL
22	1		*REAR EXHAUST ASSY	Broken	865.40 FL	*567.00 FL
23	1		*REAR EXHAUST MOUNTING	Bent	68.90 FL	*54.40 FL
24	1		*REAR EXHAUST MUFFLER TIP	Bent	156.20 FL	*115.00 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*30.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	120.00 FS	*120.00 FS
31	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
32	4		*REAR BUMPER REVERSE SENSOR	Cut	600.00 FS	*200.00 FS
33	1		*STICKER	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,264.00 5,392.10
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,800.80 984.42

Total Parts (\$\$) 8,463.20 4,407.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	1,400.00	600.00
2	SPRAY PAINTING	New	1,400.00	600.00
3	RUST PROOFING	New	100.00	50.00
4	CHECK WIRING	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	50.00	0.00
6	R&R TAILGATE COMPONENT	New	140.00	60.00
7	R&R REAR WINDSCREEN	New	140.00	80.00
8	R&R EXHAUST PIPE	New	150.00	50.00
Gross Labour Cost (\$\$)			3,460.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >