

ADVANCE AUTO GARAGE

23 Kaki Bukit Avenue 4
VICOM KAKI BUKIT INSPECTION CENTRE
#04-01 SINGAPORE 415933
Tel: +65 9007 9247
Email: advanceag@hotmail.com
Reg No: 53395571L

TO	: EQ INSURANCE	DATE	: 4/10/2019
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:	<i>Xiao Tony</i>	
VEHICLE DETAILS			
VEHICLE NO	: SJF734R	<i>WBASA32060D333925</i>	
VEHICLE MODEL	: BMW 520i		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE: 9/10/2019 TIME: 1800HRS		
THIRD PARTY REQUESTOR / CONTACT	:	XAIVER	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BOOT <i>Dented</i>	1	\$ 1,750.00	\$ 1,750.00
2	BOOT LOGO <i>new</i>	1	\$ 200.00	\$ 200.00
4	BOOT LOCK <i>Damaged</i>	1	\$ 180.00	\$ 180.00
5	BOOT LOCK CATCH <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR NUMBER PLATE LAMP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
6	REAR BOOT INNER TRIM BOARD <i>new</i>	1	\$ 200.00	\$ 200.00
7	BOOT WEATHER STRIPE <i>new</i>	1	\$ 250.00	\$ 250.00
9	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 100.00	\$ 200.00
11	REAR BUMPER CENTER RETAINER <i>new</i>	1	\$ 150.00	\$ 150.00
12	REAR BUMPER REFLECTOR <i>2H ended</i>	2	\$ 120.00	\$ 240.00
13	REAR BUMPER REFLECTOR BRACKET <i>new</i>	2	\$ 50.00	\$ 100.00
14	REAR INNER TAIL LIGHT <i>new</i>	2	\$ 420.00	\$ 840.00
15	REAR INNER TAIL LIGHT BRACKET <i>new</i>	2	\$ 30.00	\$ 60.00
14	REAR OUTER TAIL LIGHT <i>new</i>	2	\$ 700.00	\$ 1,400.00
16	REAR BUMPER REINFORCEMENT BAR <i>Best</i>	1	\$ 870.00	\$ 870.00
18	SMART ADAPTER <i>new</i>	1	\$ 87.00	\$ 87.00
18	REAR END PANEL <i>Repair</i>	1	\$ 900.00	\$ 900.00
19	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 160.00	\$ 160.00
20	TAILGATE KICK SENSOR MODULE <i>ended</i>	1	\$ 1,500.00	\$ 1,500.00

covers
TOTAL PRICE: \$ 9,317.00
LESS 5% \$ 465.85

Bumper under cover.

ended

158

3761

3572.55

1593
120

120

715

525

SUB TOTAL PRICE: \$ 8,851.15

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER MPERFORMANCE <i>could</i>	1	\$ 1,800.00	\$ 1,800.00
3	REAR MPERFORMANCE CARBON FIBRE DIFFUSER <i>could</i>	1	\$ 1,500.00	\$ 1,500.00
4	REVERSE SENSOR <i>only 1 piece</i>	4	\$ 220.00	\$ 880.00
4	REVERSE SENSOR BRACKET <i>new</i>	4	\$ 50.00	\$ 200.00
4	REAR BOOT CARBON FIBRE SPOILER M4 DESIGN <i>new</i>	1	\$ 1,200.00	\$ 1,200.00
5	REAR BUMPER CLIP (SET) <i>new</i>	3	\$ 20.00	\$ 60.00
6	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00

3100

TOTAL: \$ 5,830.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	1600 800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1600 750	
3	WIRING CHECK (REVERSE CAMERA)	\$ 100.00	100 40	
4	TUFF COAT	\$ 120.00	x	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	100 60	
6	WATER LEAKAGE TEST	\$ 80.00	x	
7	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATIONS	\$ 300.00	300 100	

TOTAL: \$ 3,900.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 14,681.15

TOTAL LABOUR COST: \$ 3,900.00

TOTAL REPAIR COST: 18,581.15

APPROVED DETAILS

SURVEYOR:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/s 04/11/19
04 Days

Total 8122.850

H/s: 6.5K

6.5K

1450