Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019623/EEA3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100368602-05 Claimant SHC4193P

Insured Vehicle No: SJH5380J Vehicle No:

Date of Loss: Nature of Claim: TP 03/11/2019 Claim No: 8601882100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHC4193P Reg No:

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR5882856

Reg. Date: 29/11/2013 (Man. Year: 2013) Chassis No: JTDKN36U905708983

Colour: Odometer: 782148 km Maroon

Engine Capacity: 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15 Front Left Side: Neuton 5 mm Rear Left Side: Neuton 5 mm Neuton 5 mm Front Right Side: Rear Right Side: Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,386.70	1,090.81	1,295.89	54.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,356.00	540.00	816.00	60.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,742.70	1,630.81	2,111.89	56.43
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	3,742.70	1,400.00	2,342.70	62.59
+ Car Rental (4.0 x S\$10	04.86/day) (S\$)	419.44		
+ Doc/Se	earch Fee (S\$)	7.00		
Net	tt Liability (S\$)	1,826.44		

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: Asher Sng Rong Yi Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
2	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
3	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
4	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
5	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
6	1		*BUMPER LIP REAR	Not Necessary	essary 228.90 F	
7	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
8	1		*BUMPER CLIPS (10 PCS) (DISC 25%)	Necessary	cessary 16.10 F	
9	2		*PIXEL STICKER (SN)	Necessary	Necessary 120.00 F	
10	1		*ANTENNA,ELECTRICAL LOWER REAR	Not Necessary 157.40		*- F
11	1		*SENSOR REVERSE (SN)	Shorted 180.00 F		*180.00 F
12	1		*BUMPER SEAL, RR LH	Not Necessary 88.90 F		*- F
13	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
14	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent 139.60 F		*104.70 F
15	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
F=Fra	F=Franchise part.					
				Total Parts (S\$)	2,386.70	1,090.81

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
2	TO REPLACE SUNDRY PARTS	New	100.00	20.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	SPRAY PAINT	New	738.00	300.00
5	PANEL BEATING & BODY WORK	New	338.00	200.00
	Gross I	Labour Cost (S\$)	1,356.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >