

Case Details

Case Reference Number : TAX/11/19/2006
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4193P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-9164-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 03/11/2019 05:45 AM
 Vehicle Age(In Months) : 72

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾	✓ 00
Standard	Main		6505547	BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check ▾	X NM
Standard	Main		6505546	ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾	X NM
Standard	Main		6505545	ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾	X NM
Standard	Main		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾	✓ BR
Standard	Main		6505619	BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give ▾	X NM
Standard	Main		6505617	BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give ▾	X NM
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	✓ NCC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	✓ NCC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check ▾	X NM
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾	✓ SHM
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give ▾	X NM
Total Spare Part Cost									1,524.97	Surveyor Total		727.13		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									1,176.66	Final Sur Total		581.70		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			338.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	✓ n/c
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ n/c
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			280.00	40.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,176.66	581.70
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	280.00	40.00
Overall Total	2,352.66	1,021.70
Lump Sum Repair Option	☒	☒
Lump Sum Total	2,350.00	1,000.00
Surveyor Approved Amount		1,000.00
No of Repair Days*	3	2
Remarks	-	Lumpsum repair, take after spray.
Surveyor Name		STEVE CHEN

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature

A handwritten signature in black ink, consisting of a long horizontal stroke followed by a large, stylized 'S' shape.

Save

Clear

Survey Date

05/11/2019