Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019626/KPA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800122740

Claimant Vehicle No: SHD95K Insured Vehicle No: SMF1253U

Date of Loss: 02/11/2019 Nature of Claim: TP Claim No: 6403163513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD95K

 Make & Model:
 RENAULT LATITUDE, 2.0 L (A)
 Engine No:
 M9R8839C002652

 Reg. Date:
 14/08/2015 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC282163

Colour: Metallic White/Red Odometer: 462075 km

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1995 сс

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 9 mm Rear Left Side: Giti 8 mm
Front Right Side: Sailun 9 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,454.35	2,543.85	7,910.50	75.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,510.00	1,430.00	13,080.00	90.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	24,964.35	3,973.85	20,990.50	84.08
Approved Total (Overridden) (S\$	5)	3,200.00		
(\$\$	24,964.35	3,200.00	21,764.35	87.18
+ GST 7.00/7.00% (S\$	1,747.50	224.00	1,523.50	87.18
Nett Amount (S\$	26,711.85	3,424.00	23,287.85	87.18
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x	+ Car Rental (3.5 x S\$81.13/day) (S\$)			
+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)			
Global Sum Settlement (S\$)		3,890.00		

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111 Adjuster Report Page 2 of 5

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*-FL
13	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*-FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*-FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*-FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*-FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*-FL
19	1		*BOOT REAR	Repair	1,677.20 FL	*-FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*-FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*-FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*-FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
25	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*-FL
31	2		*BOOT BUFFER	Serviceable	26.80 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*-FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*-FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
36	1		*BOOT LOCK	Repair	246.60 FL	*-FL
37	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
38	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
39	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
40	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
41	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
42	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
43	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
44	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
45	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
47	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
49	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
50	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
52	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
53	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
			Report was unsubmitted during thi			
				1		

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
56	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
57	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
58	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*-FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	'		
				Sub Total (S\$)	11,451.26	2,801.50
- List Item Discount on L Items 10.00/10.00% (S\$)			996.91	257.65		
				Total Parts (S\$)	10,454.35	2,543.85
			Report was unsubmitted during this	print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	60.00
TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	30.00
TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
TO TRANSFER PF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	600.00
TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
TO CHECK GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	660.00
Gross Labour Cost (S\$)		14,510.00	1,430.00
	AND PERFORM WATER SEEPAGE TEST. TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. TO RUST-PROOFING OF THE AFFECTED AREAS. TO CHECK ELECTRICAL LIGHTING CONCERNED. TO TRANSFER PF TIRE, RIM AND ON WHEEL BALANCING. TO REINSTALL REAR BUMPER PARKING SENSOR. PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR. TO CHECK GEOMETRY AND COMPUTER WHEEL ALIGNMENT. TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO REPAIR AND REALIGN REAR EXHAUST PIPE. LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. TO RUST-PROOFING OF THE AFFECTED AREAS. TO CHECK ELECTRICAL LIGHTING CONCERNED. TO TRANSFER PF TIRE, RIM AND ON WHEEL BALANCING. TO REINSTALL REAR BUMPER PARKING SENSOR. PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR. TO CHECK GEOMETRY AND COMPUTER WHEEL ALIGNMENT. TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO REPAIR AND REALIGN REAR EXHAUST PIPE. New LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. PUTTY AND SPRAY PAINTING OF THE AFFECTED New PORTION.	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. TO RUST-PROOFING OF THE AFFECTED AREAS. TO CHECK ELECTRICAL LIGHTING CONCERNED. TO TRANSFER PF TIRE, RIM AND ON WHEEL BALANCING. TO REINSTALL REAR BUMPER PARKING SENSOR. New 170.00 PANEL BEATING, KNOCKING AND STRAIGHTENING THE NEW 6,000.00 PARTS, ADJUST AND REALIGN THE SAME. TO TRANSFER OF REAR END PANEL FITTINGS, NEW 170.00 ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO TRANSFER OF REAR WINDSCREEN GLASS TO NEW 170.00 FACILITATE BODYWORK REPAIR. TO CHECK GEOMETRY AND COMPUTER WHEEL New 220.00 ALIGNMENT. TO TRANSFER OF REAR BUMPER FITTINGS, NEW 170.00 ATTACHMENT AND PERFORM WATER SEEPAGE TEST. TO REPAIR AND REALIGN REAR EXHAUST PIPE. New 170.00 LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. PUTTY AND SPRAY PAINTING OF THE AFFECTED New 6,000.00 PORTION.

< END OF ESTIMATES >