

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19019641/UHA3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00001546-01

Claimant
Vehicle No : SJE7911E **Insured Vehicle No :** SGQ7114L

Date of Loss: 26/10/2019 Nature of Claim: TP Claim No: 1201900036554

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE7911E	Engine No:	3ZZ4758542
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106106550
Reg. Date:	08/05/2008 (Man. Year: 2008)	Odometer:	135511 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,474.47	4,605.15	1,869.32	28.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,940.00	1,040.00	34.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,454.47	6,545.15	2,909.32	30.77
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	9,454.47	5,200.00	4,254.47	45.00
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,836.45		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At:

T K Lee Automotive Pte Ltd (HQ)
NO. 1 KAKI BUKIT AVE 6 #02-47
AUTOBAY
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE7911E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	110.45 FL	*- FL
2	1		*REAR BUMPER	Torn	607.15 FL	*559.20 FL
3	1		*REAR BUMPER SIDE HOLDER RH/LH	N/S Bent	156.20 FL	*60.50 FL
4	1		*REAR BUMPER SIDE RETAINER RH/LH	N/S Bent	242.50 FL	*121.25 FL
5	1		*REAR FENDER LH	Badly Dented / Bent	981.25 FL	*981.25 FL
6	1		*REAR FENDER LOWER SHIELD LH	Torn	112.10 FL	*112.10 FL
7	1		*REAR SHOCK ABSORBER LH	Twisted	218.60 FL	*218.60 FL
8	1		*REAR AXLE	Bent / Twisted	2,017.10 FL	*2,017.10 FL
9	1		*REAR AXLE BEARING WITH HUB LH	Damaged	594.10 FL	*594.10 FL
10	1		*REAR DOOR LH	Repair	1,004.94 FL	*- FL
11	1		*REAR DOOR BLACK TAPE	Not Necessary	78.10 FL	*- FL
12	1		*REAR DOOR RUBBER LH	Not Necessary	166.35 FL	*- FL
13	1		*REAR DOOR PROTECTOR LH	Cut / Necessary	110.34 FL	*110.34 FL
14	1		*REAR DOOR PROTECTOR MOULDING LH	Not Necessary	54.35 FL	*- FL
15	1		*ROCKLE PANEL OUTER SIDE SKIRT RH	Distorted	659.10 FL	*659.10 FL
16	1		*REAR WINDSCREEN SPONGE TAPE	Not Necessary	20.00 FS	*- FS
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
19	1		*REAR SPORT RIM LH	Cut / Bent	680.00 FS	*450.00 FS
20	1		*REAR TYRE LH	Serviceable	280.00 FS	*- FS
21	1		*ROCKER PANEL OUTER SIDE SKIRT CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,252.63	5,963.54
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,778.16	1,358.39
Total Parts (\$\$)	6,474.47	4,605.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK OUT DENT ,CUT /WELD REAR FENDER LH AND REPLACE ACCIDENT PARTS	New	900.00	600.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	1,000.00	800.00
3	TO REMOVE REFIX REAR WINDSCREEN	New	120.00	0.00
4	TO REMOVE REFIX CUSHION AND INNER TRIM	New	120.00	80.00
5	TO REMOVE REFIX FUEL TANK	New	120.00	60.00
6	TO REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
7	TO TRANSFER REAR DOOR PARTS	New	100.00	0.00
8	TO REMOVE REPLACE REAR UNDERCARRIAGE	New	350.00	200.00
9	4 WHEEL ALIGNMENT	New	100.00	100.00
10	TO TUFF KOTE	New	90.00	50.00
Gross Labour Cost (\$)			2,980.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >