

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19019653/KPA3N2

Date: 21/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00010033

Claimant
Vehicle No : SLE7648S **Insured Vehicle No :** SLJ5990P

Date of Loss: 05/11/2019 Nature of Claim: TP Claim No: 1201900033956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7648S	Engine No:	27182030047948
Make & Model:	MERCEDES-BENZ C180, 1.8 CGI (A)	Chassis No:	WDD2040492A381119
Reg. Date:	28/06/2010 (Man. Year: 2010)	Odometer:	139955 km
Colour:	Metallic Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,227.17	5,164.61	7,062.56	57.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,170.00	2,370.00	66.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,767.17	6,334.61	9,432.56	59.82
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	15,767.17	5,000.00	10,767.17	68.29
+ GST 7.00/7.00% (S\$)	1,103.70	350.00	753.70	68.29
Nett Amount (S\$)	16,870.87	5,350.00	11,520.87	68.29
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,077.45		

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 06/11/2019 Inspected At:

Leong Auto Pte Ltd (HQ)
160 Sin Ming Drive, #02-13, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2020)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE7648S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,848.40 FL	*1,655.00 FL
2	1		*REAR BOOT LID CENTRE LOGO	Necessary	95.70 FL	*95.70 FL
3	1		*REAR BOOT LID C180 EMBLEM	Necessary	85.00 FL	*85.00 FL
4	1		*REAR BOOT LID CYCLE & CARRIAGE EMBLEM	Necessary	65.00 FL	*65.00 FL
5	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	200.10 FL	*- FL
6	1		*REAR BOOT LID LOCK MECHANISM	Repair	524.30 FL	*- FL
7	1		*REAR BOOT LID LOCK CATCH	Repair	84.50 FL	*- FL
8	1		*REAR BOOT LID CHROME MOULDING	Serviceable	241.20 FL	*- FL
9	1		*REAR END LOWER PANEL	Repair	1,143.70 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	389.50 FL	*135.00 FL
11	1		*REAR TAIL LAMP	O/S Cut / N/S	1,164.20 FL	*545.00 FL
12	1		*REAR SPARE TYRE PANEL TOP BOARD	Serviceable	511.50 FL	*- FL
13	1		*REAR BUMPER	Buckled	1,577.90 FL	*1,400.00 FL
14	1		*REAR BUMPER RETAINER	O/S Distorted	152.40 FL	*76.20 FL
15	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	156.80 FL	*120.00 FL
16	1		*REAR BUMPER LEFT SIDE CHROME MOULDING	Necessary	130.20 FL	*110.00 FL
17	1		*REAR BUMPER RIGHT SIDE CHROME MOULDING	Necessary	130.20 FL	*110.00 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	551.50 FL	*551.50 FL
19	1		*REAR EXHAUST MUFFLER	Repair	1,875.00 FL	*- FL
20	1		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Serviceable	104.90 FL	*- FL
21	1		*REAR EXHAUST MUFFLER CHROME FINISHER	Serviceable	228.80 FL	*- FL
22	1		*REAR EXHAUST HEAT SHIELD	Repair	262.50 FL	*- FL
23	1		*REAR EXHAUST BRACKET	Repair	83.50 FL	*- FL
24	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
25	1		*REAR BOOT LID AMG EMBLEM	Necessary	180.00 FS	*180.00 FS
26	1		*SET REAR BOOT LID INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	2		*SETS REAR EXHAUST HEAT SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*SET REAR SPARE TYRE TOOLS GARNISH SEALANT	Not Necessary	80.00 FS	*- FS
32	4		*REAR REVERSE SENSOR	Shorted (1 PCS ONLY)	850.00 FS	*220.00 FS
33	1		*REAR NO PLATE WITH GARNISH	Serviceable	80.00 FS	*- FS
34	1		*REAR BUMPER CENTRE RETAINER	Cracked	234.50 FL	*234.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	13,411.30	5,682.90
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,184.13	518.29
					Total Parts (S\$)	12,227.17	5,164.61
Report was unsubmitted during this print-out.							

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN AND REPLACE REAR DAMAGED PARTS	New	1,400.00	500.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	500.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR BOOT LID LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR SEAT ,INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	280.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	150.00	30.00
7	TO REMOVE AND INSTALL REAR REVERSE SENSOR	New	80.00	60.00
8	TO REMOVE AND INSTALL EXHAUST MUFFLER AND REAR EXHAUST CENTRE PIPE	New	180.00	0.00
9	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOTLID,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	New	120.00	0.00
Gross Labour Cost (\$\$)			3,540.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >