

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019684/AKA3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMJ5096J **Insured Vehicle No :** SKT7908A

Date of Loss: 31/10/2019 **Nature of Claim:** TP **Claim No:** 0555746296SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMJ5096J | Engine No: | R16B25502850 |
| Make & Model: | HONDA CIVIC, 1.6 VTI CVT (A) | Chassis No: | MRHFC5650JT002435 |
| Reg. Date: | 08/03/2019 (Man. Year: 2018) | Odometer: | 11948 km |
| Colour: | Blue | | |
| Engine Capacity: | 1597 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 215/55 R16 | Rear Tyre Size: | 215/55 R16 |
| Front Left Side: | Hankook 6 mm | Rear Left Side: | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 6,271.84 | 2,118.72 | 4,153.12 | 66.22 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,380.00 | 1,690.00 | 2,690.00 | 61.42 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 10,651.84 | 3,808.72 | 6,843.12 | 64.24 |
| Approved Total (Overridden) (\$\$) | | 3,000.00 | | |
| (\$\$) | 10,651.84 | 3,000.00 | 7,651.84 | 71.84 |
| + GST 7.00/7.00% (\$\$) | 745.63 | 210.00 | 535.63 | 71.84 |
| Nett Amount (\$\$) | 11,397.47 | 3,210.00 | 8,187.47 | 71.84 |
| Global Sum Settlement (\$\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 06/11/2019

Date Inspected: 06/11/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|------------|------------|
| 1 | 1 | | *SIDE SKIRT LH | Deformed | 355.90 FL | *355.90 FL |
| 2 | 1 | | *FRONT DOOR LH | Repair | 980.00 FL | *- FL |
| 3 | 1 | | *REAR DOOR LH | Dented | 950.00 FL | *950.00 FL |
| 4 | 1 | | *REAR BUMPER | Torn | 680.00 FL | *680.00 FL |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER | Not Necessary | 55.90 FL | *- FL |
| 6 | 1 | | *REAR FENDER | Repair | 941.50 FL | *- FL |
| 7 | 1 | | *REAR FENDER INNER COWLING | Not Necessary | 93.00 FL | *- FL |
| 8 | 1 | | *REAR LOWER ARM LH | Not Necessary | 384.40 FL | *- FL |
| 9 | 1 | | *REAR UPPER ARM LH | Not Necessary | 280.00 FL | *- FL |
| 10 | 1 | | *REAR SWING ARM LH | Not Necessary | 355.00 FL | *- FL |
| 11 | 1 | | *REAR SHOCK ABSORBER LH | Not Necessary | 324.10 FL | *- FL |
| 12 | 1 | | *REAR WHEEL HUP WITH BEARING LH | Not Necessary | 290.00 FL | *- FL |
| 13 | 1 | | *SET SIDE SKIRT CLIP | Necessary | 20.00 FS | *20.00 FS |
| 14 | 1 | | *SET REAR BUMPER CLIP | Not Necessary | 20.00 FS | *- FS |
| 15 | 1 | | *REAR FENDER SEALANT | Not Necessary | 80.00 FS | *- FS |
| 16 | 1 | | *SET REAR FENDER INNER COWLING CLIPS | Not Necessary | 20.00 FS | *- FS |
| 17 | 1 | | *SET SUN BLADE | Necessary | 280.00 FS | *60.00 FS |
| 18 | 1 | | *REAR WHEEL TYRE LH | Not Necessary | 450.00 FS | *- FS |
| 19 | 1 | | *REAR WHEEL RIM LH | Cut | 850.00 FS | *450.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **7,409.80** **2,515.90**

- List Item Discount on L Items 20.00/20.00% (\$\$) 1,137.96 397.18

Total Parts (\$\$) **6,271.84** **2,118.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING ,REMOVAL AND REPLACING PARTS | New | 1,600.00 | 600.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA | New | 1,400.00 | 900.00 |
| 3 | TUFF COAT | New | 250.00 | 0.00 |
| 4 | WIRING CHECK | New | 180.00 | 30.00 |
| 5 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | New | 80.00 | 0.00 |
| 6 | REMOVE AND REFIX REAR UNDERCARRIAGE | New | 350.00 | 0.00 |
| 7 | FOUR WHEEL ALIGNMENT | New | 100.00 | 80.00 |
| 8 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New | 180.00 | 0.00 |
| 9 | TO REMOVE AND REFIX FRONT DOOR MECHANISM | New | 120.00 | 0.00 |
| 10 | TO REMOVE AND REFIX REAR DOOR MECHANISM | New | 120.00 | 80.00 |
| Gross Labour Cost (\$\$) | | | 4,380.00 | 1,690.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >