

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19019739/UDS3Q2

**Date:** 15/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800145373

**Claimant**  
**Vehicle No :** SLT7827M **Insured Vehicle No :** SMG1305Z

Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: 5265487174SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7827M		
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Engine No:	HRA2512445A
Reg. Date:	10/11/2017 (Man. Year: 2017)	Chassis No:	SJNFEAJ11U2065408
Colour:	Brown	Odometer:	25150 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,957.30	3,511.78	19,445.52	84.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,640.00	2,420.00	59.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>27,017.30</b>	<b>5,151.78</b>	<b>21,865.52</b>	<b>80.93</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,100.00</b>		
<b>(\$\$)</b>	27,017.30	4,100.00	22,917.30	84.82
<b>+ GST 7.00/7.00% (\$\$)</b>	1,891.21	287.00	1,604.21	84.82
<b>Nett Amount (\$\$)</b>	<b>28,908.51</b>	<b>4,387.00</b>	<b>24,521.51</b>	<b>84.82</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,689.00</b>		

### INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 07/11/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN W/MOULDING	Not Necessary	1,855.30 F	*- FL
2	2		*REAR WINDSCREEN INNER SIDE GARNISH	Not Necessary	330.00 F	*- FL
3	1		*TAILGATE	Repair	3,066.20 F	*- FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	450.00 F	*- FL
5	1		*TAILGATE REAR LOGO	Not Necessary	38.50 F	*- FL
6	1		*TAILGATE QASHQAI EMBLEM	Necessary	78.50 F	*78.50 FL
7	2		*TAILGATE REFLECTORS	Not Necessary	1,300.00 F	*- FL
8	1		*TAILGATE REAR WIPER ARM	Not Necessary	166.00 F	*- FL
9	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	966.00 F	*- FL
10	1		*TAILGATE INNER LOCK	Not Necessary	292.00 F	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	595.30 F	*- FL
12	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 F	*- FL
13	1		*TAILGATE WEATHERSTRIP	Twisted	166.20 F	*166.20 FL
14	1		*TAILGATE REVERSE CAMERA	Not Necessary	485.00 F	*- FL
15	2		*TAILGATE LICENCE PLATE LAMPS	Not Necessary	106.00 F	*- FL
16	1		*REAR BUMPER	Distorted	891.00 F	*717.00 FL
17	1		*REAR BUMPER TOW COVER	Torn	22.00 F	*22.00 FL
18	1		*REAR BUMPER REFLECTORS	O/S Cracked	136.00 F	*68.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.00 F	*- FL
20	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
21	1		*REAR BUMPER SPONGE	Torn	185.00 F	*185.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	721.00 F	*619.20 FL
23	1		*REAR BUMPER REINFORCEMENT BRACKETS	O/S Dented	300.00 F	*121.00 FL
24	1		*REAR END PANEL	Dented	720.00 F	*482.60 FL
25	1		*REAR SUPPORT PANEL TOP GARNISH	Not Necessary	408.00 F	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,288.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	622.00 F	*- FL
28	2		*REAR FLOOR PANEL TOOLS SPONGES	Not Necessary	610.00 F	*- FL
29	1		*REAR END PANEL LOCK SENSOR	Shorted	265.00 F	*265.00 FL
30	1		*REAR FLOOR PANEL TOP BOARD SPONGE	Not Necessary	495.00 F	*- FL
31	1		*REAR EXHAUST	Not Necessary	1,122.30 F	*- FL
32	2		*REAR EXHAUST MOUNTINGS	Not Necessary	120.00 F	*- FL
33	1		*TAILLAMPS	O/S Cracked	1,160.00 F	*323.70 FL
34	2		*REAR FENDERS	Not Necessary	2,300.00 F	*- FL
35	1		*REAR FENDER OUTER PROTECTORS	O/S Torn	1,082.00 F	*541.00 FL
36	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
40	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$) 22,957.30 3,874.20**  
**- List Item Discount on L Items 0.00/10.00% (S\$) 0.00 362.42**

**Total Parts (S\$) 22,957.30 3,511.78**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	0.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	100.00	80.00
6	TO SPRAY RUST PROOFING	New	120.00	30.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	850.00
<b>Gross Labour Cost (\$)</b>			<b>4,060.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**