

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD $\sharp 16\text{-}00$

SPRINGLEAF TOWER SINGAPORE 079909 INV No. AC2005127

INV Date 22/07/2020

Reference CC6/CTI19019741/Aes3s2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 3023L

Insured Veh. YK 9409S

Claim No. SNM19D205268

Policy No. DMCVSN1903351900

Accident Date 05/11/2019

Inspection Date 06/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

NSA



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
CHIN	NA TAIPING INSURANCE (S) PTE LTD Ref: CC6/CTI19019741/Aes3s2				
	SON ROAD #16-0 NGLEAF TOWER	00 SINGAPORE 079909	Date: 22-07-2020 Code: CTI		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	YK 9409S	Veh. Inspected	SMN 3023L	
	Policy No.	DMCVSN1903351900	Coverage (\$)	0.00	
	Claim No.	SNM19D205268	Excess (\$)	0.00	
	Assign From		Assign Date	06/11/2019	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11114204	Colour	BLACK	
	Odometer	37733	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	CONTINENTAL	6 mm	
	L/H Front Tyre	215/60 R16	CONTINENTAL	6 mm	
	R/H Rear Tyre	215/60 R16	CONTINENTAL	6 mm	
	L/H Rear Tyre	215/60 R16	CONTINENTAL	6 mm	
4.		•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.	,	General	Information		
	Accident Date	05/11/2019	Inspection Date	06/11/2019	
	Survey held at GREEN FOREST AUTOMOBILE				
	8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.			emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	·				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 3023L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID SIDE REFLECTOR - RH	NOT NECESSARY	385.00	-
1	REAR TAIL LAMP - RH	NOT NECESSARY	405.50	-
4	REAR TAIL LAMP CLIPS @ \$6.50	NOT NECESSARY	26.00	-
1	REAR BUMPER	CUT	785.00	785.00
8	REAR BUMPER CLIPS @ \$6.50	NECESSARY	52.00	30.00
1	REARB BUMPER REVERSE SENSOR	NOT NECESSARY	300.00	-
2	REAR BUMPER BRACKET @ \$131.20	NOT NECESSARY	262.40	-
1	REAR BUMPER SIDE REFLECTOR - RH	NOT NECESSARY	83.10	-
1	REAR FENDER - RH	DENTED	972.40	972.40
1	REAR FENDER INNER COWLING - RH	NOT NECESSARY	288.00	-
1	REAR FENDER INNER TRIM BOARD - RH	NOT NECESSARY	388.00	-
10	REAR FENDER INNER TRIM BOARD CLIPS @ \$6.50	NOT NECESSARY	65.00	-
1	REAR FENDER MUD-SHIELD - RH	TORN	112.10	112.10
1	REAR FENDER MUD-SHIELD CLIPS	NECESSARY	12.90	12.90
1	REAR DOOR	DENTED	1,020.00	1,020.00
1	REAR DOOR INNER LOCK	DAMAGED	255.00	255.00
1	R/H ROCKER PANEL SKIRTING	CUT	680.30	680.30
1	REAR TIRE- RH	NOT NECESSARY	400.00	-
1	REAR AXLE ASSY	NOT NECESSARY	2,350.00	-
1	REAR RIM - RH	CUT	400.00	400.00
1	REAR AXLE BEARING - RH	DAMAGED	358.00	358.00
	LESS 20% DISCOUNT		-	-925.14
			9,600.70	3,700.56
	SPECIAL NETT ITEMS			
1	GUM (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		120.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO REMOVE & REFIX REAR FENDER GLASS - RH.		120.00	60.00

Report Ref No. CC6/CTI19019741/Aes3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE & REFIT REAR UNDERCARRIAGE WITH AXLE ASSY.		380.00	100.00
	TO CHECK WIRING.		60.00	30.00
	WHEEL ALIGNMENT (COMPUTER).		120.00	80.00
	TUFF KOTE.		120.00	80.00
	PANEL BEATING.		1,000.00	800.00
	SPRAY PAINTING.		1,000.00	700.00
			3,040.00	1,980.00
	GRAND TOTAL		12,690.70	5,710.56

RECOMMENDED COST OF LUMP SUM REPAIRS		4,550.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI19019741/Aes3s2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.