

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019742/UHA3Q2

Date: 24/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700077366-02

Claimant
Vehicle No : SMP412G **Insured Vehicle No :** SLT4562X

Date of Loss: 25/10/2019 **Nature of Claim:** TP **Claim No:** 7240821062SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP412G

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A)

Engine No: 2ZR0E11360

Reg. Date: 06/09/2019 (Man. Year: 2019)

Chassis No: ZWR800398826

Colour: Black

Odometer: 18271 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,902.25	1,685.50	9,216.75	84.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	580.00	2,070.00	78.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	13,552.25	2,265.50	11,286.75	83.28
Approved Total (Overridden) (\$)		1,800.00		
Nett Amount (\$)	13,552.25	1,800.00	11,752.25	86.72
+ Car Rental (4.0 x \$120.00/day) (\$)		480.00		
+ Doc/Search Fee (\$)		36.45		
Nett Liability (\$)		2,316.45		

INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 07/11/2019 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	1,758.50 FL	*1,758.50 FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	180.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	231.20 FL	*- FL
4	1		*FRONT BUMPER LOWER LIP	Not fitted	785.60 FL	*- FL
5	1		*FRONT BUMPER CENTRE -AIR GRILLE	Twisted / Torn	375.50 FL	*375.50 FL
6	2		*FRONT BUMPER SIDE GARNISH	Not Necessary	230.00 FL	*- FL
7	1		*FRONT BUMPER CENTRE GARNISH	Not Necessary	164.00 FL	*- FL
8	1		*FRONT BUMPER CENTRE GARNISH CHROME	Not Necessary	60.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	254.10 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	675.90 FL	*- FL
11	10		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
12	1		*FRONT RADIATOR GRILLE LOWER WITH CHROME GARNISH	Not Necessary	375.60 FL	*- FL
13	1		*FRONT RADIATOR GRILLE TOP WITH CHROME GARNISH	Not Necessary	420.10 FL	*- FL
14	15		*FRONT RADIATOR GRILLE CLIPS	Not Necessary	90.00 FL	*- FL
15	2		*FRONT DAY LIGHT	Not Necessary	1,191.60 FL	*- FL
16	2		*FRONT HEADLAMP LED	Not Necessary	5,971.20 FL	*- FL
17	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	375.40 FL	*- FL
18	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Not Necessary	768.90 FL	*- FL
20	1		*CENTRE BRACE PANEL	Not Necessary	275.40 FL	*- FL
21	1		*FRONT NUMBER PLATE WITH GARNISH	Scratched	80.00 FS	*40.00 FS
22	1		*RADIATOR COOLANT	Not Necessary	95.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,478.00	2,234.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,575.75	548.50
Total Parts (\$\$)	10,902.25	1,685.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,100.00	280.00
2	TO PUTTY, SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,000.00	300.00
3	TO CONDUCT LEAKAGE TEST & TOP UP AC GAS	New	150.00	0.00
4	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
5	TO RUST PROOF AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			2,650.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >