

22/03/2002

ASS. REC. BY:

REF: CS/CT1/9019447/EV f302

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Chang Boon Sen

of

CT1

Date/Time:

7.11.19 14.58 p.m

Estimated Cost:

63596171

Eddie

911424(8)

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 888 L (SM) 8935U

Insured:

at Workshop m/s

Jin Auto

Tel:

6289 8126

Jing

of

Blk 14 Deda Lane 10 #01-401 412

Policy No:

Claim No:

SNM190705247101

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 16.10.19

(Client's Record)

CA /

REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

7.11.19 3.00 p.m

Person Contacted:

Jouis

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SKL 888 L - CS/CT1/9019460/KSCL3

DOA - 16/10/2019

13/11/19

Revert via merimen

20/11/19

@1144am Boon Sen will check

the

21/11/19

@314pm Boon Sen call up want to check on modification

6/12/19

@310pm Boon Sen said they already update OI

REC. BY: Steve

REP: CTI  
(Enfile)

ASSIGNMENT

From: \_\_\_\_\_ Date: 11/11/19  
Estimated Cost: \_\_\_\_\_  
OD / NS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMC 89354  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \$500.00  
(Client's Record)  
Make of Veh: 9488 8998 Ah Hui

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<del>X</del>	<del>X</del>
N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SMC 89354 Yr Regn: 30/1/13  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Lexus GS250 C.C. 2500  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 96475 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JTHBF1BL905905977  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 255/35ZR19  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front Rear  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. 16/10/19 D.O.I. 11/11/19  
Survey held at LKK (Anga Ubi)  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV - 100K</u>
	<u>PV - 65,784.42</u>
	<u>NV - 34,215.58</u>
<u>10/12/19</u>	<u>@ 956am Spoken to Boun Sen we will submit preli report</u>
RECEIVED 10 DEC 2019	

Date/Time, File Pass to? ☒ : Preli. Report ☐ : Final Report  
1) \_\_\_\_\_  
Date/Time, File Return to? \_\_\_\_\_  
2) 10/12 - typist  
Report Format : \_\_\_\_\_  
Lump Sum / L.B.R : \_\_\_\_\_  
Days Of Repair: 4  
Resurvey No. of Trip: \_\_\_\_\_  
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)  
Survey Fee: 770  
Transportation: \_\_\_\_\_  
S + RS, SI \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL: 770

The vehicle ~~was~~<sup>is</sup> installed with a modified front bumper.  
However, the safety of the vehicle is not compromised  
as a result of a ~~the~~ fitted modified front bumper.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2019 Sendback Est	07 Nov 2019 12:27 S\$8,071.32	07 Nov 2019 14:58 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	ANG POH HOY, ID: S0184725B								
Vehicle Reg. No.:	SKL888L	Date of Loss:	16/10/2019 00:00 - :59 [80 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205247C01	Policy/Cover Note No.:	DMPCSN3038341900 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/11/2019]								
Driver/Custodian:	ONG YUN HAN (WANG YUNHAN) ( / Male) Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :  
**SKL888L (SNM19D205247C01)**  
OD  
Oct 16 2019 12:00AM  
[ANG POH HOY]  
Jin Auto Services Pte Ltd

ReplyReply AllMark as UnreadPrint MessageDelete MessageForward

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 10/12/2019 09:57 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Maintained - SKL888L - Claim Handler: Chong Boon Sen

Maintained:TO SUBMIT PLA FOR INSURER TO REVIEW

**DOCUMENTS SUMMARY**  
There are no documents.

## View Sent Message

This mail is associated with :

**SKL888L (SNM19D205247C01)**

OD

Oct 16 2019 12:00AM

[ANG POH HOY]

Jin Auto Services Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **22/11/2019 09:03 AM.**

**To** boonsen.chong@sg.cntaiping.com; claimsdept@sg.cntaiping.com

**Subject** SKL 888L (SMC 8935U)

Dear Boon Sen,

We refer to your conversation with our surveyor's Steve on 21/11/2019.

The vehicle is installed with a modified front bumper. However, the safety of the vehicle is not compromised as a result of a fitted modified front bumper.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Chong Boon Sen	Date:	13 Nov 2019
<b><u>Preliminary Advice</u></b>			

Vehicle No	: SKL888L (SMC 8935U)	Accident Date	: 16/10/2019
Make	: LEXUS GS250	Policy No.	: DMPCSN3038341900
Assignment Date	: 07/11/2019	Excess	: S\$500.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 4
Inspection At	: IDAC PAYA UBI, REPAIRER: JIN AUTO SERVICES PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,071.32
Revised Amount	:S\$	5,935.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,935.95

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate (Estimated)	:S\$	65,784.42
Salvage Value	:S\$	
Margin for Repair	:S\$	34,215.58

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :



**SINGAPORE  
POLICE FORCE**



G/20191017/2112

1 of 2

**POLICE REPORT (NP299)**

Report No. G/20191017/21

Police Station Of Origin  
Joo Chiat NPP  
267 Onan Road SINGAPORE 424773  
Tel No: 1800-3459999

Date/Time Report Made 17/10/2019 18:07	Vide Report No.	Station Diary No. 36
Name Of Informant ONG YUN HAN	Address APT BLK 700A ANG MO KIO AVENUE 6 #15-302 SINGAPORE 561700	
ID Type / ID No. NRIC NO / S7928490D	Contact No. Home/Office Mobile 94888998	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Helper in automotive shop	Sex Male	Age 40
Institution/School Name	Date of Birth 03/10/1979	Race Chinese
Date/Time Of Incident 17/10/2019 02:20 16/10/2019	Location Of Incident Johor Bahru, after Shell petrol station near to JB checkpoint. MALAYSIA	

**Brief details.**

No. 267 Onan Road  
Singapore 424773  
Tel: 1800-3459999

On 17/10/2019, at about 0220hrs, I was driving at Johor Bahru, after the immigration near to the Shell petrol station. While I was driving at the said road, I noticed that there was an empty lane, which I drove to the said lane. After turning into the lane, I noticed that there was a white in colour Audi (SKD6043K) which was moving off. I did not noticed that he was driving at a very slow speed. When I was approaching near, I noticed that the said Audi was at a very slow speed. I then applied my brake, which

Signature Of Officer Recording The Report: G / Staff Sgt KWOK WEI JIE, DANIEL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/10/2019 18:07
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Insp LAU YUN FANG Contact No.: 62447200	Classification Of Case:

Authentication Stamp





**SINGAPORE  
POLICE FORCE**



G/20191017/2112

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191017/2112

my car skidded and knocked onto the rear of the white Audi. The front bumper of my car was seriously damaged and the white Audi only suffered scratches at the rear bumper. We then came out and exchanged particulars before leaving the scene. I am lodging this report for insurance purposes.

Signature Of Officer Recording The Report:

G / Staff Sgt KWOK WEI JIE, DANIEL

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
G / Bedok Police Divisional Investigation Branch /  
Insp LAU YUN FANG  
Contact No.: 62447200

Authentication Stamp

Signature Of Informant:

Date/Time:  
17/10/2019 18:07

Classification Of Case:

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSN3038341900	Engine No : 4GR0853860 Chassis No: JTHBF1BL905005977
1. Index Mark and Registration Number of Vehicle	SKL888L	
2. Name of Policy Holder	MDM ANG POH HOY	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	24 MAY 2019 (10:53 HOURS) 23 MAY 2020	NAMED DRIVERS EX SECT. I.....\$S\$1,500.00 IN ADDITION TO NAMED DRIVERS EX: EX SECT. I - AGE <= 25.....\$S\$3,000.00 EX SECT. I - AGE >= 26.....\$S\$500.00 * AGE AS AT DATE OF ACCIDENT EX ON WINDSCREEN.....\$S\$100.00
4. Date of Expiry of Insurance		
5. Persons or Classes of Persons entitled to drive *		

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: \*

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.  
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$S\$1,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : HONG LEONG FINANCE LTD AS HP OWNER

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse  
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Countersigned By:

Authorised Officer

Authorised Signatory

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MJAS19139617-01 Vehicle Registration No: SKL 888 L  
Name (as shown in NRIC): WANG YUN HAN (WANG YUNHAN) NRIC/FIN/Passport No: S7928490D  
(\*Vehicle Driver / ~~XXXXXXXXXX~~ (\*) Please delete as appropriate  
Address : BLK 700A ANG MO KIO AVENUE 6 #15-302 Singapore 584700  
Contact (Tel) : 94888998 Mobile No. : 94888998  
Email Address : HUIONG79@GMAIL.COM  
Date of Accident : 16/10/2019 Time of Accident : 02:20  
Place of Accident AFTER SHELL STATION NEAR JB CHECKPOINT MALAYSIA  
Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I WISH TO MAKE THE FOLLOWING AMENDMENT TO MY ACCIDENT REPORT : DURING  
THAT TIME OF ACCIDENT . MY CAR SKL888L WAS INSURED UNDER POLICY NUMBER  
DMPCSN3075771900 , INSURED NAME VISA SG HOLDING

TRANSFER OF OWNERSHIP FOR SKL888L TO VISA SG HOLDING EFFECT ON  
18/10/ 2019.

✓  
\_\_\_\_\_  
Policyholder / Driver's Signature  
Date:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:

# Inquire Transaction History

## Transaction History Details

Log Date/Time:	18 Oct 2019 / 16:12:42
Receipt No.:	ITNET-00000-191018-002585
Asset Type:	Vehicle
Transaction Amount:	\$25.00
Asset ID:	SKL888L
Channel:	Internet
Transaction Type:	05.02 Confirm Pending Vehicle Transfer Appln (Self)
Business Transaction Reference No.:	20191018161242464226
CorpPass UID (Last 5 Characters):	8490D
Owner ID Type:	Company
Owner Name:	TAI THONG LEE TRADING (PRIVATE) LIMITED
Owner ID:	196900725C
Owner Country/Region:	Singapore
Status:	The vehicle has been transferred successfully
Next Owner ID Type:	Business
Next Owner Name:	VISA SG HOLDING
Next Owner ID:	53396002M
Next Owner Country/Region:	Singapore
Next Owner's Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Next Owner's Registered Block/House No.:	53
Next Owner's Registered Street name:	UBI AVENUE 1
Next Owner's Registered Floor No.:	01
Next Owner's Registered Unit No.:	42
Next Owner's Registered Building Name:	PAYA UBI INDUSTRIAL PARK
Next Owner's Registered Postal Code:	408934
Vehicle No.:	SKL888L
Previous Vehicle No.:	-
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS250 PREMIUM AUTO
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Chassis No. / Trailer Chassis No.:	JTHBF1BL905005977
Engine No./Motor No.:	4GR0853860/-
Engine Capacity(cc)/Power Rating(kW):	2500 / -
Passenger Capacity:	4
Propellant:	Petrol
Primary Color:	White
Secondary Color:	-
Maximum Laden Weight (Kg):	2170
Unladen Weight (Kg):	1640
Effective Ownership Date/Time:	18 Oct 2019 16:12:42
No. of Transfer:	3
First Registration Date:	30 Jan 2013
Original Registration Date:	30 Jan 2013
Year of Manufacture:	2012
PARF Eligibility Expiry Date:	29 Jan 2023
Financing Expiry Date:	-
Pending Expiry Date:	-
COE No.:	2013010107000207H
COE Bid Category:	E - Open Category
COE Expiry Date:	29 Jan 2023
Open Market Value:	52,707.00
ActualPQP Paid / QP Paid:	97,000.00
Actual ARF paid:	\$52,707.00
Minimum PARF Benefit:	26,353.00

31,524.87  
34,259.55  
= 65,784.42 - COE Rebate

$\approx 120 = 808.33 \times 39 \text{ month} = 31,524.87$   
 $\times 65\% = 34,259.55$

## Exclusive 11.11 deal

Give the gift of a smart speaker for only \$84.50 this 11.11. Deal ends

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



2.88% P.A, \$0 Down,\$0 Admin,  
Monthly from \$468, 2 Years  
Warranty Engine,Gear  
StarAd

**AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page

2 vehicles

Lexus GS250

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

**Search Selection** Lexus GS250 Any Any 2013 Any Any Any Availabl



**Lexus GS250 Luxury** \$100,800 \$15,290 /yr 14-Oct-2013 2,500 cc 82,202 km Luxury Availabl

Highest Grade Luxury Model. High ARF Value Of \$81,635. First Owner Bought At \$300K During Brand New! 4 Words To Describe This Sedan, Comfort, Luxury, Powerful And Sporty! Furthermore This Car Gone Through A 100 Points Check By Our Appointed Workshop To...

PREMIUM

Posted: 10-Nov-2019 Tags: 2013 Lexus GS250, 2013 lexus gs250, Lexus GS250, lexus gs250, Lexus, GS250, gs250, Used Lexus



**Lexus GS250 F Sport** \$89,800 \$14,870 /yr 14-May-2013 2,500 cc 86,998 km Luxury Availabl

Agent Maintained, GS 250 F Sport, Very Well Maintained By Owner, View To Appreciate, High ARF \$75371, Accident Free No Repair Needed, High Trade In And Loan Available, Hurry.

Posted: 09-Nov-2019 Tags: 2013 Lexus GS250, 2013 lexus gs250, Lexus GS250, lexus gs250, Lexus, GS250, gs250, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/pag

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate: insurance. Find buy used Lexus GS250, Lexus GS250 Singapore, used Lexus GS250 Singapore, used Lexus GS250, used vehicles Singapore or even buy used Lexus GS250 Singapore. We new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partne for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: SNM19D205009.**  
**Repairer Reference: SKL888L**  
**DMPCSN30383419000**  
**Date calculated: 07/11/2019 12:07 PM**

**Full Report**  
**Registration: SKL888L**

**Printed: 07/11/2019 12:07 PM**

### Summary Information

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	SNM19D205009.	Date of Incident:	16/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details


<b>Vehicle</b>			
Manufacturer:	LEXUS		
Model:	GS 250		
Sub Model:	BASE MODEL		
Model Sheet Number:	24 10 95		
Registration:	SKL888L		
VIN number:	JTHBF1BL905005977		
Odometer:			
<b>Model Specs</b>			
FROM 01/2012	FOG LAMPS	TRIM F SPORT	2.5 LTR 153/154KW
WHEELS 9J/10JX19 ALU	ALL WHEEL DRIVE(4X4)	PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

### Vehicle Condition

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

**All** ☐  
**Underbody** ☐



**Labour**

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	19.0	79.80	
B020)	RENEW FRONT BUMPER REINFORCEMENT	5.0	21.00	
B110	RENEW L/FRT WING (FRONT BUMPER, LEFT HEADLAMP ASSY AND L/SILL MOULDING REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R.	6.0	25.20	
B110	RENEW R/FRT WING (FRONT BUMPER, RIGHT HEADLAMP ASSY AND R/SILL MOULDING REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R.	6.0	25.20	
B131)	RENEW LEFT FRONT PANEL	5.0	21.00	
B131)	RENEW RIGHT FRONT PANEL	5.0	21.00	
B100	R + R LEFT SILL RAIL	3.0	12.60	
B100	R + R RIGHT SILL RAIL	3.0	12.60	
B040)	R + R HEADLAMP (ADD)	3.0	12.60	
B040)	R + R LEFT FRONT HEADLAMP (FRONT BUMPER REMOVED)	1.0	4.20	
B040)	R + R RIGHT HEADLAMP (FRONT BUMPER REMOVED)	1.0	4.20	
B070	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW	7.0	29.40	
B125	R + R FRONT LOCK CARRIER	3.0	12.60	
M020)	R + R RADIATOR	5.0	21.00	
M010	CONDENSER AND ADD RADIATOR R + R INCLUDES: REFILL COOLANT	10.0	42.00	
420018)	R + R L/FRONT WHEEL	2.0	8.40	
420018)	R + R R/FRONT WHEEL	2.0	8.40	
420091A)	R + R L/F TYRE AND WHEEL	3.0	12.60	
420091A)	R + R R/F TYRE AND WHEEL	3.0	12.60	
4465	CONDENSER CPL CHECK			
7761	RADIATOR CPL CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>9.20</b>	<b>92.0</b>	<b>386.40</b>
<b>Total of Labour</b>				<b>386.40</b>

**Paint**

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD		
	LOCK CARRIER STRUT SURFACE PAINT	4.0			
	FRT LOCK CARRIER SURFACE PAINT	4.0			
	L/F PANEL SURFACE PAINT	4.0			
	R/F PANEL SURFACE PAINT	4.0			
	FRONT BUMPER NEW PART PAINT K1R	12.0			



Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0	
	BONNET REPAIR PAINTING >50%	42.0	
	L/F WING REPAIR PAINTING >50%	17.0	
	R/F WING REPAIR PAINTING >50%	17.0	

## Paint Material Per Part

Code	Description	Price SGD
0988	LOCK CARRIER STRUT SURFACE PAINT	0.75
1017	FRT LOCK CARRIER SURFACE PAINT	4.48
1187	L/F PANEL SURFACE PAINT	1.25
1188	R/F PANEL SURFACE PAINT	1.25
0283	FRONT BUMPER NEW PART PAINT K1R	61.01
0299	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.49
0471	BONNET REPAIR PAINTING >50%	70.71
0741	L/F WING REPAIR PAINTING >50%	16.99
0742	R/F WING REPAIR PAINTING >50%	16.99

## Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		107.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>13.70</b>	<b>575.40</b>

## Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	61.50
Repair Painting	104.69
Surface-/Blend Paint	7.73
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>211.52</b>

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	OR		35.00
0258	FRT NO PLATE REINF	KNPL0	X NAI		0.00
0260	FRT NO PLATE BRKT	52114 30230	X NF		35.00
0283	FRONT BUMPER	52119 3A933	OR		300.00
0299	FRT BUMPER TRIM CAP	52129 30911	X NAI		10.00
0321	L/INN BUMPER BRACKET	52116 30090	X NAI		12.00
0322	R/INN BUMPER BRACKET	52115 30140	X NAI		12.00
0323	L/F BUMPER SUPPORT	52536 30220	OR		33.00
0324	R/F BUMPER SUPPORT	52535 30230	OR		33.00
0325	L/F OUT BUMPER BRKT	52116 30100	X NAI		23.00
0326	R/F BUMPER OUT BRKT	52115 30150	X NAI		23.00
0340	FRT BUMPER REINF	52131 30300	X NAI		135.00



Code	Description	Part Number	Supplier	Price SGD
0344	FRT IMPACT ABSORBER	52611 30420	X NF	42.00
0410	GRILLE	53111 30E00	/ GR	290.00
0412	CTR BUMPER GRILLE	53112 30380	/ GR	60.00
0420	RADIATOR GRILLE TRIM	52711 30270	/ GR	140.00
0431	GRILLE BADGE	90975 02125	X NF	145.00
0471	BONNET	53301 30491	/ OO	800.00
0481	BONNET INSULATION	53341 30310	/ CRH	0.00
0493	BONNET LOCK	53510 30360	/ DT	55.00
0502	BONNET LOCK COVER	53525 30080	/ GR	28.00
0561	LEFT HEADLAMP ASSY	81185 30G10	/ CUT	1,350.00
0562	RIGHT HEADLAMP ASSY	81145 30G10	/ CUT	1,350.00
0639	L/BUMPER GRILLE	53142 30100	X NAI	22.00
0640	R/BUMPER GRILLE	53141 30260	X NAI	22.00
0741	L/F WING	53802 30A30	X R	350.00
0742	R/F WING	53801 30A40	X R	350.00
0839	L/F WIND DEFLECTOR	53852 30110	X NAI	45.00
0840	R/F WIND DEFLECTOR	53851 30110	X NAI	45.00
0841	L/WHEELHOUSE SHELL	53806 30203	/ TN	120.00
0842	R/WHEELHOUSE SHELL	53805 30203	/ TN	120.00
0845	L/W-HOUSE AIR DEFL	53286 30130	X NAI	88.00
0846	R/W-HOUSE AIR DEFL	53285 30120	/ TN (cowl panel rubber)	88.00
0988	LOCK CARRIER STRUT	53217 30903	X NAI	36.00
1015	UPPER AIR GUIDE	53295 30100	X NAI	120.00
1017	FRT LOCK CARRIER	53216 30261	X NAI	125.00
1169	L/RADIATOR AIR GUIDE	53154 30190	X NAI	48.00
1170	R/RADIATOR AIR GUIDE	53153 30200	X NAI	48.00
1187	L/F PANEL	53203 30130	X NAI	130.00
1188	R/F PANEL	53202 30122	X NAI	130.00
7201	L/F WHEEL	42611 30F60	X NAI	0.00
7202	R/F WHEEL	42611 30F60	X BF NAI	(M NAI) 0.00
7227	L/F TYRE	225/50 R17 .. W	X FAF NAI	(M NAI) 0.00
1000	engine top cover	engine topcover	/ GR	(M NAI) 0.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**  
**Fixed Sundry Parts Price**  
  
**Total**

0.00  
6,798.00  
100.00  
6,898.00

## Final Calculation

	SGD	SGD
<b>Parts</b>	6,798.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>6,898.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 92.0 WU X 42.00 SGD/h	386.40	281.40
<b>Total of Labour</b>		<b>386.40</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 137.0 WU X 42.00 SGD/h	575.40	546
Material Cost	211.52	206.55
<b>Total Paint Including Material</b>		<b>786.92</b>
<b>Repair Cost Excludes GST</b>		<b>8,071.32</b>
GST (+7.00%)		<b>564.99</b>
<b>Repair Cost Included GST</b>		<b>8,636.31</b>

### Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK)  
8322 8813

11/11/19, 4.30pm

DD - not Authorise (Remot)  
Excess - \$500

L/S

RJ AFL spy

4 days

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

*Revert*

**Insurer Reference: 19/5247/OD**  
**Repairer Reference: SKL888L**  
**DMPCSN30383419000**  
**Date calculated: 13/11/2019 10:53 AM**

**Full Report**  
**Registration: SKL888L**

**Printed: 13/11/2019 10:54 AM**

### Summary Information

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	19/5247/OD	Date of Incident:	16/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details


<b>Vehicle</b>			
Manufacturer:	LEXUS		
Model:	GS 250		
Sub Model:	BASE MODEL		
Model Sheet Number:	24 10 95		
Registration:	SKL888L		
VIN number:	JTHBF1BL905005977		
Odometer:			
<b>Model Specs</b>			
FROM 01/2012	FOG LAMPS	TRIM F SPORT	2.5 LTR 153/154KW
WHEELS 9J/10JX19 ALU	ALL WHEEL DRIVE(4X4)	PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

### Vehicle Condition

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

**All** ☐  
**Underbody** ☐



## Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		19.0	79.80
NO NUMBER	RENEW L/F BUMPER BRACKET		1.0	4.20
NO NUMBER	RENEW R/F BUMPER BRACKET		1.0	4.20
B010)	R + R FRONT BUMPER REINFORCEMENT		2.0	8.40
B040)	R + R HEADLAMP (ADD)		3.0	12.60
B040)	R + R LEFT FRONT HEADLAMP (FRONT BUMPER REMOVED)		1.0	4.20
B040)	R + R RIGHT HEADLAMP (FRONT BUMPER REMOVED)		1.0	4.20
531041)	R + R LEFT FRONT WHEELHOUSE SHELL		2.0	8.40
531041)	R + R RIGHT FRONT WHEELHOUSE SHELL		2.0	8.40
NO NUMBER	R + R R/F VENTILATION COVER		1.0	4.20
B070	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW		7.0	29.40
530111)	R + R BONNET LOCK		2.0	8.40
M020)	R + R RADIATOR		5.0	21.00
M010	CONDENSER AND ADD RADIATOR R + R INCLUDES: REFILL COOLANT		10.0	42.00
420018)	R + R L/F FRONT WHEEL		2.0	8.40
420018)	R + R R/F FRONT WHEEL		2.0	8.40
420091A)	R + R L/F TYRE AND WHEEL		3.0	12.60
420091A)	R + R R/F TYRE AND WHEEL		3.0	12.60
4465	CONDENSER CPL CHECK			
7761	RADIATOR CPL CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>6.70</b>	<b>67.0</b>	<b>281.40</b>
<b>Total of Labour</b>				<b>281.40</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT PEARL/MICA		WU	Price SGD
	LOCK CARRIER STRUT SURFACE PAINT		4.0	
	L/F PANEL SURFACE PAINT		4.0	
	R/F PANEL SURFACE PAINT		4.0	
	FRONT BUMPER NEW PART PAINT K1R		12.0	
	BONNET REPAIR PAINTING >50%		42.0	
	L/F WING REPAIR PAINTING >50%		17.0	
	R/F WING REPAIR PAINTING >50%		17.0	

## Paint Material Per Part

Code	Description	Price SGD
0988	LOCK CARRIER STRUT SURFACE PAINT	0.75
1187	L/F PANEL SURFACE PAINT	1.25
1188	R/F PANEL SURFACE PAINT	1.25

**Paint Material Per Part**

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	61.01
0471	BONNET REPAIR PAINTING >50%	70.71
0741	L/F WING REPAIR PAINTING >50%	16.99
0742	R/F WING REPAIR PAINTING >50%	16.99

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		100.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>13.00</b>	<b>546.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1R	61.01
Repair Painting	104.69
Surface-/Blend Paint	3.25
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>206.55</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3			35.00
0258	FRT NO PLATE REINF	KNPL0			0.00
0283	FRONT BUMPER	52119 3A933			300.00
0323	L/F BUMPER SUPPORT	52536 30220			33.00
0324	R/F BUMPER SUPPORT	52535 30230			33.00
0410	GRILLE	53111 30E00			290.00
0412	CTR BUMPER GRILLE	53112 30380			60.00
0420	RADIATOR GRILLE TRIM	52711 30270			140.00
0471	BONNET	53301 30491			800.00
0481	BONNET INSULATION	53341 30310			0.00
0493	BONNET LOCK	53510 30360			55.00
0502	BONNET LOCK COVER	53525 30080			28.00
0561	LEFT HEADLAMP ASSY	81185 30G10			1,350.00
0562	RIGHT HEADLAMP ASSY	81145 30G10			1,350.00
0841	L/WHEELHOUSE SHELL	53806 30203			120.00
0842	R/WHEELHOUSE SHELL	53805 30203			120.00
0846	R/W-HOUSE AIR DEFL	53285 30120			88.00
7202	R/F WHEEL	42611 30F60			0.00
7227	L/F TYRE	225/50 R17 .. W			0.00
1000	engine top cover	engine topcover			0.00
f: OEM Parts	<b>Savings</b>				0.00
n: Non-OEM Parts	<b>Subtotal</b>				4,802.00
u: Used parts	<b>Fixed Sundry Parts Price</b>				100.00

**Total****4,902.00****Final Calculation**

	SGD	SGD
<b>Parts</b>	4,802.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>4,902.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 67.0 WU X 42.00 SGD/h	281.40	
<b>Total of Labour</b>		<b>281.40</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 130.0 WU X 42.00 SGD/h	546.00	
Material Cost	206.55	
<b>Total Paint Including Material</b>		<b>752.55</b>
<b>Repair Cost Excludes GST</b>		<b>5,935.95</b>
GST (+7.00%)		<b>415.52</b>
<b>Repair Cost Included GST</b>		<b>6,351.47</b>

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

No assessment notes entered.

During our survey on 11/11/2019, the owner drive over to our office, block 51, #01-25 paya ubi industrial park. ~~using his car plate~~

We observed that the car has been repaired after the accident.

The owner advised that he sent the vehicle for repair by himself, because he wanted to use the car as soon as possible, and he didn't notify the insurance regarding that. However, we list down those parts which have been repaired or replaced.

1. Front bumper — Replaced (Broken)
2. Front number plate — Replaced (Broken)
3. Front bonnet — Repaired (Dented)
4. Front bonnet lock cover — Torn (reuse)
5. Front bonnet insulation — Torn (reuse)
6. Front Headlamp RH — CUT (reuse)
7. Front Headlamp LH — CUT (reuse)
8. Front LH fender — Dented (repaired)
9. Front RH fender — Dented (repaired)
10. Front LH fender liner — Torn (reuse)
11. Front RH fender liner — Torn (reuse)
12. Engine top cover — Broken (reuse)

## View Sent Message

This mail is associated with :

**SKL888L (SNM19D205247C01)**

OD

Oct 16 2019 12:00AM

[ANG POH HOY]

Jin Auto Services Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 27/11/2019 16:35 PM.

**To** boonsen.chong@sg.cntaiping.com; CHINA\_TAIPING

**Subject** SKL 888L (SMC 8935U)

Dear Boon Sen,

According to surveyor,during our survey on 11/11/2019,the owner drive over to our office, Blk 51 #01-25 Paya Ubi Industrial Park.We observed that the vehicle has been repaired after the accident.

The owner advised that he sent the vehicle for repair by himself,because he wanted to use the vehicle as soon as possible and he didn't notify the insurance regarding that. However, we list down those parts which have been repaired or replaced.

1. Front bumper-Replaced (Broken)
2. Front number plate-Replaced (Broken)
3. Front bonnet-Repaired (Dented)
4. Front bonnet lock cover-Torn (Reuse)
5. Front bonnet insulation-Torn (Reuse)
6. Front headlamp RH-Cut (Reuse)
7. Front headlamp LH- Cut (Reuse)
8. Front LH fender-Dented (Repaired)
9. Front RH fender-Dented (Repaired)
- 10.Front LH fender liner-Torn (Reuse)
11. Front RH fender liner-Torn (Reuse)
12. Engine top cover-Broken (Reuse)

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2019 <a href="#">Sendback Est</a>	07 Nov 2019 12:27 <b>S\$8,071.32</b>	07 Nov 2019 14:58 <a href="#">Edit Adj Rpt</a>	<b>S\$5,935.95</b> <a href="#">Edit Estimates</a>	<b>S\$5,935.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	ANG POH HOY, ID: S0184725B								
Vehicle Reg. No.:	SKL888L	Date of Loss:	16/10/2019 00:00 - :59 [80 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205247C01	Policy/Cover Note No.:	DMPCSN3038341900 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/11/2019]								
Driver/Custodian:	ONG YUN HAN (WANG YUNHAN) ( / Male) Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>CHINA_TAIPING (10/12/2019): Alert - Adj Mandate Maintained - SKL888L - Claim Handler: Chong Boon Sen</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SKL888L (SNM19D205247C01)























































OD

Oct 16 2019 12:00AM

[ANG POH HOY]

Jin Auto Services Pte Ltd

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	07/11/19 12:27	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/19 11:13	Adjuster Immediate Advice		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	07/11/19 12:24	Photographs of Damaged Parts		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/11/19 16:15	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
8	12/11/19 16:15	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
9	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
17	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
18	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
19	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
20	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
21	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
22	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
23	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
24	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
25	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
26	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
27	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
28	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
29	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
30	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
31	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
32	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
33	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
34	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
35	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
36	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
37	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>
38	12/11/19 16:15	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
39	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/11/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/11/19 16:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/11/19 16:17	Driver temporary repair back	 Load JPG	<input checked="" type="checkbox"/>
90	12/11/19 16:17	Driver temporary repair back	 Load JPG	<input checked="" type="checkbox"/>
91	12/11/19 16:17	Driver temporary repair back	 Load JPG	<input checked="" type="checkbox"/>
92	12/11/19 16:17	Driver temporary repair back	 Load JPG	<input checked="" type="checkbox"/>
93	12/11/19 16:17	Driver temporary repair back	Load JPG	<input checked="" type="checkbox"/>
94	12/11/19 16:17	Driver temporary repair back	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
95	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
96	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
97	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
98	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
99	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
100	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
101	12/11/19 16:17	Driver temporary repair back		Load JPG	<input checked="" type="checkbox"/>
102	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
103	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
104	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
105	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
106	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
107	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
108	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
109	12/11/19 16:19	Driver change front RH rim & damaged engine cover		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	07/11/19 12:26	AUDATEX REPORT		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/19 11:15	MARK ESTIMATE		Load PDF	
2	13/11/19 11:15	AUDATEX		Load PDF	
3	29/11/19 09:32	SURVEYOR'S MARKING		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CT119019747/EVF3E2

Date: 17/12/2019

### REFERENCE

Insured/Claimant: ANG POH HOY Policy No: DMPCSN3038341900  
Date of Loss: 16/10/2019 Nature of Claim: OD Claim No: SNM19D205247C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL888L  
Make & Model: LEXUS GS250, 2.5 Premium (GRL11R) (A) Engine No: 4GR0853860  
Reg. Date: 30/01/2013 (Man. Year: 2012) Chassis No: JTHBF1BL905005977  
Colour: Grey Odometer: 96475 km  
Engine Capacity: 2500 cc  
Market Value/New Car Price: S\$100,000.00  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/35Z R19 Rear Tyre Size: 255/35Z R19  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,898.00	4,902.00	1,996.00	28.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,173.32	1,033.95	139.37	11.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,071.32</b>	<b>5,935.95</b>	<b>2,135.37</b>	<b>26.46</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>500.00</b>	<b>-500.00</b>	
<b>(S\$)</b>	<b>8,071.32</b>	<b>5,435.95</b>	<b>2,635.37</b>	<b>32.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>564.99</b>	<b>380.52</b>	<b>184.47</b>	<b>32.65</b>
<b>Nett Amount (S\$)</b>	<b>8,636.31</b>	<b>5,816.47</b>	<b>2,819.84</b>	<b>32.65</b>

### INSPECTION

Date of Assignment: 07/11/2019 Present Location: Jin Auto Services Pte Ltd (Defu)  
Date Inspected: 11/11/2019 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195  
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2019)
<b>Parts:</b>	143	LEXUS GS250 2.5 Premium (GRL11R) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKL888L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		6,898.00 F	*4,902.00 F
					<b>Total Parts (S\$)</b>	<b>6,898.00</b>
						<b>4,902.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PAINT	New	786.92	752.55
2	TOTAL LABOUR	New	386.40	281.40
Gross Labour Cost (S\$)			<b>1,173.32</b>	<b>1,033.95</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >