

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS19019758/AVD3E2

**Date:** 05/02/2020

#### REFERENCE

Handling Insurer: ECICS Limited

Policy No:

**Claimant Vehicle No :**

SDS839A

**Insured Vehicle No :**

SLR3612C

Date of Loss: 03/11/2019

Nature of Claim:

TP

Claim No: N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SDS839A**

Make & Model:

TOYOTA VELLFIRE, 2.4 V (A)

Engine No:

2AZG444066

Reg. Date:

27/03/2015 (Man. Year: 2014)

Chassis No:

ANH208346738

Colour:

White

Odometer:

119348 km

Engine Capacity:

2362 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

**Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:

235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,450.16	2,416.00	4,034.16	62.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,200.00	1,250.00	36.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,900.16</b>	<b>4,616.00</b>	<b>5,284.16</b>	<b>53.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>693.01</b>	<b>323.12</b>	<b>369.89</b>	<b>53.37</b>
<b>Nett Amount (S\$)</b>	<b>10,593.17</b>	<b>4,939.12</b>	<b>5,654.05</b>	<b>53.37</b>

#### INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 08/11/2019 Inspected At:

Progressive Car Care Pte Ltd (HQ)

Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2020)
<b>Parts:</b> M1-MPV	TOYOTA VELLFIRE 2.4 V (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SDS839A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PARKING CAMERA	Not Necessary	350.00 FS	*- FS
2	1		*FRONT NUMBER PLATE WITH CASING	Bent	35.00 FS	*35.00 FS
3	1		*SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
4	2		*SEALANT	Necessary	40.00 FS	*40.00 FS
5	1		*REAR BOOT	Distorted	700.00 F	*700.00 F
6	1		*REAR BOOT REFLECTOR - LH	Not Necessary	170.00 F	*- F
7	1		*REAR BOOT REFLECTOR - RH	Not Necessary	170.00 F	*- F
8	1		*REAR BOOT TOP LOCK	Not Necessary	170.00 F	*- F
9	1		*REAR BOOT BOTTOM LOCK	Not Necessary	28.00 F	*- F
10	1		*REAR BOOT RUBBER	Cut	140.00 F	*140.00 F
11	1		*REAR BOOT VELLFIRE WORDING	Necessary	45.00 F	*45.00 F
12	1		*REAR BOOT OUTER LOWER CHROME	Not Necessary	680.00 F	*- F
13	1		*REAR BOOT KEYLESS SENSOR	Not Necessary	100.00 F	*- F
14	1		*REAR BUMPER	Deformed	350.00 F	*350.00 F
15	10		*REAR BUMPER CLIPS	Necessary	25.00 F	*25.00 F
16	1		*REAR BUMPER SIDE HOLDER - LH	Necessary	40.00 F	*40.00 F
17	1		*REAR BUMPER SIDE HOLDER - RH	Necessary	40.00 F	*40.00 F
18	1		*REAR BUMPER END PANEL BRACKET - RH	Not Necessary	70.00 F	*- F
19	1		*REAR BUMPER END PANEL BRACKET - LH	Not Necessary	70.00 F	*- F
20	4		*REAR BUMPER SENSOR	Not Necessary	640.00 F	*- F
21	1		*REAR BUMPER SENSOR COVER - OUTER	Not Necessary	15.00 F	*- F
22	1		*REAR BUMPER SENSOR WIRE	Not Necessary	200.00 F	*- F
23	1		*REAR BUMPER REFLECTORS - LH	Not Necessary	28.00 F	*- F
24	1		*REAR BUMPER REFLECTORS - RH	Not Necessary	28.00 F	*- F
25	1		*REAR BUMPER TOW COVER - LH	Not Necessary	35.00 F	*- F
26	1		*REAR BUMPER TOW COVER - RH	Not Necessary	35.00 F	*- F
27	1		*REAR PANEL - INNER / OUTER	Dented	360.00 F	*320.00 F
28	1		*REAR PANEL TOP GARNISH	Not Necessary	110.00 F	*- F
29	1		*TAILLAMP ASSY - RH	Not Necessary	210.00 F	*- F
30	1		*TAILLAMP LOWER GARNISH - RH	Not Necessary	50.00 F	*- F
31	1		*FRONT BUMPER	Deformed	300.00 F	*300.00 F
32	10		*FRONT BUMPER CLIPS	Necessary	15.00 F	*15.00 F
33	1		*FRONT BUMPER SIDE HOLDER - LH	Not Necessary	40.00 F	*- F
34	1		*FRONT BUMPER SIDE HOLDER - RH	Not Necessary	40.00 F	*- F
35	1		*FRONT BUMPER CENTRE LOWER GRILLE	Deformed	85.00 F	*85.00 F
36	1		*FRONT BUMPER PARKING SENSOR	Not Necessary	190.24 F	*- F
37	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	180.00 F	*- F
38	1		*FRONT BUMPER FOAM	Not Necessary	50.00 F	*- F
39	1		*RETAINER FRONT FENDER LINER	Necessary	5.00 F	*5.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
40	1		*REAR BOOT GOLDEN EYES II WORDING	Necessary	45.00 F	*45.00 F	
F=Franchise part. S=SpcNett.							
					<b>Sub Total (\$)</b>	<b>5,904.24</b>	<b>2,205.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	545.92	211.00
					<b>Total Parts (\$)</b>	<b>6,450.16</b>	<b>2,416.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE / REPLACE FRONT BUMPER, REAR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	New	1,200.00	1,000.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,400.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE, REFIT REAR GARNISH	New	150.00	60.00
5	TO TUFF-KOTE	New	120.00	60.00
6	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
7	TO TRANSFER FRONT BUMPER SENSOR	New	100.00	50.00
8	TO RESET CHECK LIGHT	New	60.00	30.00
9	TO REMOVE, REFIT REAR BOOT GLASS	New	150.00	120.00
10	TO REMOVE, REPAIR REAR EXHAUST PIPE	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,450.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >