

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019774/UBA3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100364786-05

Claimant
Vehicle No : FBL7712X **Insured Vehicle No :** SKM3211P

Date of Loss: 31/10/2019 **Nature of Claim:** TP **Claim No:** 3628169516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------------|
| Reg No: | FBL7712X | | |
| Make & Model: | HONDA CBF 190, 184cc | Engine No: | MC46E5035451 |
| Reg. Date: | 04/03/2017 (Man. Year: 2017) | Chassis No: | LWBMCA4694H1111216 |
| Colour: | Red | Odometer: | 41170 km |
| Engine Capacity: | 184 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 110-70 R17 | Rear Tyre Size: | 140-70 R17 |
| Front Left Side: | Radial 6 mm | Rear Left Side: | Radial 6 mm |
| Front Right Side: | 0 mm | Rear Right Side: | 0 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 2,894.30 | 1,036.90 | 1,857.40 | 64.17 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 860.00 | 350.00 | 510.00 | 59.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,754.30 | 1,386.90 | 2,367.40 | 63.06 |
| Approved Total (Overridden) (S\$) | | 1,100.00 | | |
| Nett Amount (S\$) | 3,754.30 | 1,100.00 | 2,654.30 | 70.70 |
| + Loss of Use (5.0 x S\$20.00/day) (S\$) | | 100.00 | | |
| (S\$) | | 1,200.00 | | |
| Liabile Amount (50.00%) (S\$) | | 600.00 | | |
| Global Sum Settlement (S\$) | | 580.00 | | |

INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 07/11/2019 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------|----------------|------------|------------|
| 1 | 1 | | *FRONT FENDER | Cut / Deformed | 70.00 FL | *70.00 FL |
| 2 | 2 | | *FORK INNER TUBES | Repair | 350.00 FL | *- FL |
| 3 | 2 | | *FORK OUTER TUBES | Serviceable | 360.00 FL | *- FL |
| 4 | 1 | | *FRONT BRAKE DISC | Not Necessary | 155.00 FL | *- FL |
| 5 | 1 | | *FRONT RIM SHAFT | Not Necessary | 42.00 FL | *- FL |
| 6 | 1 | | *FRONT RIM BEARING | Not Necessary | 38.00 FL | *- FL |
| 7 | 1 | | *HANDLE -BARS | N/S Bent | 250.00 FL | *125.00 FL |
| 8 | 1 | | *HANDLE -BAR BALANCERS | N/S Scratched | 56.00 FL | *28.00 FL |
| 9 | 1 | | *SIDE MIRRORS | N/S Cut | 100.00 FL | *50.00 FL |
| 10 | 1 | | *CLUTCH LEVER | Scratched | 28.00 FL | *28.00 FL |
| 11 | 1 | | *BRAKE LEVER | Serviceable | 28.00 FL | *- FL |
| 12 | 1 | | *HEADLAMP SIDE COWLING | Cut | 198.00 FL | *198.00 FL |
| 13 | 1 | | *SIDE COWLING | Repair | 225.00 FL | *- FL |
| 14 | 1 | | *FRONT FOOTREST -L/H | Twisted | 45.00 FL | *45.00 FL |
| 15 | 1 | | *FRONT FOOTREST BRACKET | Bent | 60.00 FL | *60.00 FL |
| 16 | 1 | | *GEAR PEDAL | Twisted | 42.00 FL | *42.00 FL |
| 17 | 1 | | *REAR FOOTREST -L/H | Serviceable | 45.00 FL | *- FL |
| 18 | 1 | | *MAIN STAND | Bent | 95.00 FL | *95.00 FL |
| 19 | 1 | | *SIDE STAND | Serviceable | 80.00 FL | *- FL |
| 20 | 1 | | *SET NUMBER PLATE | Not Necessary | 28.00 FS | *- FS |
| 21 | 1 | | *REAR BOX | Cut | 250.00 FS | *250.00 FS |
| 22 | 1 | | *REAR BOX BRACKET | Serviceable | 100.00 FS | *- FS |
| 23 | 2 | | *FORK OILS | Not Necessary | 30.00 FS | *- FS |
| 24 | 2 | | *FORK OIL SEALS | Not Necessary | 56.00 FS | *- FS |
| 25 | 1 | | *SET STEERING CONE | Not Necessary | 90.00 FS | *- FS |
| 26 | 1 | | *SET SIDE FRAME SLIDING | Cut | 120.00 FS | *120.00 FS |
| 27 | 1 | | *SET LOWER COWLING | Serviceable | 180.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 3,121.00 | 1,111.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 226.70 | 74.10 |
| Total Parts (\$) | 2,894.30 | 1,036.90 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|---------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO PROVIDE TOWING SERVICE | New | 50.00 | 50.00 |
| 2 | TO CHECK WIRING AND RESET HEADLAMP FOCUSING | New | 80.00 | 0.00 |
| 3 | TO PROVIDE LABOUR | New | 380.00 | 300.00 |
| 4 | TO REPAIR BODY FRAME | New | 350.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 860.00 | 350.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >