



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3816P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT) (WCP)	DENTED	215.00	215.00
1	REAR CORNER GARNISH L (CONSISTENT) (WCP)	SERVICEABLE	88.00	-
1	REAR BUMPER SIDE RETAINER R (CONSISTENT) (WCP)	NOT NECESSARY	18.00	-
1	REAR BUMPER SIDE RETAINER L (CONSISTENT) (WCP)	NECESSARY	18.00	18.00
1	REAR END PANEL (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	335.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT) (WCP)	SERVICEABLE	185.00	-
1	REAR TAILGATE (CONSISTENT) (WCP)	DENTED	580.00	580.00
1	REAR BUMPER REFLECTOR L(CONSISTENT) (WCP)	SERVICEABLE	48.00	-
	COST PLUS 15%		223.05	121.95
			1,710.05	934.95
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	40.00	30.00
2	REAR BUMPER REVERSE SENSORS (SN)(CONSISTENT)	SHORTED	700.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
			780.00	230.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION .	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR .		80.00	60.00
	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	400.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		500.00	400.00
			1,310.00	890.00
<b>GRAND TOTAL</b>			<b>3,800.05</b>	<b>2,054.95</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CC4/ASM19019786/Qpa3q2

**OI SUN PIN**

**Asst. Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**