

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1910/016
Policy No:	5094358705-02	Date of Loss:	23/10/2019
Vehicle Reg. No.:	SLG3816P	Driveable?	no
Driver Age:	02/06/1981	Third Party Vehicle No.:	SGR5994X
Any Injuries?	no	Contact No:	92280158
Insured/Claimant:	LEE HONGYUN ERIC	Driver:	LEE HONGYUN ERIC

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	28/09/2016
Vehicle Colour:	WHITE	Engine Number:	
Chassis No:	RU11115724	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	1,710.05
Miscellaneous Items	780.00
Labour	810.00
Paintwork Labour	500.00
Towing	0.00
Gross Total(S\$):	3,800.05
GST 7.00%(S\$):	266.00
Nett Amount(S\$):	4,066.05

This claim is handled by: SHUYI

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / DP.	215.00	+15.00	247.25
2	1	REAR CORNER GARNISH L ?	88.00	+15.00	101.20
3	1	REAR BUMPER SIDE RETAINER R X	18.00	+15.00	20.70
4	1	REAR BUMPER SIDE RETAINER L / NEC	18.00	+15.00	20.70
5	1	REAR END PANEL ?	335.00	+15.00	385.25
6	1	REAR END PANEL TOP GARNISH ?	185.00	+15.00	212.75
7	1	REAR TAILGATE / DP	580.00	+15.00	667.00
8	1	REAR BUMPER REFLECTOR L ?	48.00	+15.00	55.20

Total Parts (\$\$) 1,710.05

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS / NEC	40.00	0.00	40.00 30
2	2	REAR BUMPER REVERSE SENSORS / short	700.00	0.00	700.00 200.
3	1	REAR END PANEL TOP GARNISH CLIPS X	40.00	0.00	40.00

Sub Total (\$\$) 780.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 X
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 60
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	0.00	600.00 400

Gross Labour Cost (\$\$) 810.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	500.00	0.00	500.00 400

Repair day - 3 days.

Sun Pm

Lump Sum Repair.

After spray photo.

TP without prejudice.

Gross Labour Cost (\$\$) 500.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- party survey is on a "With no police" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: