

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19019793/QRA3Q2

**Date:** 02/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800150135

**Claimant**  
**Vehicle No :** SFJ9688H **Insured Vehicle No :** SMG2874R

Date of Loss: 15/10/2019 Nature of Claim: TP Claim No: 3560773443SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFJ9688H**

Make & Model: TOYOTA ESTIMA, 2.4 E X Hybrid (A)

Engine No: 2AZH362404

Reg. Date: 14/09/2009 (Man. Year: 2009)

Chassis No: AHR207036661

Colour: Silver

Odometer: 204325 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Grenlander 5 mm

Rear Left Side: Grenlander 5 mm

Front Right Side: Grenlander 5 mm

Rear Right Side: Grenlander 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,410.43	77.85	2,332.58	96.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	750.00	450.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,610.43</b>	<b>827.85</b>	<b>2,782.58</b>	<b>77.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	252.73	57.95	194.78	77.07
<b>Nett Amount (S\$)</b>	<b>3,863.16</b>	<b>885.80</b>	<b>2,977.36</b>	<b>77.07</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 06/11/2019

Date Inspected: 07/11/2019 Inspected At:

51 UBI AVE 1 #01-25

Repairer: ENTERPRISE ONE AUTO

PTE LTD - EUNOS (HQ)

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	2,560.56 FL	* - FL
2	1		*REAR BUMPER RETAINER	Broken	86.50 FL	*86.50 FL
3	1		*REAR BUMPER CLIP	Serviceable	31.20 FL	* - FL
					<b>Sub Total (\$\$)</b>	<b>2,678.26</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>86.50</b>
						<b>267.83</b>
					<b>Total Parts (\$\$)</b>	<b>77.85</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BEING REPAIR NEW BUMPER	New	400.00	250.00
2	BEING PLASTIC PRIMER COAT ON THE BUMPER AND PAINTING ON REPLACING AND REPAIR PARTS	New	800.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,200.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >