Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019810/URA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994242

Claimant
Vehicle No: Insured Vehicle No: SMM560C

Date of Loss: 06/11/2019 Nature of Claim: TP Claim No: 8536210894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY3278G

Make & Model: NISSAN URVAN, 3.0 D (M) Engine No: ZD30046484

Reg. Date: 08/03/2005 (Man. Year: 2005) Chassis No: JN1MG4E25Z0712711

Colour: Blue Odometer: 295333 km

Engine Capacity: 2953 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
4,959.84	3,592.74	1,367.10	27.56
0.00	0.00	0.00	
2,680.00	1,610.00	1,070.00	39.93
0.00	0.00	0.00	
0.00	0.00	0.00	
7,639.84	5,202.74	2,437.10	31.90
	3,600.00		
7,639.84	3,600.00	4,039.84	52.88
534.79	252.00	282.79	52.88
8,174.63	3,852.00	4,322.63	52.88
30.00/day) (S\$)	480.00		
earch Fee (S\$)	7.45		
tt Liability (S\$)	4,339.45		
	7,639.84 7,639.84	4,959.84 3,592.74 0.00 0.00 2,680.00 1,610.00 0.00 0.00 0.00 0.00 7,639.84 5,202.74 3,600.00 3,600.00 534.79 252.00 8,174.63 3,852.00 80.00/day) (\$\$) 480.00 earch Fee (\$\$) 7.45	4,959.84 3,592.74 1,367.10 0.00 0.00 0.00 2,680.00 1,610.00 1,070.00 0.00 0.00 0.00 0.00 0.00 0.00 7,639.84 5,202.74 2,437.10 3,600.00 3,600.00 4,039.84 534.79 252.00 282.79 8,174.63 3,852.00 4,322.63 80.00/day) (\$\$) 480.00 earch Fee (\$\$) 7.45

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 12/11/2019 Inspected At: Hock Wah Motor Workshop Pte Ltd

(Bedok)

Blk 3011, Bedok Industrial Park E,,

#01-2008/2010/2012 Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE	Badly Dented	1,998.30 FL	*1,742.00 FL	
2	1		*TAILGATE LOGO-URVAN	Necessary	19.50 FL	*19.50 FL	
3	1		*REAR BUMPER	Distorted	660.60 FL	*660.60 FL	
4	1		*TAILGATE LOGO -3.0DI	Necessary	19.50 FL	*19.50 FL	
5	1		*TAILGATE EMBLEM	Necessary	59.70 FL	*59.70 FL	
6	1		*END PANEL	Badly Dented	453.00 FL	*453.00 FL	
7	1		*END PANEL TOP GARNISH	Serviceable	65.31 FL	*- FL	
8	1		*TAILGATE LOCK	Dented / Jammed	354.50 FL	*354.50 FL	
9	1		*TAILGATE RUBBER	Twisted	180.80 FL	*180.80 FL	
10	1		*TAILGATE TRIMBOARD	Not Necessary	152.50 FL	*- FL	
11	1		*REAR BUMPER STEP PANEL	Bent	169.00 FL	*169.00 FL	
12	1		*REAR BUMPER RETAINER RH	Not Necessary	17.40 FL	*- FL	
13	1		*REAR BUMPER RETAINER LH	Not Necessary	17.40 FL	*- FL	
14	1		*REAR BUMPER BRACKET RH (NPA)	No such part	0.00 FL	*- FL	
15	1		*REAR BUMPER BRACKET LH (NPA)	No such part	0.00 FL	*- FL	
16	1		*REAR STEP GARNISH CENTER (NPA)	No such part	0.00 FL	*- FL	
17	1		*SPARE TYRE BRACKET	Serviceable	175.00 FL	*- FL	
18	1		*TAILGATE ABSORBER LH	Not Necessary	277.10 FL	*- FL	
19	1		*TAILGATE ABSORBER RH	Not Necessary	277.10 FL	*- FL	
20	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
21	1		*REAR NUMBER PLATE	Serviceable	30.00 FS	*-FS	
22	1		*TAILGATE STICKER -70KM/H	Necessary	30.00 FS	*10.00 FS	
23	1		*TAILGATE ARM COVER	Not Necessary	12.40 FS	*-FS	
24	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS	
25	1		*END PANEL SEALANT	Necessary	152.40 FS	*50.00 FS	
26	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FS	*- FS	
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	5,449.51 489.67	3,958.60	
	- List Item Discount on L Items 10.00/10.00% (S\$)					365.86	
				Total Parts (S\$)	4,959.84	3,592.74	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	LABOUR TO REMOVE & REFIT NECESSARY PA	ARTS New	1,200.00	700.00				
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	700.00				
3	ANTI RUST COATING	New	250.00	60.00				
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	100.00				
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00				
	Gi	ross Labour Cost (S\$)	2,680.00	1,610.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.