

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19019828/EPA3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SMG896R	Insured Vehicle No :	SHA4505J	
Date of Loss: 28/10/2019	Nature of Claim: TP	Claim No: MCT19100753	

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG896R		
Make & Model:	MINI COOPER, 1.5 CLUBMAN AT LED (A)	Engine No:	F687H819B48A20A
Reg. Date:	15/11/2018 (Man. Year: 2018)	Chassis No:	WMWLN720302H56656
Colour:	Grey	Odometer:	11447 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35 R19	Rear Tyre Size:	225/35 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,767.94	2,615.82	152.12	5.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,720.00	820.00	32.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,307.94	4,335.82	972.12	18.31
+ GST 7.00/7.00% (S\$)	371.56	303.51	68.05	18.31
Nett Amount (S\$)	5,679.50	4,639.33	1,040.17	18.31
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
		4,839.33		

INSPECTION

Date of Assignment:	04/11/2019		
Date Inspected:	04/11/2019	Inspected At:	Eurokars Habitat Pte Ltd (HQ) 27A Tanjong Penjuru Level 5 Singapore 609042
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2020)
Parts:	144	MINI COOPER 1.5 CLUBMAN AT LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG896R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR MI	Repair	102.12 F	*- F
2	1		*COVER ,WHEEL	Cut	178.30 F	*178.30 F
3	1		*BLACK BAND S	Cut	302.90 F	*302.90 F
4	1		*EXPANDING RI	Necessary	0.65 F	*0.65 F
5	4		*BLIND RIVET	Necessary	4.96 F	*4.96 F
6	1		*GLOSS -TURNED	Cut	2,129.01 F	*2,129.01 F
7	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
					Total Parts (S\$)	2,767.94
						2,615.82

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE WING MIRROR COVER RH ,FRONT WHEEL ARCH RH ,FRONT SPOILER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	840.00
2	TO RESPRAY WING MIRROR COVER RH	New	350.00	200.00
3	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	0.00
Gross Labour Cost (\$\$)			2,540.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >