

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019841/KBA3Q2
Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant
Vehicle No : SHC5991X **Insured Vehicle No :** SKA4913D
Date of Loss: 05/11/2019 Nature of Claim: TP Claim No: 1151994146SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5991X**
Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002434
Reg. Date: 18/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280996
Colour: Metallic White/Red Odometer: 600282 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 8 mm Rear Left Side: Giti 7 mm
Front Right Side: Sailun 8 mm Rear Right Side: Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,175.47	5,553.35	20,622.12	78.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,200.00	1,520.00	17,680.00	92.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,375.47	7,073.35	38,302.12	84.41
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	45,375.47	5,650.00	39,725.47	87.55
+ GST 7.00/7.00% (S\$)	3,176.28	395.50	2,780.78	87.55
Nett Amount (S\$)	48,551.75	6,045.50	42,506.25	87.55
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$96.99/day) (S\$)		678.93		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,081.92		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 07/11/2019
Date Inspected: 07/11/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Bent / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	100.90 FL	*100.90 FL
13	1		*BUMPER BLOCK LH REAR	Serviceable	75.70 FL	*- FL
14	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*- FL
15	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	*- FL
16	1		*BOOT REAR	Buckled	1,677.20 FL	*1,677.20 FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
19	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
20	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
21	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
22	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
23	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
24	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
26	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
27	1		*BOOT INNER BOARD	Serviceable	611.00 FL	*- FL
28	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
29	1		*BOOT LOCK	Repair	246.60 FL	*- FL
30	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
31	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
32	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
33	2		*BOOT BUFFER	Serviceable	26.80 FL	*- FL
34	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
35	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
36	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
37	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
38	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
39	1		*WHEELARCH REAR LH	Serviceable	181.60 FL	*- FL
40	1		*FENDER PANEL INNER TRIM REAR RH	Repair	671.45 FL	*- FL
41	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
42	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
43	1		*AR VENT LH	Serviceable	59.40 FL	*- FL
44	1		*AIR VENT RH	Serviceable	59.40 FL	*- FL
45	1		*TAILLAMP RH	Mtg Cracked	313.10 FL	*313.10 FL
46	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
47	1		*TAILLAMP LH	Mtg Cracked	401.40 FL	*401.40 FL
48	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
49	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
50	1		*OUTER PANEL REAR (END PANEL) TRIM	Mtg Distorted	404.56 FL	*404.56 FL
51	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
52	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
53	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
55	1		*FUEL FLAP	Serviceable	244.70 FL	*- FL
56	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
57	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
58	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
59	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
60	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
61	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
62	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
63	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
64	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
65	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*- FS
66	1		*EXHAUST BRACKET REAR	Not Necessary	24.80 FS	*- FS
67	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
68	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
69	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
70	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
71	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
72	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
73	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
74	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
75	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
76	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
77	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
78	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
79	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
80	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
81	1		*REAR LEFT TYRE	Serviceable	300.00 FS	*- FS
82	1		*REAR LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
83	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
84	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
85	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
86	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
87	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
88	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,662.97	6,099.06
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,487.50	545.71
Total Parts (\$\$)	26,175.47	5,553.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	7,500.00	660.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL PARTS, ADJUST AND REALIGN THE SAME.	New	7,500.00	600.00
3	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	0.00
4	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }	New	170.00	60.00
7	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
11	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
13	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
14	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
16	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
17	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
18	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
19	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
Gross Labour Cost (\$\$)			19,200.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >