

ASS. REC. BY:

HKT:

(C3) MSH P0101849 V9+3M2

MS16/
ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 10766

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/11/19 @ 1.46pm Email EIA statement to MS16.
LTA 48552 3rd 100%

18/11/19 @ 1.33pm Email EIA report.
L/S # 13.400 confirmed with Alen (Ref to 38757.96, 74%)

19/11/19 @ 1.33pm Email to Christina Wong via Messenger.

RECEIVED 20 NOV 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 19/11/19

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / B/L:

MER-TP

13400

Veh No:

SKL 10766

Yr Regn:

9, 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A/

Make:

Toyota Camry

C.C.

2494

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

154079

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053AK500 4006135

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: N/A / SRim / STD A/Rim or

Tyre Size:

F:

215/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/11/19

D.O.I.

8/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 19/11/19

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / B/L:

MER-TP

13400

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Misc. and (\$

Survey Fee:

Transportation:

8 + RS \$

Photos

Other

Total

300

11

311

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 19 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLP4287L	Accident Date	: 07/11/2019
TP Vehicle No	: SKL1076G	Assignment Date	: 12/11/2019
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 9.00
Date of Inspection	: 08/11/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & o/s front portion and parts claimed are consistent to the accident. The undercarriage & chassis frame affected due to collision.

Repairer's Estimate (Gross)	:S\$	52,157.96
Revised Amount	:S\$	20,211.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,211.19
Lump Sum Repair	:S\$	13,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 12 November 2019 1:46 PM
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 07/11/2019, SKL 1076G (TP VEHICLE), SLP 4287L (OI VEHICLE)
Attachments: SKL1076 GIA STATEMENT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SKL 1076G at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



CAMRY

Price Range ▼

Depreciation ▼

2013 ▼

Vehicle Type ▼



Home » Used Cars » Karz Automobile » Toyota Camry 2.0A

Toyota Camry 2.0A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map


 SINGAPORE VEHICLE
TRADERS ASSOCIATION
A member of the
Singapore Vehicle Traders Association

Price \$62,388

 Depreciation ⓘ \$12,020 /yr
View models with similar depre

 Reg Date 02-Dec-2013
(4yrs 13days COE left)

Mileage 77,500 km (13k /yr)

Manufactured ⓘ 2013

Road Tax ⓘ \$1,210 /yr

Transmission Auto

Dereg Value ⓘ \$51,404 as of today (change)

OMV ⓘ \$25,490

COE ⓘ \$79,300

ARF ⓘ \$27,686

Engine Cap 1,998 cc

Power 109.0 kW (146 bhp)

Curb Weight ⓘ 1,445 kg

No. of Owners ⓘ 1

Type of Vehicle Luxury Sedan

Features

Powered By A Responsive And Fuel Efficient 2.0L DOHC VVT-I Engine, ABS, Airbags. Multi Functions Steering, Auto Head Lights, Dual Electric Seats. View specs of the Toyota Camry (2012-2015)

Accessories

Factory Fitted DVD Audio System/Navigation/Bluetooth/Reverse Camera. Dual Electric Leather Seats. Auto Headlights And Rain Sensors. Sports Rims.

Description

A Luxury Japan Sedan With Great Reliability Rating, Ride Comfort And Roomy Interior Cabin Space, Perfect Car For The Family Outing And Your Daily Workhorse, Super Well Taken Care Unit By Previous Owner With No Repairs Required, Safe Buy, Selling Close To Export Price, Full Loan Options Is Available With High Trade In, Don't Miss The Chance To Own This Unit, Call Us For Viewing And Test Drive Today


Cat

Compare



Location Map

Price Chart



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



HUAWEI Ma

toyota camry

Price Range

Depreciation

2012

Vehicle Type

Home » Used Cars » Dynamic Motoring » Toyota Camry 2.0A

Toyota Camry 2.0A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Dynamic Motoring

Insurance Agency

INCOME

Liberty Insurance

ERGO

Dynamic Motoring

QBE

Insurance

Insurance

Insurance



Location Map

Price	\$48,800		
Depreciation	\$13,080 /yr View models with similar depre	Reg Date	13-Sep-2012 (2yrs 10mths 4days COE left)
Mileage	116,000 km (16.2k /yr)	Manufactured	2012
Road Tax	\$1,210 /yr	Transmission	Auto
Dereg Value	\$40,638 as of today (change)	OMV	\$23,138
COE	\$93,990	ARF	\$23,138
Engine Cap	1,998 cc	Power	109.0 kW (146 bhp)
Curb Weight	1,445 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		

Features

Luxurious Spacious And Responsive 2.0L 4 Cylinders 16 Valves Engine. Smooth Auto Transmission. Airbags, Multi Function Steering Wheel Control! View specs of the Toyota Camry (2012-2015)

Accessories

Factory Fitted Audio System With USB. Bluetooth. Electrical Seats, Auto Headlights, Retractable Mirrors With Indicators.

Description

\$0 Down Payment! Offer Bank Interest Rate From 1.98%! Best Seller 2012 Toyota Camry 2.0A Luxury Yet Spacious Sedan On Sale Now! New Facelift Model! High ARF \$23K! Highest COE \$93K High Paper Value! Wear & Tear Replaced. Trade In Welcome. Come View This Probably The Best Toyota Camry Condition In Town! Viewing Strictly By Appointment Only.

Call

Compare

https://www.sgcar mart.com/used_cars/info.php?ID=866186&DL=3043

Shortlist

Compare

Report Error

More Action

Seller Information

Company

Dynamic Mo



» dealer's price!

» 39 vehs sold |

Address

8 Kaki Bukit Ave

Search cars near

Location

Premier @ Kaki

Website

dynamicmotorin

Office No

63866020

Contact Person(s)

Dickson

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 564B

Vehicle Details

Vehicle No.: SKL1076G
Vehicle to be Exported: No
Intended Deregistration Date: 11 Nov 2019
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.5 AT
Primary Colour: Silver
Manufacturing Year: 2013
Engine No.: 2ARU063371
Chassis No.: MR053AK5004006135
Maximum Power Output: 133.0 kW (178 bhp)
Open Market Value: \$27,547.00
Original Registration Date: 27 Sep 2013
First Registration Date: 27 Sep 2013
Transfer Count: 1
Actual ARF Paid: \$30,566.00 15483

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Sep 2023
PARF Rebate Amount: \$19,867.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$76,607.00
COE Rebate Amount: \$29,685.00
Total Rebate Amount: \$49,552.00

The information contained herein is correct as at 08 Nov 2019

OK

Date of Accident : 07 11 2019 Accident Time: 10 05 (24-HR-Format)
Accident Place : 1 North link Slim Binacks Rise
Vehicle No. (Car Plate No.) : SKL 10766 Make/Model: Toyota Camry
Insurance Company : FWD Policy No: PNPV 2018 - 00012482-01
Owner or Company Name / IC No. : Yung Yew Hon David (S1733564B)
Owner or Company Contact No. : 96622 807 Owner's Hp Company Tel
DRIVER'S Name / IC No. : Sally Eng Koa Koon (S1736003E)
DRIVER'S Date Of Birth : 28 07 1966 DRIVER'S License Pass Date 28 01 1988
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others:
DRIVER'S Address : B1K 607 chao chu tang street 62 #05-127 (S) 680607
DRIVER'S Contact No / Alt No. : 1) 9111 1117 2)
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address :
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim \ Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 1 Driver
Was there any video Captured by car camera: YES (NO)
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any injury (If YES, Pls state): Yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SLP 4287L</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:



FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
N/A
8/11/18
1/5H 13.400/
9dy.

VEHICLE NO: SKL1076G

QTY	PARTICULAR			
1 PCS	BONNET		BUC	\$1,267.40 ✓
2 PCS	BONNET HINGES @\$52.60		o/s bent	\$105.20 1PC
1 PCS	BONNET RUBBER	45.00	MR	\$66.00 ✓
1 PCS	BONNET LOCK		2W	\$145.20 ✓
1 PCS	BONNET INSULATOR		11	\$356.85 X
1 SET	BONNET INSULATOR CLIPS		11	\$50.00 X
1 PCS	BONNET LOCK CABLE		11	\$162.50 X
1 PCS	BONNET FRONT CHROME MOULDING	168.50	C/A	\$381.10 ✓
1 PCS	FRONT BUNPER	421.10	D.S	\$615.40 ✓
2 PCS	FRONT BUMPER SIDE HOLDERS @\$66.50		Bent	\$133.00 ✓
1 PCS	FRONT BUMPER CENTRE GRILLE	145.20	D.S	\$211.20 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	340.19	D/S	\$520.50 ✓
1 PCS	FRONT BUMPER SPONGE		70.1	\$185.40 ✓
1 PCS	FRONT BUMPER LICENCE PLATE GARNISH		11	\$69.50 X
1 SET	FRONT BUMPER CLIPS		MR	\$50.00 ✓
1 PCS	FRONT BUMPER TOW COVER	20.50	70.1	\$312.30 ✓
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$165.00	105.10	o/s MR	\$330.00 1PC
2 PCS	FRONT BUMPER FOG LAMPS @\$425.00	348.30	o/s CUC	\$850.00 1PC
1 PCS	FRONT BUMPER LOWER COVER		11	\$312.30 X
1 PCS	FRONT GRILLE	439.52	C/A	\$670.50 ✓
1 PCS	FRONT GRILLE LOGO		MR	\$59.60 ✓
1 PCS	FRONT SUPPORT PANEL	845.10	Bent/2W	\$911.10 ✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH		70.1	\$366.20 ✓
1 PCS	FRONT BRACE PANEL		2W	\$151.20 ✓
2 PCS	HEADLAMP ASSY HIDS @\$2800.00	2410.10 x 2 = 4820.20	110/320	\$5,600.00 ✓
1 PCS	AIR DUCT		C/A	\$192.30 ✓
2 PCS	FRONT FENDERS @\$775.10	581.95 MR	o/s BUC	\$1,163.90 1PC
2 PCS	FRONT FENDER INNERSHIELDS @\$181.50		o/s 2W	\$363.00 1PC
1 SET	FRONT FENDER INNERSHIELD CLIPS		MR	\$50.00 ✓
2 PCS	FRONT FENDER VVTI EMBLEMS @\$66.50		MR	\$133.00 ✓
1 PCS	WIPER WASHER TANK		D.S	\$215.20 ✓
1 PCS	AIR CON CONDENSER		Bent/2W	\$1,485.91 ✓
1 PCS	AIR CON FAN MOTOR ASSY		11	\$489.50 X
2 PCS	AIR CON SIDE GARNISHS @\$96.10		o/s 2W	\$196.20 1PC
1 PCS	AIR CON SUCTION HOSE		11	\$388.20 X
1 PCS	AIR CON DISCHARGE HOSE		11	\$399.20 X
1 PCS	AIR CON LIQUID PIPE		11	\$211.40 X
1 PCS	RADIATOR	1689.10	Bent/2W	\$1,881.20 ✓
1 PCS	RADIATOR FAN MOTOR	425.10	20/2W	\$488.50 ✓
1 PCS	RADIATOR FAN COWLING	166.50	C/A	\$266.20 ✓
2 PCS	FRONT CHASSIS MEMBERS @\$1050.00		R	\$2,100.00 X
1 PCS	FRONT SHOCK ABSORBER O/S		11	\$692.30 X
1 PCS	FRONT KNUCKLE ARM O/S		11	\$545.50 X
1 PCS	FRONT KNUCKLE ARM BEARING O/S		11	\$250.00 X
1 PCS	FRONT LOWER ARM O/S		11	\$699.50 X
1 PCS	FRONT sport rim o/s		Bent	\$2,112.50 4005. ✓

(257)

1 PCS	AIR BAG DRIVER	1845.20
1 PCS	AIR BAG PASSENGER	2622.30
1 PCS	AIR BAG SPIRAL SENSOR	195.50
1 PCS	AIR BAG IMPACT SENSOR	
2 PCS	SEATBELTS @\$950.00	645.25 x 2 = 1290.50
2 PCS	SEATBELT BUCKLES @\$450.00	
1 PCS	DASHBOARD	
1 PCS	FRONT WINDSCREEN	845.30
1 PCS	FRONT WINDSCREEN MOULDING	109.60
1 PCS	ABS PUMP	
1 PCS	FRONT WINDSCREEN SEALANT	
1 PCS	FRONT LICENCE PLATE W/HOLDER	
1 SET	FRONT PARKING SENSOR	


Actual	\$2,280.10	
Actual	\$3,350.20	
Actual	\$265.00	
11	\$250.50	X
Actual	\$1,900.00	
11	\$900.00	X
11	\$1,650.00	X
11	\$1,120.20	X
11	\$151.00	X
11	\$4,850.00	X
11	\$50.00	X
310	\$50.00	405.00
1100	\$250.00	2025.00
	\$45,272.96	

LABOUR CHARGES
TOWING CHARGE
TO CHECK WIRING
TO REFILL AIR CON GAS
TO DISMANTLE & REPLACING FRONT WINDSCREEN
TO DISMANTLE & REFIX ENGINE
TO DISMANTLE & REFIX FRONT DASHBOARD
TO CONDUCT WHEEL ALIGNMENT
TO SPRAY RUST PROOFING
TO DISMANTLE & REFIX FRONT UNDERCARRIAGE
TO RESET & REPROGRAMME AIR BAG SYSTEM
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$65.00	50
	\$80.00	30
	\$150.00	100
11	\$150.00	X
11	\$380.00	X
	\$380.00	260
	\$120.00	60
	\$180.00	90
11	\$380.00	X
	\$500.00	300
	\$2,500.00	1200
	\$2,000.00	1300
TOTAL	\$52,157.96	

21794.12
16345.59

63390
5-6440
7-16345.59
20375.59



LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19019843/UQF3N2

Date: 20/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SKL1076G	Insured Vehicle No :	SLP4287L
Date of Loss:	07/11/2019	Nature of Claim:	TP
		Claim No:	610947

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL1076G	Engine No:	2ARU063371
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004006135
Reg. Date:	27/09/2013 (Man. Year: 2013)	Odometer:	154079 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	45,272.96	16,676.33	28,596.63	63.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,885.00	3,390.00	3,495.00	50.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,157.96	20,066.33	32,091.63	61.53
Approved Total (Overridden) (S\$)		13,400.00		
(S\$)	52,157.96	13,400.00	38,757.96	74.31
+ GST 7.00/7.00% (S\$)	3,651.06	938.00	2,713.06	74.31
Nett Amount (S\$)	55,809.02	14,338.00	41,471.02	74.31

INSPECTION

Date of Assignment:	12/11/2019		
Date Inspected:	08/11/2019	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	9.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2019)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL1076G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,267.40 F	*1,267.40 FL
2	1		*BONNET HINGES	O/s Bent	105.20 F	*52.60 FL
3	1		*BONNET RUBBER	Necessary	66.00 F	*45.00 FL
4	1		*BONNET LOCK	Twisted	145.20 F	*145.20 FL
5	1		*BONNET INSULATOR	Not Necessary	356.85 F	*- FL
6	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
7	1		*BONNET LOCK CABLE	Not Necessary	162.50 F	*- FL
8	1		*BONNET FRONT CHROME MOULDING	Cracked	381.10 F	*168.80 FL
9	1		*FRONT BUMPER	Distorted	615.40 F	*521.10 FL
10	2		*FRONT BUMPER SIDE HOLDERS	Bent	133.00 F	*133.00 FL
11	1		*FRONT BUMPER CENTRE GRILLE	Distorted	211.20 F	*145.20 FL
12	1		*FRONT BUMPER REINFORCEMENT	Distorted	520.50 F	*340.19 FL
13	1		*FRONT BUMPER SPONGE	Torn	185.40 F	*185.40 FL
14	1		*FRONT BUMPER LICENCE PLATE GARNISH	Not Necessary	69.50 F	*- FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	1		*FRONT BUMPER TOW COVER	Torn	312.30 F	*20.50 FL
17	1		*FRONT BUMPER FOG LAMP COVERS	O/s Cracked	330.00 F	*105.10 FL
18	1		*FRONT BUMPER FOG LAMPS	O/s Cracked	850.00 F	*348.30 FL
19	1		*FRONT BUMPER LOWER COVER	Not Necessary	312.30 F	*- FL
20	1		*FRONT GRILLE	Cracked	670.50 F	*439.52 FL
21	1		*FRONT GRILLE LOGO	Necessary	59.60 F	*59.60 FL
22	1		*FRONT SUPPORT PANEL	Bent/Twisted	911.10 F	*845.10 FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Torn	366.20 F	*366.20 FL
24	1		*FRONT BRACE PANEL	Twisted	151.20 F	*151.20 FL
25	2		*HEADLAMP ASSY HIDS	Cracked/Broken	5,600.00 F	*4,820.20 FL
26	1		*AIR DUCT	Cracked	192.30 F	*192.30 FL
27	1		*FRONT FENDERS	O/s Buckled/N/s Repair	1,163.90 F	*581.95 FL
28	1		*FRONT FENDER INNERSHIELDS	O/s Torn	363.00 F	*181.50 FL
29	1		*SET FRONT FENDER INNERSHIELD CLIPS	Necessary	50.00 F	*50.00 FL
30	2		*FRONT FENDER VVTI EMBLEMS	Necessary	133.00 F	*133.00 FL
31	1		*WIPER WASHER TANK	Distorted	215.20 F	*215.20 FL
32	1		*AIR CON CONDENSER	Bent/Punctured	1,485.91 F	*1,485.91 FL
33	1		*AIR CON FAN MOTOR ASSY	Not Necessary	489.50 F	*- FL
34	1		*AIR CON SIDE GARNISHS	O/s Torn	196.20 F	*98.10 FL
35	1		*AIR CON SUCTION HOSE	Not Necessary	388.20 F	*- FL
36	1		*AIR CON DISCHARGE HOSE	Not Necessary	399.20 F	*- FL
37	1		*AIR CON LIQUID PIPE	Not Necessary	211.40 F	*- FL
38	1		*RADIATOR	Bent/Punctured	1,881.20 F	*1,689.10 FL
39	1		*RADIATOR FAN MOTOR	Dented/Jammed	488.50 F	*425.10 FL
40	1		*RADIATOR FAN COWLING	Cracked	266.20 F	*166.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*FRONT CHASSIS MEMBERS	Repair	2,100.00 F	*- FL
42	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	692.30 F	*- FL
43	1		*FRONT KNUCKLE ARM O/S	Not Necessary	545.50 F	*- FL
44	1		*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	250.00 F	*- FL
45	1		*FRONT LOWER ARM O/S	Not Necessary	699.50 F	*- FL
46	1		*AIR BAG DRIVER	Activated	2,280.10 F	*1,845.20 FL
47	1		*AIR BAG PASSENGER	Activated	3,350.20 F	*2,622.30 FL
48	1		*AIR BAG SPIRAL SENSOR	Activated	265.00 F	*195.50 FL
49	1		*AIR BAG IMPACT SENSOR	Not Necessary	250.50 F	*- FL
50	2		*SEATBELTS	Activated	1,900.00 F	*1,290.50 FL
51	2		*SEATBELT BUCKLES	Not Necessary	900.00 F	*- FL
52	1		*DASHBOARD	Not Necessary	1,650.00 F	*- FL
53	1		*FRONT WINDSCREEN (CRACKED)	Not Consistent With The Impact	1,120.20 F	*- FL
54	1		*FRONT WINDSCREEN MOULDING	Not Necessary	151.00 F	*- FL
55	1		*ABS PUMP	Not Necessary	4,850.00 F	*- FL
56	1		*FRONT WINDSCREEN SEALANT	Not Necessary	50.00 F	*- FL
57	1		*FRONT LICENCE PLATE W/HOLDER	Broken	50.00 FS	*40.00 FS
58	1		*SET FRONT PARKING SENSOR	Shorted	250.00 FS	*200.00 FS
59	1		*FRONT SPORT RIM O/S	Bent	2,112.50 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 45,272.96 22,021.77
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 5,345.44
Total Parts (\$\$) 45,272.96 16,676.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	65.00	50.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO REFILL AIR CON GAS	New	150.00	100.00
4	TO DISMANTLE & REPLACING FRONT WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX ENGINE	New	380.00	0.00
6	TO DISMANTLE & REFIX FRONT DASHBOARD	New	380.00	260.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
8	TO SPRAY RUST PROOFING	New	180.00	90.00
9	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	380.00	0.00
10	TO RESET & REPROGRAMME AIR BAG SYSTEM	New	500.00	300.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,500.00	1,200.00
12	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,300.00
Gross Labour Cost (S\$)			6,885.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >