

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQ19019852/T1VD3E2
Date: 26/01/2021

REFERENCE

Handling Insurer:	EQ Insurance Company Ltd	Policy No:	
Claimant Vehicle No :	GBB2469J	Insured Vehicle No :	YN5354B
Date of Loss:	14/10/2019	Nature of Claim:	TP
		Claim No:	DM19HO02808/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB2469J		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD1868625
Reg. Date:	15/10/2008 (Man. Year: 2008)	Chassis No:	JTFAT35Y20K200093
Colour:	White	Odometer:	383648 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/80 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,446.30	1,013.30	433.00	29.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,460.00	620.00	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,526.30	2,473.30	1,053.00	29.86
Approved Total (Overridden) (\$\$)		1,950.00		
(\$\$)	3,526.30	1,950.00	1,576.30	44.70
+ GST 7.00/7.00% (\$\$)	246.84	136.50	110.34	44.70
Nett Amount (\$\$)	3,773.14	2,086.50	1,686.64	44.70

INSPECTION

Date of Assignment:	21/10/2020	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	30/11/2020	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB2469J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Repair	155.00 F	*- F
2	1		*FRT BUMPER H/LAMP RH (WCP)	Cut	220.00 F	*220.00 F
3	1		*FRT GRILLE (WCP)	Cracked	160.00 F	*160.00 F
4	1		*FRT GRILLE TOP SEAL (WCP)	Necessary	15.00 F	*15.00 F
5	10		*FRT GRILLE CLIP (WCP)	Necessary	20.00 F	*20.00 F
6	1		*FRT GRILLE EMBLEM (WCP)	Necessary	28.00 F	*28.00 F
7	1		*FRT PANEL (WCP)	Bent	350.00 F	*350.00 F
8	1		*FRT PANEL TOP CTR GARNISH (WCP)	Not Necessary	120.00 F	*- F
9	1		*FRT PANEL TOP RH GARNISH (WCP)	Cut	45.00 F	*45.00 F
10	1		*FRT CORNER PANEL RH (WCP)	Bent	65.00 F	*65.00 F
11	1		*FRT WINDSCREEN RUBBER (WCP)	Not Necessary	95.00 F	*- F
12	1		*ERP STICKER	Not Necessary	26.00 FS	*- FS
13	1		*FRT DOOR ROC STICKER RH	Necessary	20.00 FS	*20.00 FS
					Sub Total (\$\$)	1,319.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	127.30
					Total Parts (\$\$)	1,446.30
						923.00
						1,013.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT DOOR RH,WELD, REMOVE & REPLACE ABOVE PARTS	New	800.00	700.00
2	TO PUTTY & RESPRAY PAINTING ON FRT BUMPER,FRT PANEL , WIPER ARM COVER RH,FRT DOOR RH & AFFECTEDS AREA.	New	800.00	700.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE & REFIC FRT DASHBOARD	New	180.00	0.00
5	TO REMOVE & REFIX FRT WINDSCREEN	New	150.00	0.00
6	TO APPLY ANTI RUST COAT	New	120.00	30.00
Gross Labour Cost (\$\$)			2,080.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >