

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19019887/UKA3Q2

**Date:** 09/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** FBJ895H **Insured Vehicle No :** SLV7344D

**Date of Loss:** 25/10/2019 **Nature of Claim:** TP **Claim No:** 7265042890SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBJ895H</b>	Engine No:	E3J3E712944
Make & Model:	YAMAHA MIO I, 125cc	Chassis No:	MLESE572111712944
Reg. Date:	27/12/2013 (Man. Year: 2013)	Odometer:	87840 km
Colour:	Multi-colour		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70-90-14	Rear Tyre Size:	90-90-14
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,691.00	1,645.80	3,045.20	64.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	315.00	545.00	63.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,551.00</b>	<b>1,960.80</b>	<b>3,590.20</b>	<b>64.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,551.00</b>	<b>1,550.00</b>	<b>4,001.00</b>	<b>72.08</b>
<b>+ Loss of Use (6.0 x S\$20.00/day) (S\$)</b>		120.00		
<b>Nett Liability (S\$)</b>		<b>1,670.00</b>		

### INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 07/11/2019 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)  
1 Kaki Bukit Avenue 6, #02-62  
AutoBay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Serviceable	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
3	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
4	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
6	1		*HANDLE-BAR	Bent	88.00 FL	*88.00 FL
7	1		*HANDLE-BAR ENDS	O/S Cut	64.00 FL	*32.00 FL
8	1		*SET HAND GRIP	Torn	55.00 FL	*55.00 FL
9	1		*HANDLE -BAR INNER BRACKET	Not Necessary	68.00 FL	*- FL
10	1		*SIDE MIRRORS	O/S Cut	110.00 FL	*55.00 FL
11	1		*CLUTCH LEVER (Scratched)	Not Consistent With The Impact	30.00 FL	*- FL
12	1		*BRAKE LEVER	Scratched	32.00 FL	*32.00 FL
13	2		*FRONT SIGNALS	Not Necessary	140.00 FL	*- FL
14	1		*HEADLAMP	Cracked	285.00 FL	*285.00 FL
15	1		*SET FAIRING ASSY	Deep Cut	580.00 FL	*580.00 FL
16	1		*RADIATOR GRILLE COVER	Not Necessary	125.00 FL	*- FL
17	1		*REAR FOOTREST -R/H	Cut	40.00 FL	*40.00 FL
18	1		*EXHAUST ASSY	Repair	485.00 FL	*- FL
19	1		*EXHAUST PROTECTOR	Cut	60.00 FL	*60.00 FL
20	1		*STEP BOARD PANEL	Cut	285.00 FL	*285.00 FL
21	1		*REAR FENDER	Repair	120.00 FL	*- FL
22	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
23	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
24	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
25	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
26	1		*REAR BOX	Cut	250.00 FS	*180.00 FS
27	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
28	1		*ERP IU	Not Necessary	175.00 FS	*- FS
29	1		*SET STICKER	Necessary	95.00 FS	*95.00 FS
30	1		*DELIVERY BAG	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,054.00</b>	<b>1,797.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	363.00	151.20
<b>Total Parts (\$)</b>	<b>4,691.00</b>	<b>1,645.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	280.00
4	TO REPAIR BODY FRAME	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>860.00</b>	<b>315.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >