

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019909/UPA3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900165395

Claimant
Vehicle No : SLD4590Z **Insured Vehicle No :** GBH8267D

Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: 7411104084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD4590Z	Engine No:	27186030003913
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A080975
Reg. Date:	12/11/2009 (Man. Year: 2009)	Odometer:	159464 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Jinyu 6 mm	Rear Left Side:	Jinyu 6 mm
Front Right Side:	Jinyu 6 mm	Rear Right Side:	Jinyu 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,266.20	11,040.11	10,226.09	48.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	2,350.00	2,820.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,436.20	13,390.11	13,046.09	49.35
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	26,436.20	10,500.00	15,936.20	60.28
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		11,496.45		

INSPECTION

Date of Assignment: 08/11/2019

Date Inspected: 08/11/2019 Inspected At: Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -L/H	Badly Dented	2,235.00 FL	*2,080.00 FL
2	1		*FRONT DOOR INNER BOARD	Not Necessary	1,000.00 FL	*- FL
3	1		*FRONT DOOR LOCK	Serviceable	435.00 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE	Cut	530.00 FL	*425.00 FL
5	1		*FRONT DOOR CHROME MOULDING	Necessary	165.00 FL	*165.00 FL
6	1		*FRONT DOOR REGULATOR	Not Necessary	650.00 FL	*- FL
7	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	590.00 FL	*- FL
8	1		*FRONT DOOR SIDE MIRROR	Not Necessary	758.00 FL	*- FL
9	1		*FRONT DOOR WEATHERSTRIP	Necessary	295.00 FL	*295.00 FL
10	1		*FRONT DOOR LOWER RUBBER SEAL	No such part	190.00 FL	*- FL
11	1		*REAR DOOR -L/H	Badly Dented	2,235.00 FL	*2,065.00 FL
12	1		*REAR DOOR CHECKER	Not Necessary	155.00 FL	*- FL
13	2		*REAR DOOR HINGES	Not Necessary	330.00 FL	*- FL
14	1		*REAR DOOR INNER BOARD	Warped / Cracked	950.00 FL	*950.00 FL
15	1		*REAR DOOR OUTER HANDLE	Cut	495.00 FL	*425.00 FL
16	1		*REAR DOOR REGULATOR	Bent	358.00 FL	*358.00 FL
17	1		*REAR DOOR REGULATOR MOTOR	Jammed	485.00 FL	*485.00 FL
18	1		*REAR DOOR WEATHERSTRIP	Necessary	280.00 FL	*280.00 FL
19	1		*REAR DOOR LOWER RUBBER SEAL	No such part	185.00 FL	*- FL
20	1		*REAR WINDSCREEN REPAIR KIT	Necessary	195.00 FL	*195.00 FL
21	1		*REAR BUMPER	Deformed / Cut	2,094.00 FL	*1,537.12 FL
22	1		*REAR BUMPER SIDE CHROME MOULDING	Necessary	155.00 FL	*155.00 FL
23	1		*REAR BUMPER SIDE RETAINER	Not Necessary	48.00 FL	*- FL
24	1		*REAR FENDER	Badly Dented	2,185.00 FL	*2,185.00 FL
25	1		*REAR FENDER INNER SHIELD	Not Necessary	186.00 FL	*- FL
26	1		*REAR SPORT RIM	Cut	1,080.00 FS	*600.00 FS
27	1		*REAR WHEEL BEARING WITH HUB	Not Necessary	316.00 FL	*- FL
28	1		*REAR SHOCK ABSORBER	Not Necessary	520.00 FL	*- FL
29	1		*REAR KNUCKLE ARM	Not Necessary	1,265.00 FL	*- FL
30	1		*REAR CONTROL ARM	Not Necessary	530.00 FL	*- FL
31	1		*REAR LOWER ARM	Not Necessary	520.00 FL	*- FL
32	1		*REAR STAY ARM	Not Necessary	608.00 FL	*- FL
33	1		*REAR TOP ARM	Not Necessary	435.00 FL	*- FL
34	1		*REAR TRAILING ARM	Not Necessary	440.00 FL	*- FL
35	1		*REAR TYRE	Serviceable	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,448.00	12,200.12
- List Item Discount on L Items 10.00/10.00% (\$)	2,181.80	1,160.01
Total Parts (\$)	21,266.20	11,040.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT DOOR FITTINGS & REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	120.00
2	TO REMOVE ,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL	New	400.00	0.00
9	TO APPLY UNDERCOATING	New	200.00	80.00
10	PANEL BEATING	New	1,600.00	800.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			5,170.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >