

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019949/KBA3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant
Vehicle No : SMD8001U **Insured Vehicle No :** SLX7821H

Date of Loss: 11/01/2019 **Nature of Claim:** TP **Claim No:** 8664663774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD8001U	Engine No:	HIDDEN
Make & Model:	VOLVO V40, 1.5 T2 (A)	Chassis No:	YV1MV28H0H2390831
Reg. Date:	01/12/2016 (Man. Year: 2016)	Odometer:	38986 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	250.00	150.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	400.00	250.00	150.00	37.50
+ GST 7.00/7.00% (S\$)	28.00	17.50	10.50	37.50
Nett Amount (S\$)	428.00	267.50	160.50	37.50
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 12/11/2019 Inspected At: Ricardo Auto Centre Pte Ltd (HQ)
160 Sin Ming Drive, #02-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND SPRAY PAINT ON FRONT BUMPER	New	400.00	250.00
Gross Labour Cost (\$\$)			400.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >