

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19019970/KEA3Q2

**Date:** 30/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SGG8203J **Insured Vehicle No :** SLE9372Z

Date of Loss: 29/10/2019 Nature of Claim: TP Claim No: 4374388353SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGG8203J</b>		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2569269
Reg. Date:	24/05/2006 (Man. Year: 2006)	Chassis No:	ZNE100306144
Colour:	Metallic Grey	Odometer:	286030 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Continental 3 mm	Rear Right Side:	Michelin 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,286.80	1,757.44	2,529.36	59.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,315.00	645.00	32.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,246.80</b>	<b>3,072.44</b>	<b>3,174.36</b>	<b>50.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,450.00</b>		
<b>(S\$)</b>	6,246.80	2,450.00	3,796.80	60.78
<b>+ GST 7.00/7.00% (S\$)</b>	437.28	171.50	265.78	60.78
<b>Nett Amount (S\$)</b>	<b>6,684.08</b>	<b>2,621.50</b>	<b>4,062.58</b>	<b>60.78</b>
<b>+ Loss of Use (6.0 x S\$80.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,103.50</b>		

### INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 24/03/2020 Inspected At:

Ah Lim Motor Company (AMK)  
10 Ang Mo Kio Industrial Park 2A,  
#01-09 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN M/SIDE/LOWERROULding TOP	Necessary	70.20 FL	*70.20 FL
2	1		*TAILGATE	Bent	1,472.30 FL	*1,472.30 FL
3	1		*TAILGATE EMBLEM	Necessary	68.50 FL	*68.50 FL
4	1		*TAILGATE INNER LOCK	Repair	490.40 FL	*- FL
5	1		*TAILGATE RUBBER	Serviceable	362.30 FL	*- FL
6	1		*TAILLAMP RH	Serviceable	524.70 FL	*- FL
7	1		*REAR BUMPER	Buckled	524.30 FL	*524.30 FL
8	1		*REAR BUMPER SIDE RETAINER RH	Distorted	69.60 FL	*69.60 FL
9	15		*REAR BUMPER CLIPS	Necessary	58.35 FL	*58.35 FL
10	1		*REAR BUMPER REFLECTOR RH	Serviceable	57.60 FL	*- FL
11	1		*REAR END PANEL	Serviceable	568.70 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Serviceable	265.30 FL	*- FL
13	1		*REAR EXHAUST PIPE	Repair	790.15 FL	*- FL
14	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
15	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
16	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
17	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,617.40</b>	<b>2,323.25</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,330.60</b>	<b>565.81</b>
<b>Total Parts (\$\$)</b>	<b>4,286.80</b>	<b>1,757.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	80.00	50.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO REALIGN ,DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS,TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
7	TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL	New	800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>1,960.00</b>	<b>1,315.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**