

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019989/KDA3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994303

Claimant
Vehicle No : SLJ3328R **Insured Vehicle No :** GBC4416T

Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: 0790802942SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ3328R	Engine No:	2ZR1862204
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20WX0J006120
Reg. Date:	06/12/2016 (Man. Year: 2016)	Odometer:	57255 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,060.73	4,385.43	4,675.30	51.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	2,140.00	1,100.00	33.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,300.73	6,525.43	5,775.30	46.95
+ GST 7.00/7.00% (\$\$)	861.05	456.78	404.27	46.95
Nett Amount (\$\$)	13,161.78	6,982.21	6,179.57	46.95
+ Loss of Use (6.0 x S\$80.00/day) (\$\$)		480.00		
Nett Liability (\$\$)		7,462.21		
Global Sum Settlement (\$\$)		7,460.00		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Ricardo Auto Centre Pte Ltd (HQ)
160 Sin Ming Drive, #02-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,615.90 F	*1,209.65 FL
2	1		*TAILGATE TOYOTA LOGO	Necessary	66.15 F	*66.15 FL
3	1		*TAILGATE PLATE VALVE MATIC	Necessary	45.00 F	*45.00 FL
4	1		*TAILGATE OUTER GARNISH (CHROME)	Cracked	298.70 F	*298.70 FL
5	2		*REAR LAMP LH & RH	Serviceable	731.40 F	*- FL
6	1		*BACK DOOR TRIM BOARD	Serviceable	375.40 F	*- FL
7	1		*BACK DOOR LOCK	Dented	402.60 F	*402.60 FL
8	1		*BACK DOOR OPENER	Serviceable	149.80 F	*- FL
9	2		*BACK DOOR HINGES LH & RH	Repair	137.40 F	*- FL
10	1		*REAR END PANEL	Bent	580.20 F	*580.20 FL
11	1		*BACK DOOR SCUFF PLATE	Mtg Distorted	278.66 F	*278.66 FL
12	1		*REAR BUMPER	Bent	688.90 F	*605.10 FL
13	10		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
14	1		*REAR BUMPER REFLECTOR LH	Cracked	54.70 F	*54.70 FL
15	1		*REAR BUMPER ARM LH	Distorted	97.66 F	*97.66 FL
16	1		*REAR BUMPER SIDE SUPPORT LH & RH	N/S Distorted	190.00 F	*95.00 FL
17	1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Distorted	186.20 F	*93.10 FL
18	1		*REAR FENDER LH	Repair	898.50 F	*- FL
19	1		*REAR COMBINATION LAMP LH	Serviceable	289.70 F	*- FL
20	1		*BACK DOOR WEATHERSTRIP	Dented / Distorted	381.10 F	*381.10 FL
21	1		*REAR FENDER INNER TRIM LH	Cracked	679.40 F	*679.40 FL
22	2		*BACK WINDSCREEN MOULDING LH & RH	Necessary	140.40 F	*140.40 FL
23	1		*BACK WINDSCREEN MOULDING TOP	Necessary	68.00 F	*68.00 FL
24	1		*BACK WINDSCREEN MOULDING BOTTOM	Necessary	70.20 F	*70.20 FL
25	1		*REAR NO PLATE WITH HOLDER	Dented	45.00 FS	*45.00 FS
26	1		*SUPPLY WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
27	1		*EXHAUST MOUNTING	Serviceable	48.70 F	*- FL
28	1		*SET REAR BUMPER SENSOR (ORIGINAL)	Shorted	201.70 FS	*201.70 FS
29	1		*REAR BUMPER ARM RH	Cracked	97.66 F	*97.66 FL
30	1		*ANTENNA ELECTRICAL KEY	Cracked	161.70 F	*161.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,060.73	5,751.68
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,366.25
Total Parts (\$)	9,060.73	4,385.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE REAR WINDSCREEN GLASS ENABLE TO REPLACE NEW BACK DOOR	New	100.00	100.00
2	TO TUFF COAT AFFECTED AREA	New	100.00	60.00
3	TO REMOVE INNER TRIM AND ATTACHED PARTS ENABLE TO REPLACE LH REAR INNER TRIM BOARD & FIX SAME	New	300.00	80.00
4	TO CUT ,WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT ADJUST & REPLACE DAMAGE PARTS	New	1,400.00	900.00
5	TO REPSRAY ON REPAIRED AREAS	New	1,200.00	1,000.00
6	COMPUTERIZED WHEEL ALIGNMENT	New	60.00	0.00
7	TO REPAIR EXHAUST TAIL PIPE	New	80.00	0.00
Gross Labour Cost (\$)			3,240.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >