

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19020032/AKA3N2**Date:** 20/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant
Vehicle No : EQ1415G **Insured Vehicle No :** SKM289K
Date of Loss: 01/11/2019 Nature of Claim: TP Claim No: 4131111006SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EQ1415G**
Make & Model: HONDA HR-V, 1.5 LX CVT (A) Engine No: L15Z71000884
Reg. Date: 12/11/2015 (Man. Year: 2015) Chassis No: MRHRU1830FP000473
Colour: Black Odometer: 75698 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,011.37	3,210.25	3,801.12	54.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,390.00	1,910.00	57.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,311.37	4,600.25	5,711.12	55.39
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	10,311.37	3,650.00	6,661.37	64.60
+ GST 7.00/7.00% (S\$)	721.80	255.50	466.30	64.60
Nett Amount (S\$)	11,033.17	3,905.50	7,127.67	64.60
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,267.50		
Global Sum Settlement (S\$)		4,260.00		

INSPECTION

Date of Assignment: 11/11/2019
Date Inspected: 11/11/2019 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR WEATHERSTRIP RH	Not Necessary	86.40 FL	*- FL
2	1		*FRT DOOR RH	Dented	1,355.90 FL	*966.20 FL
3	1		*REAR DOOR RH	Dented	1,280.60 FL	*1,030.60 FL
4	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	98.40 FL	*- FL
5	1		*REAR DOOR MECHANISM LOCK RH	Not Necessary	283.00 FL	*- FL
6	2		*REAR DOOR HINGE, TOP/LOWER RH	Not Necessary	179.40 FL	*- FL
7	1		*REAR DOOR CENTER CHECK RH	Not Necessary	62.80 FL	*- FL
8	1		*REAR DOOR GLASS REGULATOR GEAR RH	Not Necessary	420.00 FL	*- FL
9	1		*SIDE ROCKER SKIRT RH	Cut	477.50 FL	*477.50 FL
10	1		*REAR FENDER GUARD RH	Cut	281.00 FL	*195.00 FL
11	1		*REAR SHOCK ABSORBER RH	Damaged	385.00 FL	*385.00 FL
12	1		*REAR WHEEL BEARING RH	Not Necessary	363.50 FL	*- FL
13	1		*REAR AXLE BEAM ASSY	Not Necessary	1,513.50 FL	*- FL
14	1		*REAR DOOR STICKER RH	Necessary	78.20 FL	*78.20 FL
15	1		*REAR FENDER INNER LINER RH	Not Necessary	268.70 FL	*- FL
16	1		*REAR BUMPER SPLASH GUARD RH	Cut	255.31 FL	*255.31 FL
17	1		*REAR SPORTS RIM RH	Cut	720.00 FS	*500.00 FS
18	1		*REAR TYRE RH	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,489.21	3,887.81
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,477.84	677.56
Total Parts (\$\$)	7,011.37	3,210.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TRANSFER GLASS ,GEAR & COMPONENTS	New	-	-
3	TO REMOVE,REPLACE & TRANSFER DOOR COMPONENTS TRANSFER GLASS ,GEAR & COMPONENTS	New	200.00	160.00
4	TO REMOVE,REPLACE REAR UNDERCARRIAGE PARTS	New	320.00	0.00
5	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	600.00
6	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,300.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >