

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020036/BKA3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463927-03

Claimant
Vehicle No : SLZ1385D **Insured Vehicle No :** SCY7808Z

Date of Loss: 23/09/2019 Nature of Claim: TP Claim No: 5712091233SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1385D		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	LEB6549941
Reg. Date:	24/04/2018 (Man. Year: 2018)	Chassis No:	GP71208125
Colour:	Black	Odometer:	133427 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,230.16	4,879.76	2,350.40	32.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,940.00	1,260.00	39.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,430.16	6,819.76	3,610.40	34.62
Approved Total (Overridden) (S\$)		5,450.00		
Nett Amount (S\$)	10,430.16	5,450.00	4,980.16	47.75
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		15.00		
Nett Liability (S\$)		5,945.00		
Global Sum Settlement (S\$)		5,930.00		

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 12/11/2019 Inspected At: 160 SIN MING DRIVE #01-14
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,345.00 FL	*1,345.00 FL
2	1		*TAILGATE LOGO	Necessary	87.00 FL	*38.60 FL
3	1		*TAILGATE EMBLEM SHUTTLE	Necessary	78.00 FL	*58.00 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	198.70 FL	*80.00 FL
5	1		*TAILGATE OUTER CHROME MOULDING	Broken	365.00 FL	*350.00 FL
6	1		*TAILGATE OUTER GARNISH	Not Damaged	471.00 FL	*- FL
7	1		*TAILGATE INNER LOCK ACTUATOR	Jammed	221.00 FL	*180.00 FL
8	1		*TAILGATE INNER HANDLE	Not Damaged	68.40 FL	*- FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	98.60 FL	*98.60 FL
10	1		*TAILGATE WEATHERSTRIP	Torn	259.80 FL	*168.50 FL
11	1		*TAILGATE LOCK STRIKER	Not Damaged	61.00 FL	*- FL
12	1		*REAR BUMPER	Dented	1,068.40 FL	*986.50 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	182.00 FL	*129.00 FL
14	2		*REAR BUMPER BRACKET	Bent	244.00 FL	*97.40 FL
15	1		*REAR BUMPER REFLECTOR	O/S Broken	279.60 FL	*139.80 FL
16	1		*REAR BUMPER REFLECTOR GARNISH	O/S Broken	376.40 FL	*188.20 FL
17	1		*REAR BUMPER TOW CAP	Broken	65.00 FL	*65.00 FL
18	1		*REAR END PANEL	Dented	864.20 FL	*769.10 FL
19	1		*REAR END PANEL TOP GARNISH	Dislodged	258.60 FL	*215.00 FL
20	1		*TAILLAMP RH	Broken	696.00 FL	*528.50 FL
21	1		*SUNDRIES	Not Applicable	80.00 FS	*- FS
22	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
24	2		*TAILGATE REFLECTOR CLIPS	Not Damaged	120.00 FS	*- FS
25	1		*TAILGATE PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
26	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
27	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
28	1		*TAILGATE WINDSCREEN CLIPS	Necessary	60.00 FS	*30.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
30	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
31	1		*TAILLAMP INNER SEAL	Not Applicable	80.00 FS	*- FS
32	2		*TAILLAMP CLIPS	Necessary (1 PCS ONLY)	120.00 FS	*60.00 FS
33	2		*REVERSE SENSOR C/W CONTROL MODULE	Dislodged	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,687.70	5,967.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,457.54	1,087.44
Total Parts (\$\$)	7,230.16	4,879.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R WIRE HARNESS TO FACILITATE REPAIR AND CHECK FUNCTION	New	100.00	50.00
2	R&R TAILGATE COMPONENT	New	150.00	50.00
3	R&R REAR WINDSCREEN	New	300.00	120.00
4	R&R REVERSE SENSOR	New	150.00	60.00
5	PANEL BEAR	New	1,200.00	800.00
6	RUST PROOFING	New	100.00	60.00
7	SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (\$)			3,200.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >