

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19020041/BBA3Q2**Date:** 03/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800050616-01

Claimant
Vehicle No : SJX8901C **Insured Vehicle No :** SKT1272P

Date of Loss: 10/11/2019 Nature of Claim: TP Claim No: 9419225323SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX8901C	Engine No:	3ZZB005969
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106177497
Reg. Date:	21/07/2010 (Man. Year: 2010)	Odometer:	160102 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/16 R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,923.76	3,685.40	3,238.36	46.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,600.00	1,730.00	51.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,253.76	5,285.40	4,968.36	48.45
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	10,253.76	4,200.00	6,053.76	59.04
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,836.45		
Global Sum Settlement (S\$)		4,830.00		

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 12/11/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	986.60 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	88.60 FL	*55.00 FL
3	1		*BOOTLID EMBLEM ALTIS	Necessary	69.10 FL	*49.00 FL
4	1		*BOOTLID EMBLEM COROLLA	Necessary	73.20 FL	*45.00 FL
5	1		*BOOTLID EMBLEM 1.6	Necessary	55.00 FL	*48.00 FL
6	1		*BOOTLID INNER LOCK	Jammed	268.50 FL	*199.20 FL
7	1		*BOOTLID LOCK STRIKER	Not Damaged	89.50 FL	*- FL
8	1		*BOOTLID LOCK SENSOR	Broken	169.70 FL	*169.70 FL
9	1		*BOOTLID WEATHERSTRIP	Torn	285.60 FL	*196.95 FL
10	2		*BOOTLID REFLECTOR	Not Damaged	378.80 FL	*- FL
11	1		*BOOTLID OUTER MOULDING	Cracked	264.30 FL	*243.10 FL
12	2		*REAR NUMBE PLATE LAMP	Not Damaged	124.80 FL	*- FL
13	1		*REAR BUMPER	Dented	986.40 FL	*563.50 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	196.80 FL	*158.00 FL
15	2		*REAR BUMPER BRACKET	Bent	164.60 FL	*136.00 FL
16	1		*REAR END PANEL	Dented	983.50 FL	*639.10 FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	189.20 FL	*189.20 FL
18	2		*TAILLAMP	Broken	1,675.20 FL	*1,440.00 FL
19	2		*TAILLAMP APRON PANEL	Not Damaged	367.80 FL	*- FL
20	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
21	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
22	1		*BOOTLID REFLECTOR CLIPS	Necessary	80.00 FS	*30.00 FS
23	1		*BOOTLID REFLECTOR SEAL	Not Damaged	120.00 FS	*- FS
24	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
26	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*30.00 FS
27	1		*TAILLAMP SEAL	Not Damaged	120.00 FS	*- FS
28	1		*TAILLAMP CLIP	Necessary	60.00 FS	*30.00 FS
29	1		*REVERSE SENSOR C/W MODULE	Dislodged	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,407.20	4,511.75
- List Item Discount on L Items 20.00/20.00% (\$)	1,483.44	826.35
Total Parts (\$)	6,923.76	3,685.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	120.00	50.00
2	R& REVERSE SENSOR	New	100.00	60.00
3	CHECK WIRING	New	60.00	30.00
4	PANEL BEAT	New	1,400.00	600.00
5	SPRAY PAINTING	New	1,400.00	800.00
6	RUST PROOFING	New	200.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	50.00	0.00
			Gross Labour Cost (\$\$)	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >