


YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/17: Chassis Number



2/17: Odometer Reading



3/17: Inspection Photo

YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



4/17: Inspection Photo



5/17: Inspection Photo



6/17: Inspection Photo

YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



7/17: Inspection Photo




8/17: Inspection Photo



9/17: Inspection Photo

YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



10/17: Inspection Photo



11/17: Inspection Photo



12/17: Inspection Photo

YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/17: Inspection Photo



14/17: Inspection Photo



15/17: Inspection Photo

YP6367Y [YN7813E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



16/17: Inspection Photo



17/17: Inspection Photo



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: +65 6553 3912

Reg No. 52821270B

Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



ISUZU MOTORS LTD. JAPAN

V.I.N JAANPR75HH7101677

M.D. NPR5SN AD/BH

ENGINE RDQ/4HK1 RR AXLE 6CP

TRANS. RST FINAL RU1

TIRE CQU B14

B. COLOR/TRIM 729/155

OPTION

C41 NT5 RPY S2T 33W 6KK

7QQ 7YN 8GJ 8JM

Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP



Vehicle No: YP 6367 Y

Report No: RW/0029/19TP

