

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG19020051/GBA3Q2**Date:** 02/03/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SMF3201G **Insured Vehicle No :** SLV7970X

Date of Loss: 31/10/2019 Nature of Claim: TP Claim No: 5143399206SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMF3201G</b>	Engine No:	HIDDEN
Make & Model:	TOYOTA ESQUIRE, 1.8 HYBRID (A)	Chassis No:	ZWR800299891
Reg. Date:	(Man. Year: 1900)	Odometer:	49301 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,200.00	800.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,000.00</b>	<b>1,200.00</b>	<b>800.00</b>	<b>40.00</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 12/11/2019 Inspected At:

Benz Bodywork (HQ)  
53 UBI RD 1 #05-15 PAYA UBI  
INDUSTRIAL PARK  
Singapore 408934

Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHUA ZHEN LI*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR (NPA)	Repair	0.00 F	*- F	
2	1		*REAR RH DOOR (NPA)	Repair	0.00 F	*- F	
3	1		*REAR RH FENDER (NPA)	Repair	0.00 F	*- F	
4	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- F	
5	1		*ROCKER PANEL RH (NPA)	Repair	0.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING CHARGES TO DAMAGED AREAS	New	800.00	200.00
2	SPRAY PAINTING OF ALL AFFECTED PARTS AND AREAS	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >