

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19020059/QEA3Q2
Date: 16/02/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SG5574R	Insured Vehicle No :	SLK8045T
Date of Loss:	28/10/2018	Nature of Claim:	TP
			Claim No: 8979837638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5574R		
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Engine No:	D9195431
Reg. Date:	31/08/2016 (Man. Year: 2016)	Chassis No:	YV3S4P927GA179444
Colour:	Multi-colour	Odometer:	218082 km
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 RR22.5	Rear Tyre Size:	275/70 RR22.5
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,132.00	697.00	435.00	38.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,132.00	697.00	435.00	38.43
+ Loss of Use (1.0 x S\$325.00/day) (S\$)	325.00			
		(S\$)	1,022.00	
Liable Amount (50.00%) (S\$)	511.00			
+ Doc/Search Fee (S\$)	7.00			
Nett Liability (S\$)	518.00			

INSPECTION

Date of Assignment:	08/11/2019	
Date Inspected:	08/11/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	1.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RH PORTION CENTER	New	530.00	265.00
2	TO PUTTY & RESPRAY	New	602.00	432.00
		Gross Labour Cost (S\$)	1,132.00	697.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >