

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19020064/R1EA3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMK8940Y **Insured Vehicle No :** SKZ1773D

Date of Loss: 07/11/2019 **Nature of Claim:** TP **Claim No:** 3575538333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK8940Y	Engine No:	CVK078012
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF49KA047906
Reg. Date:	27/04/2019 (Man. Year: 2019)	Odometer:	6900 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,315.20	15,240.48	11,074.72	42.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,012.00	7,482.00	3,530.00	32.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	37,327.20	22,722.48	14,604.72	39.13
+ GST 7.00/7.00% (S\$)	2,612.90	1,590.57	1,022.33	39.13
Nett Amount (S\$)	39,940.10	24,313.05	15,627.05	39.13
+ Loss of Use (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		25,515.05		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,999.00 F	*1,599.20 F
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	531.00 F	*- F
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	191.00 F	*- F
4	1		*FRONT BUMPER AIR GUIDE - LH	Serviceable	56.00 F	*- F
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Serviceable	123.00 F	*- F
6	1		*FRONT BUMPER CARRIER	Serviceable	733.00 F	*- F
7	1		*FRONT BUMPER FOAM FILTER PIECE	Serviceable	113.00 F	*- F
8	1		*FRONT BUMPER GUIDE SECTION - LH	Necessary	33.00 F	*26.08 F
9	1		*FRONT PARKING AID SENSOR - INNER/OUTER	Serviceable	231.00 F	*- F
10	4		*FRONT PARKING AID SEAL RING	Necessary	12.00 F	*10.24 F
11	1		*HORN - LH HIGH TONE	Serviceable	37.00 F	*- F
12	1		*SPRING SHACKLE - LH	Serviceable	26.00 F	*- F
13	1		*FRONT FENDER - LH	Bent	700.00 F	*559.60 F
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 F	*- F
15	1		*FRONT FENDER CLOSING ELEMENT - LH	Cracked	45.00 F	*36.00 F
16	1		*FRONT FENDER BRACKET - LH	Bent	32.00 F	*25.20 F
17	1		*FRONT FENDER BRACE - LH FRONT	Bent	107.00 F	*85.60 F
18	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	Cracked	45.00 F	*35.60 F
19	1		*FRONT FENDER BRACKET - LH	Serviceable	29.00 F	*- F
20	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	223.00 F	*178.40 F
21	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Serviceable	211.00 F	*- F
22	1		*WHEEL SPOILER - LH	Deformed	66.00 F	*52.32 F
23	1		*WHEEL SPOILER TRIM - LH	Serviceable	32.00 F	*- F
24	1		*STONE SHIP GUARD - LH	Not Necessary	46.00 F	*- F
25	1		*BONNET	Bent	2,554.00 F	*2,043.20 F
26	1		*BONNET ATTACHMENT PARTS	Serviceable	373.00 F	*- F
27	1		*BONNET IMPACT PROTECTION - CENTRE / LH / RH (3 PCS)	Necessary	75.00 F	*59.44 F
28	1		*FENDER LEDGE COVER - LH	Serviceable	28.00 F	*- F
29	1		*FENDER TOP LEDGE COVER - LH	Serviceable	21.00 F	*- F
30	1		*LED HEADLIGHT - LH	Cracked	7,087.00 F	*5,669.60 F
31	1		*LIFT CYLINDER - LH	Serviceable	192.00 F	*- F
32	1		*FRONT ALUMINIUM RIM - LH	Cut	651.00 F	*520.80 F
33	4		*ALUMINIUM RIM RUBBER VALVE	Necessary	13.00 F	*9.92 F
34	1		*FRONT WISHBONE LINK - LH	Bent	491.00 F	*392.40 F
35	1		*FRONT SUSPENSION GUIDE - LH	Bent	861.00 F	*688.40 F
36	2		*UPPER CONTROL ARM - LH FRONT / REAR	Bent	932.00 F	*745.60 F
37	1		*WHEEL BEARING HOUSING - LH	Bent	884.00 F	*707.20 F
38	1		*SWIVEL JOINT	Bent	175.00 F	*140.00 F
39	1		*WHEEL HUB	Bent	451.00 F	*360.40 F
40	1		*DOUBLE ANGLED BALL BEARING	Necessary	232.00 F	*185.20 F
41	1		*SUSPENSION FORKS - LH	Bent	239.00 F	*190.80 F
42	1		*COUPLING ROD	Bent	123.00 F	*98.00 F
43	1		*GAS SHOCK ABSORBER	Serviceable	276.00 F	*- F
44	1		*DRIVE SHAFT	Serviceable	2,422.00 F	*- F
45	1		*TRACK ROD	Bent	90.00 F	*71.68 F
46	1		*TIE ROD END	Bent	180.00 F	*144.00 F
47	1		*SUNDRIES	Necessary	400.00 F	*225.20 F
48	1		*ASSEMBLY CARRIER	Serviceable	1,380.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*AIRCON REFRIGERANT PIPE	Bent	380.40 F	*380.40 F
F=Franchise part.						
Total Parts (\$\$)					26,315.20	15,240.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE LHS FRONT DOOR AND PANEL TRIM. TO REMOVE AND REINSTALL LHS WIND MIRROR ASSY	New	300.00	300.00
3	TO DISLODGE LHS FRONT WHEEL SUSPENSION. TO INSPECT FIR FURTHER DAMAGES AND RENEW ACCORDINGLY	New	1,800.00	1,800.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	1,750.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,700.00	2,200.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO TOW VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY DIAGNOSTIC CHECKS	New	192.00	192.00
9	RENEW AIR COND PIPE. VACUUM AND REGAS	New	480.00	480.00
Gross Labour Cost (\$\$)			11,012.00	7,482.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >