

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19020068/APA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00014023
Claimant
Vehicle No : SLL6636X **Insured Vehicle No :** SGK7775K
 Date of Loss: 31/10/2019 Nature of Claim: TP Claim No: 1201900034887

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL6636X**
 Make & Model: HYUNDAI TUCSON, 2.0 TL (A) Engine No: G4NAHU342566
 Reg. Date: 06/03/2017 (Man. Year: 2017) Chassis No: KMHJ3813MHU413903
 Colour: Brown Odometer: 40473 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,072.20	1,568.80	4,503.40	74.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	830.00	970.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,872.20	2,398.80	5,473.40	69.53
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	7,872.20	1,900.00	5,972.20	75.86
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,407.45		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 11/11/2019
 Date Inspected: 12/11/2019 Inspected At: Ho Beng Trading (HQ)
 Blk 3020A #01-33, Ubi Road 1
 Singapore 408714
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Feb 2020)	
Parts:	N/A	HYUNDAI TUCSON 2.0 TL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6636X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H FENDER	Dented	695.20 F	*695.20 FL
2	1		*FRONT L/H FENDER COWLING	Not Necessary	275.30 F	*- FL
3	8		*FRONT L/H FENDER COWLING CLIPS	Not Necessary	52.00 F	*- FL
4	1		*FRONT FENDER MUD -SHIELD -LH	Not Necessary	112.10 F	*- FL
5	1		*FENDER MUD SHIELD CLIPS	Not Necessary	12.90 F	*- FL
6	1		*FRONT L/H HEADLAMP	Not Necessary	885.00 F	*- FL
7	1		*FRONT TYRE -LH	Not Necessary	350.00 F	*- FL
8	1		*FRONT RIM -LH	Not Necessary	550.00 F	*- FL
9	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	425.10 F	*- FL
10	1		*FRONT L/H LOWER ARM	Not Necessary	380.20 F	*- FL
11	1		*FRONT L/H KNUCKLE ARM	Not Necessary	360.80 F	*- FL
12	1		*FRONT L/H KNUCKLE ARM BEARING	Not Necessary	102.80 F	*- FL
13	1		*FRONT BUMPER	Deformed	882.30 F	*882.30 FL
14	8		*FRONT BUMPER CLIPS	Necessary	60.00 F	*30.00 FL
15	2		*FRONT BUMPER SIDE BRACKET	N/S Necessary	230.00 F	*65.00 FL
16	1		*FRONT BUMPER FOG LAMP -LH	Not Necessary	255.00 F	*- FL
17	1		*FRONT BUMPER FOG LAMP COVER-LH	Not Necessary	155.00 F	*- FL
18	1		*FRONT BUMPER LOWER COVER	Cut	288.50 F	*288.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,072.20	1,961.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	392.20
Total Parts (\$\$)	6,072.20	1,568.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX UNDERCARRIAGE	New	280.00	0.00
2	TO CHECK WHEEL ALIGNMENT COMPUTER	New	120.00	0.00
3	TO CHECK WIRING SYSTEM	New	80.00	30.00
4	TUFF KOTE	New	120.00	0.00
5	TO PANEL BEATING	New	600.00	400.00
6	TO SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$)			1,800.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >