

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19020069/AQF3E2  
**Date:** 21/12/2020

### REFERENCE

Insured/Claimant: YEOW TEE LENG Policy No:  
Date of Loss: 09/11/2019 Nature of Claim: OD Claim No: 5099678625SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ392A**  
Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CVK086195  
Reg. Date: 26/10/2019 (Man. Year: 2019) Chassis No: WAUZZZF41KA104681  
Colour: White Odometer: 482 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$175,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,253.00	8,028.24	3,224.76	28.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,852.00	10,652.00	6,200.00	36.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>28,105.00</b>	<b>18,680.24</b>	<b>9,424.76</b>	<b>33.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,967.35</b>	<b>1,307.62</b>	<b>659.73</b>	<b>33.53</b>
<b>Nett Amount (S\$)</b>	<b>30,072.35</b>	<b>19,987.86</b>	<b>10,084.49</b>	<b>33.53</b>

### INSPECTION

Date of Assignment: 12/11/2019  
Date Inspected: 12/11/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 12.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
2	1		*REAR FENDER - RH	Dented	2,443.00 FS	*1,954.40 FS
3	1		*REAR WINDSCREEN	Necessary	1,049.00 FS	*839.20 FS
4	1		*SIDE WINDOW - RH	Necessary	561.00 FS	*448.40 FS
5	1		*PRIMER	Necessary	19.00 FS	*14.88 FS
6	1		*LED TAIL LIGHT - RH OUTER	Cracked	931.00 FS	*744.80 FS
7	1		*TAIL LIGHT TRIM - RH OUTER	Cut	27.00 FS	*21.52 FS
8	1		*LED TAIL LIGHT - RH INNER	Cut	931.00 FS	*744.80 FS
9	1		*TAIL LIGHT TRIM - RH INNER	Cut	27.00 FS	*21.52 FS
10	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	223.00 FS	*- FS
11	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
12	1		*REAR BUMPER	Deformed	2,491.00 FS	*1,992.80 FS
13	1		*REAR BUMPER FIXING PARTS	Not Necessary	416.00 FS	*- FS
14	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*- FS
15	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
16	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
18	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
20	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
21	1		*SUNDRIES	Necessary	400.00 FS	*6.64 FS
22	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
23	1		*A4 EMBLEM	Necessary	87.00 FS	*69.28 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>11,253.00</b>	<b>8,028.24</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	New	360.00	360.00
2	TO INSTALL REAR WINDSCREEN SOLAR FILM.	New	400.00	400.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	1,400.00
5	TO DISMANTLE REAR BUMPER AND REAR LID. TO RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	5,600.00	3,000.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
7	TO RESPRAY REAR LID.	New	1,050.00	550.00
8	TO RESPRAY LHS REAR FENDER.	New	1,050.00	550.00
9	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
10	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	4,800.00	2,200.00
			<b>Gross Labour Cost (\$\$)</b>	<b>16,852.00</b>
				<b>10,652.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >