

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19020071/KPA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013611

Claimant
Vehicle No : SGC8278P **Insured Vehicle No :** SKW7279R

Date of Loss: 09/11/2019 Nature of Claim: TP Claim No: 1201900036177

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC8278P		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4024224
Reg. Date:	19/11/2015 (Man. Year: 2015)	Chassis No:	RU11104221
Colour:	Metallic Black	Odometer:	105063 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,801.96	2,477.61	2,324.35	48.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,170.00	720.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,691.96	3,647.61	3,044.35	45.49
+ GST 7.00/7.00% (\$\$)	468.44	255.33	213.11	45.49
Nett Amount (\$\$)	7,160.40	3,902.94	3,257.46	45.49
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,264.94		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 12/11/2019 Inspected At:

S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC8278P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	953.30 FL	*953.30 FL
2	1		*TAIL GATE INNER HANDLE COVER	Dented	85.60 FL	*85.60 FL
3	1		*TAIL GATE INNER TRIM BOARD	Buckled	265.30 FL	*265.30 FL
4	1		*TAIL GATE BADGE VEZEL	Necessary	68.20 FL	*68.20 FL
5	1		*TAIL GATE WEATHERSTRIP (50%)	Dented / Distorted	132.24 FS	*82.65 FS
6	1		*TAIL GATE INNER LOCK	Dented	195.20 FL	*195.20 FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	128.00 FL	*128.00 FL
8	1		*LH OUTER TAIL LAMP	Serviceable	652.00 FL	*- FL
9	1		*LH INNER TAIL LAMP	Serviceable	265.40 FL	*- FL
10	1		*REAR END PANEL	Repair	485.60 FL	*- FL
11	1		*REAR END PANEL INNER TRIM GARNISH	Serviceable	115.00 FL	*- FL
12	1		*REAR BUMPER	Bent	780.70 FL	*508.50 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	24.00 FL	*24.00 FL
14	1		*LH REAR BUMPER TOP GARNISH	Buckled	295.00 FL	*245.00 FL
15	1		*REAR BUMPER REINFORCEMENT	No such part	685.50 FL	*- FL
16	1		*LH REAR BUMPER REFLECTOR	Serviceable	161.50 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
18	1		*REAR WINDSCREEN INNER SEAL	Necessary	28.00 FS	*28.00 FS
19	1		*SET REAR PARKING SENSORS	Dented	260.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
21	1		*REAR PANEL BUZZER SENSOR	Cracked	185.60 FL	*185.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,871.14	3,009.35
- List Item Discount on L Items 20.00/20.00% (S\$)	1,069.18	531.74
Total Parts (S\$)	4,801.96	2,477.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST	New	120.00	120.00
2	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL,REAR BODY PANEL,TO STRAIGHTEN OUT REAR CHASSIS MEMBER AND ADJUST REAR BODY AND TAILGATE ALIGNMENT	New	800.00	500.00
3	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	850.00	500.00
4	TO PERFORM COMPUTER DIAGNOSTIC ON DRIVETRAIN,ABS SYSTEMS PARKING SYSTEM AND CLEAR FAULT CODES	New	120.00	50.00
Gross Labour Cost (\$\$)			1,890.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >