

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III19020083/FGA3Q2

**Date:** 16/10/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
<b>Claimant Vehicle No :</b>	SHC6099R	<b>Insured Vehicle No :</b>	GBH4816X
Date of Loss:	10/11/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001434

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6099R		Engine No:	D4FDDH308173
Make & Model:	KIA OPTIMA, 1.7 D (A)		Chassis No:	KNAGM414ME5464902
Reg. Date:	22/08/2014 (Man. Year: 2013)		Odometer:	610337 km
Colour:	Silver			
Engine Capacity:	1685 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,855.90	711.00	3,144.90	81.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,500.00	1,590.00	51.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,945.90</b>	<b>2,211.00</b>	<b>4,734.90</b>	<b>68.17</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,750.00</b>		
<b>(\$\$)</b>	6,945.90	1,750.00	5,195.90	74.81
<b>+ GST 7.00/7.00% (\$\$)</b>	486.21	122.50	363.71	74.81
<b>Nett Amount (\$\$)</b>	<b>7,432.11</b>	<b>1,872.50</b>	<b>5,559.61</b>	<b>74.81</b>
<b>+ Loss of Use (5.0 x S\$40.00/day) (\$\$)</b>		200.00		
<b>+ Car Rental (5.0 x S\$99.32/day) (\$\$)</b>		496.60		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,576.55</b>		

### INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)

23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 4.0 days

---

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2020)
<b>Parts:</b>	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC6099R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	531.00 FL	*- FL
2	1		*FRONT BUMPER EMBLEM	Not Necessary	44.00 FL	*- FL
3	1		*FRONT BUMPER O/S SIDE RETAINER	Not Necessary	16.00 FL	*- FL
4	1		*FRONT O/S FENDER	Repair	384.00 FL	*- FL
5	1		*FRONT O/S FENDER INNER SHIELD	Not fitted	120.00 FL	*- FL
6	1		*FRONT O/S DOOR	Repair	761.00 FL	*- FL
7	2		*FRONT O/S DOOR HINGES	Serviceable	68.00 FL	*- FL
8	1		*REAR O/S DOOR	Repair	791.00 FL	*- FL
9	2		*REAR O/S DOOR HINGES	Serviceable	68.00 FL	*- FL
10	1		*O/S ROCKER PANEL GARNISH	Repair	286.00 FL	*- FL
11	2		*FRONT & REAR O/S WHEEL COVER	Repair	232.00 FL	*- FL
12	1		*REAR O/S FENDER (NPA)	Repair	0.00 FL	*- FL
13	1		*O/S WING MIRROR	Damaged	590.00 FL	*590.00 FL
14	1		*SET FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
15	1		*FRONT O/S FENDER STICKER	Not Necessary	30.00 FS	*- FS
16	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
17	1		*SET O/S ROCKER PANEL GARNISH CLIPS	Not Necessary	38.00 FS	*- FS
18	1		*SET O/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
19	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS
20	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,245.00</b>	<b>770.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	389.10	59.00
<b>Total Parts (\$\$)</b>	<b>3,855.90</b>	<b>711.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WHEEL ALIGNMENT -FRONT & REAR	New	160.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	50.00
3	TO DISMANTLE /REFIT INNER COMPONENTS OF THE FRONT O/S DOOR & REAR O/S DOOR INTO NEW SHELL DOOR	New	300.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR O/S FENDER ,ETC	New	850.00	400.00
5	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR ,FRONT O/S WINDSCREEN PILLAR ,REAR O/S DOOR ,O/S ROCKER PANEL GARNISH ,REAR O/S FENDER	New	1,400.00	1,050.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,090.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >