

ASS. REC. BY:

REF: 7/11 / (C3/TM) 19020091 / K+3/12

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s: Tans Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Vehl: \_\_\_\_\_

Veh No: S14C 5920B Yr Regn: 10.14  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Perodua Longitude c.c. 1995  
 Colour: M. white 1/2 A/C: Insured / Std / NI / NA  
 Sp. Reading: 540251 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VF1ABL15AUC 239590  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_  
215/60R16

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bar. or Market Value: 39,300  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 07 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Saiten  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 8/11/19 D.O.I. 12/11/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S 1/4 body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/11/19 @ 2pm	File pass to Email GMA, police report B estimate and revised to Total.
	1 Day @ 8900. (Red: 53505, 54, 850/0)

RECEIVED 8 DEC 2019

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 1) 19/12 Typist  
 Date/Time, File Return to?

Days Of Repair: 7  
 Resurvey No. of Trip: 1

Report Format: TP  
 Lump Sum / I.B.I: 8900

- Add Fee:
- Site Insp (\$)
  - Interview (\$)
  - Tech Invs (\$)
  - Weekend (\$)

Survey Fee	
Transportation	250
S-RS St	11
Fuel	
Others	
TOTAL	261

## Denise Tay (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 17 December 2019 5:28 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** RE: CAN FINALIZED -- SHC5920B DOA 08.11.19 -- AAD1911-073

Hi Denise

Net Book Value : \$ 39,367.70

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Wednesday, 11 December, 2019 9:21 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: CAN FINALIZED -- SHC5920B DOA 08.11.19 -- AAD1911-073

Dear Wai Yin,

Please provide book value

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 10 December 2019 2:53 PM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Subject:** FW: CAN FINALIZED -- SHC5920B DOA 08.11.19 -- AAD1911-073

Hi Denise

We purpose \$ 8,900 (before GST).

Thank You  
Best Regards,

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHC5920B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001850
Chassis No.:	VF1ABL15AUC279590
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Oct 2014
First Registration Date:	14 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2022
PARF Rebate Amount:	\$8,748.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$18,605.00
<b>Total Rebate Amount:</b>	<b>\$27,353.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/11/2019 11:40
Date Of Accident	08/11/2019 17:35
Exact Location Of Accident	REPUBLIC BOULEVARD TOWARD BEACH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5920B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	YEO TANG CHOON
NRIC No	S1352218I
Date Of Birth	01/04/1959
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1980
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93881977
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 566 HOUGANG STREET 51 #04-472
Postcode	530566
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE THE ATTACH POLICE REPORT T/20191108/7029.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME9655X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ER MENG JOO
NRIC/Passport Number	S1566984E
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name YEO TANG CHOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5920B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20191108/7029

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20191108/7029

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/11/2019 20:38	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: YEO TANG CHOON		Address: APT BLK 566 HOUGANG STREET 51 #04-472 SINGAPORE 530566	
ID Type / ID No.: NRIC NO / S1352218I		Contact No.:	Mobile: 93881977
Nationality: SINGAPORE CITIZEN		Email: yeotangchoon@gmail.com	
Sex: Male	Age: 60	Date of Birth: 01/04/1959	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/11/2019 17:35	Type of Location: T-Junction
Location: REPUBLIC AVENUE TOWARDS BEACH ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5920B	Car	RENAULT	LATITUDE	Red	Seriously Damaged	1
SME9655X	Car	HONDA	ODYSSEY	Maroon	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191108/7029

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20191108/7029

**CONTINUATION OF REPORT**

Driver			
Name	YEO TANG CHOON	ID No.	S1352218I
Related Vehicle	SHC5920B (Car)	Contact No.	93881977
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	ER MENG JOO	ID No.	S1566984E
Related Vehicle	SME9655X (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I, VEHICLE A, BEARING CAR PLATE (SHC5920B) WAS DRIVING STRAIGHT TOWARDS THE TRAFFIC LIGHT IN GREEN FROM REPUBLIC AVE TOWARDS BEACH ROAD, SUDDENLY VEHICLE B, BEARING CAR PLATE (SME9655X) DASH OUT AND COLLIDED ONTO THE RIGHT PORTION OF MY VEHICLE. AS SOON AS I FELT THE IMPACT I BRAKE MY VEHICLE.

DUE TO THE HUGE IMPACT, MY VEHICLE SHIFTED TO THE LEFT SIDE AND COULD NOT MOVE ANYMORE.

AFTER THE INCIDENT HAPPENED, I COULD NOT GET DOWN FROM MY DRIVER SEAT AS VEHICLE B, WAS BLOCKING THE WAY. HENCE, HE SLIGHTLY REVERSED HIS VEHICLE AND ALLOWED ME TO GET DOWN TO EXCHANGE PARTICULARS.

WHILE CHANGING PARTICULARS, HE MENTIONED THAT HE TURNED RIGHT BECAUSE HE SAW THE GREEN LIGHT HOWEVER WITHOUT GREEN ARROW SO HE THOUGHT IT IS OKAY TO PROCEED TO TURN RIGHT.

AFTER THE ACCIDENT, I SUFFERED PAIN ON MY NECK AND BACK SO I PROCEEDED TO MOUNT ALVERNIA HOSPITAL AND CONSULTED A DOCTOR.  
I RECEIVED 5 DAYS OF MC.



**SINGAPORE  
POLICE FORCE**



T/20191108/7029

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20191108/7029

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MOHAMAD ZULFAZDLI BIN ABDULLAH  
Contact No.: 65476204

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:  
08/11/2019 20:38

Classification Of Case:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5920B**

AAD1911-073

*Not Authorized*  
*L. Sing B*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make: **1 2 NOV 2019**  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration:

**SHC 5920B**  
 VF1ABL15AUC279590  
 RENAULT  
 LATITUDE  
 8.11.19  
**TOKIO MARINE**  
 14/10/2014

	<b>PART</b>		<b>LIST</b>	
1	BUMPER COVER FRT	\$	CM 747.20	✓
1	BUMPER SPOILER FRT	\$	SL 344.70	X
1	BUMPER ABSORBER FRT	\$	SL 394.68	X
1	BUMPER RETAINER FRT RH	\$	CM 101.40	✓
1	BUMPER SUPPORT FRT	\$	SL 10.70	X
1	BUMPER UNDERTRAY FRT	\$	SL 292.50	X
1	BUMPER GRILLE LOWER FRT	\$	SL 147.00	X
1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21	<
1	BUMPER BEAM FRT	\$	N 663.70	X
1	HEADLAMP RH	\$	CM 743.60	✓
1	HEADLAMP PANEL FRT RH	\$	N 128.30	X
1	FENDER PANEL FRT RH	\$	B 437.10	✓
1	WHEELARCH FRT RH	\$	CM 191.40	✓
1	FENDER BRACKET LOWER RH	\$	N 11.80	X
1	FENDER BRACKET FRT RH	\$	N 106.40	} X
1	FENDER INSULATOR RH	\$	SL 66.30	
1	CHASSIS PANEL FRT RH L70Y	\$	N 592.90	
1	CHASSIS PANEL SUPPORT FRT RH L70Y	\$	N 431.70	
1	FENDER PANEL INNER FRT RH L70Y	\$	N 838.40	
1	FENDER PANEL SUPPORT FRT RH L70Y	\$	N 432.00	
1	WHEEL HOUSING PANEL FRT RH L70Y	\$	N 2,698.60	
1	TOW COVER FRT	\$	SL 60.90	
1	FRONT BRACE PANEL	\$	N 177.22	
1	RADIATOR GRILLE	\$	SL 969.90	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL 225.36	
1	RADIATOR GRILLE FRAME	\$	SL 686.00	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5920B**

**AAD1911-073**

1	FRAME FULL SUPPORT PANEL	\$	R	592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	R	41.60	X
1	BONNET	\$	B	1,312.70	✓
1	BONNET INSULATOR	\$	S	294.30	} X
1	BONNET STRUT RH	\$	S	53.30	
1	BONNET HINGE RH	\$	R	237.40	
1	BONNET LOCK	\$	R	152.80	
2	BONNET BUFFER	\$	S	26.80	
1	BONNET CABLE	\$	S	55.20	
1	BONNET CABLE COVER	\$	S	80.60	
1	BONNET SEAL OUTER	\$	S	83.20	} X
1	BONNET SEAL INNER	\$	S	70.10	
1	LOWER ARM RH L70Y	\$	B	192.70	✓
1	KNUCKLE ARM RH L70Y	\$	B	481.50	✓
1	KNUCKLE HUB+BEARING LH/RH L70Y	\$	B	272.30	✓
1	ABSORBER FRT RH L70Y	\$	R	203.50	✓
1	ABSORBER MOUNTING KIT RH L70Y	\$	R	273.60	✓
1	ABSORBER DUST COVER	\$	S	76.30	X
1	BRAKE DISC FRT L70Y	\$	S	158.80	X
1	BRAKE CALIPER FRT RH L70Y	\$	S	536.10	X
1	ABS SENSOR FRT RH L70Y	\$	S	152.50	X
1	BRAKE HOSE FRT RH L70Y	\$	S	80.70	X
1	BRAKE PAD FRT L70Y	\$	S	146.20	X
1	DRIVESHAFT RH	\$	R	1,355.70	X
1	STABILIZER BAR FRT	\$	S	427.90	X
1	STABILIZER LINK FRT L70Y	\$	S	69.50	X
1	ENGINE UNDERTRAY	\$	S	583.10	X
1	WIPER RESERVOIR MOTOR	\$	S	82.60	X
1	WIPER RESERVOIR	\$	W	179.60	✓
1	WIPER RESERVOIR NECK	\$	S	29.30	X
1	DOOR PANEL FRT RH	\$	B	2,844.66	✓
1	DOOR HINGE UPPER	\$	R	261.28	X
1	DOOR HINGE LOWER	\$	B	300.55	✓
1	DOOR CHECK FRT RH	\$	S	194.77	X
1	DOOR LOCK FRT RH	\$	R	908.75	X

**Trans-cab Auto Services Pte Ltd**

**AAD1911-073**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5920B**

1	DOOR CATCH FRT RH	\$	R	131.23	}
1	DOOR HANDLE OUTER FRT RH	\$	S	477.76	
1	DOOR HANDLE CAP FRT RH	\$	S	35.52	
1	DOOR HANDLE SEAL FRT RH	\$	S	7.89	
1	DOOR HANDLE COVER FRT RH	\$	S	13.22	
1	DOOR HANDLE MODULE FRT RH	\$	S	133.60	
1	DOOR REGULATOR FRT RH	\$	S	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	S	796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	S	120.97	
1	DOOR FINISHER FRT RH	\$	S	515.06	
1	DOOR MOULDING FRT RH	\$	S	176.82	
1	DOOR WEATHERSTRIP FRT RH	\$	S	410.27	
1	DOOR SEAL LOWER FRT RH	\$	S	91.17	
1	DOOR SEAL FRT RH	\$	S	72.82	
1	DOOR GLASS RUNNER SEAL FRT RH L70Y	\$	S	626.36	
1	DOOR WAIST SEAL OUTER FRT RH L70Y (DOOR CHROME)	\$	S	291.27	
1	DOOR MIRROR RH ASSY	\$	S	727.90	
1	DOOR HARNESS WIRE RH	\$	S	2,670.00	
1	DOOR PANEL REAR RH	\$	R	758.70	}
1	DOOR GUIDE REAR RH	\$	S	136.40	
1	DOOR HINGE UPPER	\$	R	241.60	
1	DOOR HINGE LOWER	\$	R	169.90	
1	DOOR CHECK REAR RH	\$	S	114.90	
1	DOOR REGULATOR REAR RH L70Y	\$	R	758.10	
1	DOOR REGULATOR MOTOR REAR RH L70Y	\$	R	450.60	
1	DOOR FINISHER REAR RH	\$	S	206.40	
1	DOOR MOULDING REAR RH	\$	S	100.50	
1	DOOR BLIND REAR RH	\$	S	506.90	
1	DOOR WHEATHESTRIIP REAR RH L70Y	\$	S	311.60	}
1	DOOR SEAL REAR RH L70Y	\$	S	119.80	
1	DOOR GLASS RUNNER SEAL REAR RH L70Y	\$	S	116.10	
1	DOOR WAIST SEAL OUTER REAR RH L70Y	\$	S	99.40	
1	ROCKER PANEL INNER GARNISH RH	\$	S	466.51	
1	ROCKER PANEL INNER RH	\$	R	1,024.79	
1	ROCKER PANEL OUTER RH	\$	R	1,184.99	

**Trans-cab Auto Services Pte Ltd**

**AAD1911-073**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5920B**

1	ROCKER PANEL CENTER RH	\$	R	990.25	X
1	SUBFRAME OUTER FRT L70Y	\$	Rn	1,094.20	X
1	SUBFRAME INNER FRT L70Y	\$	Rn	746.00	X
1	SUBFRAME SUPPORT INNER L70Y	\$	Rn	69.50	X
1	SUBFRAME BRACKET OUTER LH L70Y	\$	R	49.00	X
1	SUBFRAME BRACKET OUTER RH L70Y	\$	R	49.00	X
1	SUBFRAME BRACKET INNER LH L70Y	\$	R	101.00	X
1	SUBFRAME BRACKET INNER RH L70Y	\$	R	101.00	X
<b>TOTAL</b>		<b>\$</b>		<b>42,290.23</b>	
<b>10%</b>		<b>\$</b>		<b>4,229.02</b>	
		<b>\$</b>		<b>38,061.21</b>	

**Special Nett**

1	BUMPER CLIP FRT	\$	Rn	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	Rn	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	Rn	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	Rn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Rn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	Rn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	Rn	30.00	X
1	WHEELARCH CLIP FRT RH	\$	Rn	30.50	✓
1	FRONT RIGHT TYRE	\$	Rn	300.00	X
1	FRONT RIGHT TYRE RIM	\$	Rn	380.00	X
1	FRONT RIGHT TYRE RIM COVER	\$	Rn	50.00	✓
1SET	Front licence plate with holder	\$	Rn	80.00	} X
1SET	RADIATOR GRILLE SCREW	\$	Rn	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	Rn	52.00	
6	BONNET INSULATOR CLIP L70Y	\$	Rn	3.80	
2	BONNET CABLE COVER SCREW L70Y	\$	Rn	5.00	
2	BONNET CABLE CLIP L70Y	\$	Rn	4.20	
1	WINDSCREEN SEALANT	\$	Rn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	Rn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	Rn	100.00	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	Rn	80.00	60Rn
1	FRONT DOOR STICKER 'Classic'	\$	Rn	80.00	60Rn
1	REAR DOOR STICKER '6555-3333'	\$	Rn	100.00	60Rn

**Trans-cab Auto Services Pte Ltd**

AAD1911-073

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5920B

1	LOWER ARM BOLT L70Y	\$	S <sub>h</sub>	34.90	}
1	LOWER ARM NUT L70Y	\$	S <sub>h</sub>	25.70	
2	ABSORBER BOLT L70Y	\$	S <sub>h</sub>	31.30	
2	ABSORBER NUT L70Y	\$	S <sub>h</sub>	18.00	
1	DOOR CHECK BOLT	\$	S <sub>h</sub>	22.69	
1	DOOR GUIDE SCREW	\$	S <sub>h</sub>	10.85	
1	DOOR HINGE BOLT	\$	S <sub>h</sub>	10.85	
1	DOOR HINGE NUT RH	\$	S <sub>h</sub>	14.60	
1	DOOR CHECK BOLT	\$	S <sub>h</sub>	22.69	
1	DOOR CHECK NUT	\$	S <sub>h</sub>	3.75	
1	DOOR LOCK SCREW L70Y	\$	S <sub>h</sub>	6.12	
1	DOOR CATCH SCREW L70Y	\$	S <sub>h</sub>	10.06	
<b>TOTAL</b>		<b>\$</b>		<b>2,144.33</b>	
<b>TOTAL PARTS</b>		<b>\$</b>		<b>40,205.54</b>	

**LABOUR**

Putty and spray painting of the affected portion.	\$	9,000.00	132cl
To Check Electrical Lighting Concerned.	\$	170.00	2cl
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,000.00	80cl
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	6cl

**Trans-cab Auto Services Pte Ltd**

**AAD1911-073**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5920B**

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	200d
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00	60d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To rust-proofing of the affected areas.	\$	170.00	90d
To transfer of tire, rim and on wheel balancing.	\$	170.00	20d
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	60d
Towing Fees	\$	170.00	50d
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	~ 380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	~ 380.00	X

**TOTAL \$ 22,200.00**

**Over All Total \$ 62,405.54**

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before the spray painting
- To display damaged used (in writing)
- Part price are subject to consultation
- Third party liability (aka "Third Party" loss)
- No insurance claim allowed
- Over the limit of the work agreement and
- It is the responsibility of the repairer to comply

Approved by: \_\_\_\_\_  
 Date: \_\_\_\_\_

**LUMP SUM (REPAIR DAY)**

**30 DAYS**  
**7 days**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM119020091/KTF3N2  
Date: 27/12/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT108660
Claimant Vehicle No :	SHC5920B	Insured Vehicle No :	SME9655X
Date of Loss:	08/11/2019	Nature of Claim:	TP
		Claim No:	M1908782

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC5920B	Engine No:	M9R8839C001850
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC279590
Reg. Date:	14/10/2014 (Man. Year: 2014)	Odometer:	540251 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,205.53	8,462.96	31,742.57	78.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,200.00	2,680.00	19,520.00	87.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>62,405.53</b>	<b>11,142.96</b>	<b>51,262.57</b>	<b>82.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,900.00</b>		
<b>(S\$)</b>	62,405.53	8,900.00	53,505.53	85.74
<b>+ GST 7.00/7.00% (S\$)</b>	4,368.39	623.00	3,745.39	85.74
<b>Nett Amount (S\$)</b>	<b>66,773.92</b>	<b>9,523.00</b>	<b>57,250.92</b>	<b>85.74</b>

## INSPECTION

Date of Assignment:	13/11/2019	
Date Inspected:	12/11/2019	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2019)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5920B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER FRT	Cracked	747.20 FL	-	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	-	*-FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.69 FL	-	*-FL
4	1		*BUMPER RETAINER FRT RH	Cracked	101.40 FL	-	*101.40 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	-	*-FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	-	*-FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	-	*-FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	-	*-FL
9	1		*BUMPER BEAM FRT	Repair	663.70 FL	-	*-FL
10	1		*HEADLAMP RH	Cracked	743.60 FL	-	*743.60 FL
11	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	-	*-FL
12	1		*FENDER PANEL FRT RH	Bent	437.10 FL	-	*437.10 FL
13	1		*WHEELARCH FRT RH	Cracked	191.40 FL	-	*191.40 FL
14	1		*FENDER BRACKET LOWER RH	Repair	11.80 FL	-	*-FL
15	1		*FENDER BRACKET FRT RH	Repair	106.40 FL	-	*-FL
16	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	-	*-FL
17	1		*CHASSIS PANEL FRT RH L70Y	Repair	592.90 FL	-	*-FL
18	1		*CHASSIS PANEL SUPPORT FRT RH L70Y	Repair	431.70 FL	-	*-FL
19	1		*FENDER PANEL INNER FRT RH L70Y	Repair	838.40 FL	-	*-FL
20	1		*FENDER PANEL SUPPORT FRT RH L70Y	Repair	432.00 FL	-	*-FL
21	1		*WHEEL HOUSING PANEL FRT RH L70Y	Repair	2,698.60 FL	-	*-FL
22	1		*TOW COVER FRT	Serviceable	60.90 FL	-	*-FL
23	1		*FRONT BRACE PANEL	Repair	177.22 FL	-	*-FL
24	1		*RADIATOR GRILLE	Serviceable	969.90 FL	-	*-FL
25	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	-	*-FL
26	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	-	*-FL
27	1		*FRAME FULL SUPPORT PANEL	Repair	592.70 FL	-	*-FL
28	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	-	*-FL
29	1		*BONNET	Bent	1,312.70 FL	-	*1,312.70 FL
30	1		*BONNET INSULATOR	Serviceable	294.30 FL	-	*-FL
31	1		*BONNET STRUT RH	Serviceable	53.30 FL	-	*-FL
32	1		*BONNET HINGE RH	Repair	237.40 FL	-	*-FL
33	1		*BONNET LOCK	Repair	152.80 FL	-	*-FL
34	2		*BONNET BUFFER	Serviceable	26.80 FL	-	*-FL
35	1		*BONNET CABLE	Serviceable	55.20 FL	-	*-FL
36	1		*BONNET CABLE COVER	Serviceable	80.60 FL	-	*-FL
37	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	-	*-FL
38	1		*BONNET SEAL INNER	Serviceable	70.10 FL	-	*-FL
39	1		*LOWER ARM RH L70Y	Bent	192.70 FL	-	*192.70 FL
40	1		*KNUCKLE ARM RH L70Y	Bent	481.50 FL	-	*481.50 FL
41	1		*KNUCKLE HUB+BEARING LH/RH L70Y	Bent	272.30 FL	-	*272.30 FL
42	1		*ABSORBER FRT RH L70Y	Bent	203.50 FL	-	*203.50 FL
43	1		*ABSORBER MOUNTING KIT RH L70Y	Bent	273.60 FL	-	*273.60 FL
44	1		*ABSORBER DUST COVER	Serviceable	76.30 FL	-	*-FL
45	1		*BRAKE DISC FRT L70Y	Serviceable	158.80 FL	-	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
46	1		*BRAKE CALIPER FRT RH L70Y	Serviceable	536.10 FL	-	*- FL
47	1		*ABS SENSOR FRT RH L70Y	Serviceable	152.50 FL	-	*- FL
48	1		*BRAKE HOSE FRT RH L70Y	Serviceable	80.70 FL	-	*- FL
49	1		*BRAKE PAD FRT L70Y	Serviceable	146.20 FL	-	*- FL
50	1		*DRIVESHAFT RH	Repair	1,355.70 FL	-	*- FL
51	1		*STABILIZER BAR FRT	Serviceable	427.90 FL	-	*- FL
52	1		*STABILIZER LINK FRT L70Y	Serviceable	69.50 FL	-	*- FL
53	1		*ENGINE UNDERTRAY	Serviceable	583.10 FL	-	*- FL
54	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	-	*- FL
55	1		*WIPER RESERVOIR	Dented	179.60 FL	-	*179.60 FL
56	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	-	*- FL
57	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	-	*2,844.66 FL
58	1		*DOOR HINGE UPPER	Repair	261.28 FL	-	*- FL
59	1		*DOOR HINGE LOWER	Bent	300.55 FL	-	*300.55 FL
60	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	-	*- FL
61	1		*DOOR LOCK FRT RH	Repair	908.75 FL	-	*- FL
62	1		*DOOR CATCH FRT RH	Repair	131.23 FL	-	*- FL
63	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	-	*- FL
64	1		*DOOR HANDLE CAP FRT RH	Serviceable	35.52 FL	-	*- FL
65	1		*DOOR HANDLE SEAL FRT RH	Serviceable	7.89 FL	-	*- FL
66	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	-	*- FL
67	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	-	*- FL
68	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	-	*- FL
69	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	-	*- FL
70	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	-	*- FL
71	1		*DOOR FINISHER FRT RH	Serviceable	515.06 FL	-	*- FL
72	1		*DOOR MOULDING FRT RH	Serviceable	176.82 FL	-	*- FL
73	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	-	*- FL
74	1		*DOOR SEAL LOWER FRT RH	Serviceable	91.17 FL	-	*- FL
75	1		*DOOR SEAL FRT RH	Serviceable	72.82 FL	-	*- FL
76	1		*DOOR GLASS RUNNER SEAL FRT RH L70Y	Serviceable	626.36 FL	-	*- FL
77	1		*DOOR WAIST SEAL OUTER FRT RH L70Y (DOOR CHROME)	Serviceable	291.27 FL	-	*- FL
78	1		*DOOR MIRROR RH ASSY	Serviceable	727.90 FL	-	*- FL
79	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	-	*- FL
80	1		*DOOR PANEL REAR RH	Bent	758.70 FL	-	*758.70 FL
81	1		*DOOR GUIDE REAR RH	Serviceable	136.40 FL	-	*- FL
82	1		*DOOR HINGE UPPER	Repair	241.60 FL	-	*- FL
83	1		*DOOR HINGE LOWER	Repair	169.90 FL	-	*- FL
84	1		*DOOR CHECK REAR RH	Serviceable	114.90 FL	-	*- FL
85	1		*DOOR REGULATOR REAR RH L70Y	Repair	758.10 FL	-	*- FL
86	1		*DOOR REGULATOR MOTOR REAR RH L70Y	Repair	450.60 FL	-	*- FL
87	1		*DOOR FINISHER REAR RH	Serviceable	206.40 FL	-	*- FL
88	1		*DOOR MOULDING REAR RH	Serviceable	100.50 FL	-	*- FL
89	1		*DOOR BLIND REAR RH	Serviceable	506.90 FL	-	*- FL
90	1		*DOOR WEATHERSTRIP REAR RH L70Y	Serviceable	311.60 FL	-	*- FL
91	1		*DOOR SEAL REAR RH L70Y	Serviceable	119.80 FL	-	*- FL
92	1		*DOOR GLASS RUNNER SEAL REAR RH L70Y	Serviceable	116.10 FL	-	*- FL
93	1		*DOOR WAIST SEAL OUTER REAR RH L70Y	Serviceable	99.40 FL	-	*- FL
94	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	-	*- FL
95	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	-	*- FL
96	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	-	*- FL
97	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	-	*- FL
98	1		*SUBFRAME OUTER FRT L70Y	Serviceable	1,094.20 FL	-	*- FL
99	1		*SUBFRAME INNER FRT L70Y	Serviceable	746.00 FL	-	*- FL
100	1		*SUBFRAME SUPPORT INNER L70Y	Serviceable	69.50 FL	-	*- FL
101	1		*SUBFRAME BRACKET OUTER LH L70Y	Repair	49.00 FL	-	*- FL
102	1		*SUBFRAME BRACKET OUTER RH L70Y	Repair	49.00 FL	-	*- FL
103	1		*SUBFRAME BRACKET INNER LH L70Y	Repair	101.00 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
104	1		*SUBFRAME BRACKET INNER RH L70Y	Repair	101.00 FL	-	*- FL
105	1		*BUMPER CLIP FRT	Necessary	66.00 FS	-	*66.00 FS
106	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	-	*- FS
107	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	-	*- FS
108	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	-	*- FS
109	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	-	*- FS
110	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	-	*- FS
111	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	-	*- FS
112	1		*WHEELARCH CLIP FRT RH	Necessary	30.50 FS	-	*30.50 FS
113	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	-	*- FS
114	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	-	*- FS
115	1		*FRONT RIGHT TYRE RIM COVER	Dented	50.00 FS	-	*50.00 FS
116	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	-	*- FS
117	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	-	*- FS
118	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	-	*- FS
119	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	3.80 FS	-	*- FS
120	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	5.00 FS	-	*- FS
121	2		*BONNET CABLE CLIP L70Y	Not Necessary	4.20 FS	-	*- FS
122	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	-	*- FS
123	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	-	*- FS
124	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
125	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	-	*60.00 FS
126	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	-	*60.00 FS
127	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	-	*60.00 FS
128	1		*LOWER ARM BOLT L70Y	Serviceable	34.90 FS	-	*- FS
129	1		*LOWER ARM NUT L70Y	Serviceable	25.70 FS	-	*- FS
130	2		*ABSORBER BOLT L70Y	Serviceable	31.30 FS	-	*- FS
131	2		*ABSORBER NUT L70Y	Serviceable	18.00 FS	-	*- FS
132	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	-	*- FS
133	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	-	*- FS
134	1		*DOOR HINGE BOLT	Serviceable	10.85 FS	-	*- FS
135	1		*DOOR HINGE NUT RH	Serviceable	14.60 FS	-	*- FS
136	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	-	*- FS
137	1		*DOOR CHECK NUT	Serviceable	3.75 FS	-	*- FS
138	1		*DOOR LOCK SCREW L70Y	Serviceable	6.12 FS	-	*- FS
139	1		*DOOR CATCH SCREW L70Y	Serviceable	10.06 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **44,434.55**      **9,367.01**  
 - List Item Discount on L Items 10.00/10.00% (\$\$)    4,229.02      904.05

**Total Parts (\$\$) 40,205.53      8,462.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	1,320.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	9,000.00	800.00
4	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	200.00
9	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
13	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
14	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
15	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
16	TOWING FEES	New	170.00	50.00
17	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
18	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
19	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>22,200.00</b>	<b>2,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >