

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2019 11:38		13 Nov 2019 11:19 Edit Adj Rpt	S\$18,130.24 Edit Estimates	S\$18,130.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: LIM LAY CHENG JESSLYN (LIN LIQING) , ID: S7716013B, Tel: +6597486511									
Vehicle Reg. No.: SGJ4009P		Date of Loss: 07/11/2019 18:00 - :59 [12 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9772314680SG		Policy/Cover Note No.: 1800127905-01 (Comprehensive)							
		Excess: S\$550.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 22/11/2019]									
Driver/Custodian: HO SWEE WEE KELVIN (HE CHUIWEI) (44 / Male), NRIC: S7512667J, Tel: +6597486511 Email: GIGANTOR@SINGNET.COM.SG									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (09/12/2019): Alert - Adj Mandate Approved (S\$23109.00) - SGJ4009P - Claim Handler: Nadaraja, ... - AIG_SG (14/11/2019): Alert - Adj Mandate Approved (S\$9703.00) - SGJ4009P - Claim Handler: Nadaraja, D... - AIG_SG (13/11/2019): SGJ4009P / OD / 07/11/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGJ4009P (9772314680SG)
 OD
 Nov 7 2019 6:30PM
 [LIM LAY CHENG JESSLYN (LIN LIQING)]
 Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 16:00	Video - Accident [Linked Accident Report Documents]	Load MP4	☐

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/19 15:25	Adjuster Immediate Advice	Load HTM	☐
2	09/12/19 12:03	Adjuster Immediate Advice	Load HTM	☐

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/19 17:55	General View	Load JPG	☒
2	13/11/19 17:55	General View	Load JPG	☒
3	13/11/19 17:55	General View	Load JPG	☒
4	13/11/19 17:55	General View	Load JPG	☒
5	13/11/19 17:55	General View	Load JPG	☒
6	13/11/19 17:55	General View	Load JPG	☒
7	13/11/19 17:55	General View	Load JPG	☒
8	13/11/19 17:55	General View	Load JPG	☒
9	13/11/19 17:55	General View	Load JPG	☒
10	13/11/19 17:55	General View	Load JPG	☒
11	13/11/19 17:55	General View	Load JPG	☒
12	13/11/19 17:55	General View	Load JPG	☒
13	13/11/19 17:55	General View	Load JPG	☒
14	13/11/19 17:55	General View	Load JPG	☒
15	13/11/19 17:55	General View	Load JPG	☒
16	13/11/19 17:55	General View	Load JPG	☒
17	13/11/19 17:55	General View	Load JPG	☒
18	13/11/19 17:55	General View	Load JPG	☒
19	13/11/19 17:55	General View	Load JPG	☒
20	13/11/19 17:55	General View	Load JPG	☒
21	13/11/19 17:55	General View	Load JPG	☒
22	13/11/19 17:55	General View	Load JPG	☒
23	13/11/19 17:55	General View	Load JPG	☒
24	13/11/19 17:55	General View	Load JPG	☒
25	13/11/19 17:55	General View	Load JPG	☒
26	13/11/19 17:55	General View	Load JPG	☒
27	13/11/19 17:55	General View	Load JPG	☒
28	13/11/19 17:55	General View	Load JPG	☒
29	13/11/19 17:55	General View	Load JPG	☒
30	13/11/19 17:55	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
31	13/11/19 17:55	General View	 Load JPG	☒
32	13/11/19 17:55	General View	 Load JPG	☒
33	13/11/19 17:55	General View	 Load JPG	☒
34	13/11/19 17:55	General View	 Load JPG	☒
35	13/11/19 17:55	General View	 Load JPG	☒
36	13/11/19 17:55	General View	 Load JPG	☒
37	13/11/19 17:55	General View	 Load JPG	☒
38	13/11/19 17:55	General View	 Load JPG	☒
39	13/11/19 17:55	General View	 Load JPG	☒
40	13/11/19 17:55	General View	 Load JPG	☒
41	13/11/19 17:55	General View	 Load JPG	☒
42	13/11/19 17:55	General View	 Load JPG	☒
43	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
44	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
45	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
46	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
47	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
48	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
49	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
50	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
51	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
52	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
53	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
54	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
55	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
56	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
57	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
58	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
59	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
60	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
61	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
62	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
63	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
64	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
65	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
66	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
67	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
68	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
69	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
70	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
71	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
72	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
73	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
74	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
75	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
76	09/12/19 11:24	Reinspection Photo	 Load JPG	☒
77	09/12/19 11:24	Reinspection Photo	Load JPG	☒
78	09/12/19 11:24	Reinspection Photo	Load JPG	☒
79	09/12/19 11:24	Reinspection Photo	Load JPG	☒
80	09/12/19 11:24	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
81	09/12/19 11:24	Reinspection Photo	Load JPG	☒
82	09/12/19 11:24	Reinspection Photo	Load JPG	☒
83	09/12/19 11:24	Reinspection Photo	Load JPG	☒
84	09/12/19 11:24	Reinspection Photo	Load JPG	☒
85	09/12/19 11:24	Reinspection Photo	Load JPG	☒
86	09/12/19 11:24	Reinspection Photo	Load JPG	☒
87	09/12/19 11:24	Reinspection Photo	Load JPG	☒
88	09/12/19 11:24	Reinspection Photo	Load JPG	☒
89	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
90	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
91	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
92	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
93	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
94	12/02/20 20:02	Photographs of Damaged Parts	Load JPG	☒
95	12/02/20 20:03	Photographs of Damaged Parts	Load JPG	☒
96	12/02/20 20:03	Photographs of Damaged Parts	Load JPG	☒
97	12/02/20 20:03	Photographs of Damaged Parts	Load JPG	☒
98	12/02/20 20:03	Reinspection Photo	Load JPG	☒
99	12/02/20 20:03	Reinspection Photo	Load JPG	☒
100	12/02/20 20:03	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/19 11:51	Singapore Accident Statement	Load PDF	
2	13/11/19 11:51	Certificate of Insurance	Load PDF	
3	13/11/19 11:52	Driver's Driving License	Load PDF	
4	13/11/19 11:52	MARK ESTIMATE	Load PDF	
5	09/12/19 11:56	MARK ESTIMATE (CHECK ITEMS)	Load PDF	
6	09/12/19 11:57	SUPPLEMENTARY	Load PDF	
7	30/03/20 10:32	Workshop Invoice	Load PDF	
8	30/03/20 10:33	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 16:00	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 19:15	Accident Statement	Load HTM	
2	06/12/19 19:17	Accident Statement	Load HTM	
3	06/12/19 19:17	Accident Statement	Load HTM	
4	06/12/19 19:19	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 15:54	Accident Photo	Load JPG	☒
2	08/11/19 15:54	Accident Photo	Load JPG	☒
3	08/11/19 15:54	Accident Photo	Load JPG	☒
4	08/11/19 15:54	Accident Photo	Load JPG	☒
5	08/11/19 15:54	Accident Photo	Load JPG	☒
6	08/11/19 15:54	Accident Photo	Load JPG	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
7	08/11/19 15:54	Accident Photo	 Load JPG	☒
8	08/11/19 15:54	Accident Photo	 Load JPG	☒
9	08/11/19 15:54	Accident Photo	 Load JPG	☒
10	08/11/19 15:54	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 15:58	Sketch Plan	 Load JPG	☒
2	08/11/19 15:58	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19020095/EVF3E2

Date: 30/03/2020

REFERENCE

Insured/Claimant: LIM LAY CHENG JESSLYN (LIN LIQING) Policy No: 1800127905-01
Date of Loss: 07/11/2019 Nature of Claim: OD Claim No: 9772314680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ4009P**
Make & Model: AUDI A4, 2.0 (A) Engine No: CVK068777
Reg. Date: 26/10/2018 (Man. Year: 2018) Chassis No: WAUZZZF40JA231825
Colour: Grey Odometer: 18594 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$135,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,253.44	12,348.24	14,905.20	54.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,132.00	5,782.00	4,350.00	42.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,385.44	18,130.24	19,255.20	51.50
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	36,835.44	17,580.24	19,255.20	52.27
+ GST 7.00/7.00% (S\$)	2,578.48	1,230.62	1,347.86	52.27
Nett Amount (S\$)	39,413.92	18,810.86	20,603.06	52.27

INSPECTION

Date of Assignment: 13/11/2019
Date Inspected: 13/11/2019 Inspected At: 281 Alexandra Road
Repaier : Premium Automobiles Pte Ltd
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Dented	1,999.00 FS	*1,599.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIP	Not Necessary	64.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - CENTRE	Broken	178.00 FS	*142.40 FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*- FS
6	2	*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	112.00 FS	*- FS
7	1	*RADIATOR GRILLE	Broken	1,227.00 FS	*981.60 FS
8	2	*AIR GUIDE GRILLE - LH / RH	Not Necessary	246.00 FS	*- FS
9	1	*FRONT BUMPER CARRIER	Dented	733.00 FS	*586.00 FS
10	1	*FRONT BUMPER FOAM FILLER PIECE	Broken	113.00 FS	*90.40 FS
11	1	*FRONT BUMPER COVER	Broken	116.00 FS	*92.40 FS
12	1	*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
13	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	34.00 FS	*- FS
14	1	*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
15	1	*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
16	1	*LOCK CARRIER BRACKET	Bent	125.00 FS	*100.00 FS
17	2	*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	52.00 FS	*- FS
18	2	*FRONT PARKING AID SENSOR - LH / RH	Not Necessary	462.00 FS	*- FS
19	4	*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
20	1	*HORN - LH HIGH TONE	Not Necessary	37.00 FS	*- FS
21	2	*SPRING SHACKLE - LH / RH	Not Necessary	52.00 FS	*- FS
22	1	*BONNET	Dented	2,554.00 FS	*2,043.20 FS
23	1	*BONNET ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
24	2	*BONNET LID HINGE - LH / RH	Not Necessary	554.00 FS	*- FS
25	1	*BONNET IMPACT PROTECTION - CENTRE / LH / RH (3PCS)	Necessary	75.00 FS	*59.44 FS
26	2	*BONNET STRIKER - LH / RH	Not Necessary	92.00 FS	*- FS
27	2	*BONNET LID LOCK	Not Necessary	391.00 FS	*- FS
28	2	*FLAT CONNECTOR HOUSING	Not Necessary	24.00 FS	*- FS
29	1	*BONNET BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
30	1	*BONNET BOWDEN CABLE	Bent	53.00 FS	*41.68 FS
31	1	*BONNET RELEASE LEVER	Not Necessary	12.00 FS	*- FS
32	1	*LED HEADLIGHT - LH / RH	O/S Broken	14,174.00 FS	*5,669.60 FS
33	2	*LIFT CYLINDER - LH / RH	Not Necessary	384.00 FS	*- FS
34	1	*HEADLIGHT CORRUGATED PIPE	Not Necessary	83.00 FS	*- FS
35	2	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	50.00 FS	*- FS
36	2	*RADIATOR UPPER AIR GUIDE - LH / RH	Broken	22.00 FS	*8.32 FS
37	2	*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS
38	1	*RADIATOR AIR GUIDE - LOWER	Not Necessary	19.00 FS	*- FS
39	1	*AIR INTAKE AIR DUCT	Not Necessary	19.00 FS	*- FS
40	1	*AIR INTAKE AIR GUIDE	Not Necessary	48.00 FS	*- FS
41	1	*AIR INTAKE FILTER	Not Necessary	339.00 FS	*- FS
42	1	*AIR INTAKE HOSE	Not Necessary	85.00 FS	*- FS
43	1	*AIR MASS METRE	Not Necessary	533.00 FS	*- FS
44	1	*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
45	1	*SUNDRIES	Necessary	400.00 FS	*81.68 FS
46	1	*FRONT BUMPER REINFORCEMENT BRACKET LHS	Bent	165.20 FS	*165.20 FS
47	1	*FRONT BUMPER REINFORCEMENT BRACKET RHS	Bent	165.20 FS	*165.20 FS
48	1	*EXTERNAL TEMPERATURE BRACKET	Necessary	13.04 FS	*13.04 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*AIRCOND CONDENSER	Dented	454.00 FS	*454.00 FS
50	1		*HORN - RH LOW TONE	Not Necessary	262.00 FS	*- FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	27,253.44	12,348.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND RENEW AIRCOND CONDENSER, PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	960.00	960.00
6	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE FRONT BUMPER REINFORCEMENT BRACKETS RENEWAL	New	2,100.00	1,000.00
7	TO REPAIR RHS FRONT FENDER	New	700.00	250.00
8	TO RESPRAY RHS FRONT FENDER	New	900.00	550.00
Gross Labour Cost (S\$)			10,132.00	5,782.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >