Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020131/ADA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SKZ7279A Insured Vehicle No: SGH608Y

Date of Loss: 10/11/2019 Nature of Claim: TP Claim No: 9057651981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ7279A

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 HIDDEN

 Reg. Date:
 01/02/2016 (Man. Year: 2016)
 Chassis No:
 RU11108585

 Colour:
 Blue
 Odometer:
 40051 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,976.00	3,585.40	3,390.60	48.60
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,320.00	1,600.00	2,720.00	62.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	11,296.00	5,185.40	6,110.60	54.10
	+ GST 7.00/7.00% (S\$)	790.72	362.98	427.74	54.10
	Nett Amount (S\$)	12,086.72	5,548.38	6,538.34	54.10
					

+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$) 856.00 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 6,406.38

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 14/11/2019 Inspected At: BLK 3007 UBI ROAD 1 #01-450

SINGPORE 408700

Repairer: Jack Cars Enterprise Pte Ltd

(HQ)

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: CHAN JIA LE

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,000.00 FL	*1,000.00 FL
2	1		*REAR BOOT INNER COVER	Cracked	780.00 FL	*286.00 FL
3	1		*REAR BOOT GARNISH	Not Necessary	250.00 FL	*-FL
4	1		*REAR BUMPER	Deformed	650.00 FL	*650.00 FL
5	1		*SIDE PAD -LEFT	Not Necessary	450.00 FL	*-FL
6	1		*SIDE PAD -RIGHT	Not Necessary	450.00 FL	*-FL
7	1		*LEFT TAILLAMP -INNER	Cracked	830.00 FL	*485.00 FL
8	1		*LEFT TAILLAMP -OUTER	Cracked	980.00 FL	*385.00 FL
9	1		*REAR END PANEL	Repair	1,100.00 FL	*- FL
10	1		*REAR END PANEL TOP COVER	Cracked	190.00 FL	*190.00 FL
11	1		*REAR END PANEL TOP COVER (METAL)-AFTER MARKET	Bent	320.00 FL	*320.00 FL
12	1		*BOOT LOCK	Damaged	200.00 FL	*200.00 FL
13	1		*WEATHERSTRIP	Cut	250.00 FL	*250.00 FL
14	1		*SPARE TYRE COMPARTMENT SPONGE	Deformed	420.00 FL	*287.00 FL
15	1		*VEZEL EMBLEM	Necessary	85.00 FS	*45.00 FS
16	1		*HONDA EMBLEM	Not Necessary	95.00 FS	*-FS
17	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
18	1		*RELAY SENSOR	Cracked	180.00 FS	*68.00 FS
19	1		*CLIPS	Necessary	100.00 FS	*30.00 FS
F=Fra	ınchise	part. S=S	SpcNett. L=ListItemDisc.			
			- List Item Discount on L Items 2	Sub Total (S\$)	8,550.00 1,574.00	4,396.00 810.60
			1,574.00	010.00		
				Total Parts (S\$)	6,976.00	3,585.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	600.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,800.00	600.00
3	TO CHECK LIGHTING SYSTEM WIRING & REWIRE	New	250.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	120.00	80.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	/ New	180.00	60.00
6	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	120.00
7	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	New	150.00	50.00
8	ANTI RUST TREATMENT	New	120.00	60.00
	Gross Labour Cost (S\$)		4,320.00	1,600.00
			<u></u>	

< END OF ESTIMATES >

Report was unsubmitted during this print-out.