

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020135/AES3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100036598-12

Claimant Vehicle No : SLC2823X **Insured Vehicle No :** SGX2175G

Date of Loss: 11/11/2019 Nature of Claim: TP Claim No: 5310000726SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2823X		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	HIDDEN
Reg. Date:	01/05/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W40J004136
Colour:	Silver	Odometer:	64530 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,427.51	456.75	970.76	68.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	730.00	1,040.00	58.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,197.51	1,186.75	2,010.76	62.89
Approved Total (Overridden) (S\$)		950.00		
(S\$)	3,197.51	950.00	2,247.51	70.29
+ GST 7.00/7.00% (S\$)	223.83	66.50	157.33	70.29
Nett Amount (S\$)	3,421.34	1,016.50	2,404.84	70.29
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,264.50		

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At:

1 KAKI BUKIT AVE 6 #02-33/34

Repairer: Precise Auto Services (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deformed	1,678.90 FL	*579.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	121.25 FL	*- FL
3	8		*REAR BUMPER CLIPS	Necessary	103.20 FL	*30.00 FL
					Sub Total (\$\$)	1,903.35
					- List Item Discount on L Items 25.00/25.00% (\$\$)	475.84
					Total Parts (\$\$)	1,427.51

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
2	TO RESPRAY AFFECTED AREAS	New	780.00	400.00
3	TO CHECK COMPUTER WHEEL ALIGNMENT	New	120.00	80.00
4	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR LH FENDER ,REAR LH SPORT RIM & ALIGNED ALL PARTS	New	750.00	200.00
Gross Labour Cost (\$)			1,770.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >