

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III19020143/UGA3Q2**Date:** 28/05/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJP5599D	Insured Vehicle No :	SHD3703U
Date of Loss: 31/10/2019	Nature of Claim: TP	Claim No: MCT19100757

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP5599D		
Make & Model:	MERCEDES-BENZ GLE400, 3.0 4MATIC (R20 LED SR) (A)	Engine No:	27682130250195
Reg. Date:	27/01/2016 (Man. Year: 2015)	Chassis No:	WDC2923562A008278
Colour:	Black	Odometer:	106303 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/50 R20	Rear Tyre Size:	275/50 R20
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,633.90	776.94	2,856.96	78.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	520.00	540.00	50.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,693.90	1,296.94	3,396.96	72.37
+ Car Rental (1.0 x S\$120.00/day) (S\$)		120.00		
		1,416.94		
		1,410.00		

INSPECTION

Date of Assignment:	13/11/2019	
Date Inspected:	13/11/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)
Parts: 192	MERCEDES-BENZ GLE400 3.0 4MATIC (R20 LED SR) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP5599D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,615.45 F	*- FL
2	1		*REAR BUMPER LOWER GARNISH	Serviceable	788.50 F	*- FL
3	1		*REAR BUMPER LOWER CHROME	Scratched / Cracked	815.45 F	*743.32 FL
4	1		*REAR BUMPER LICENCE PLATE GARNISH	Deformed / Torn	99.50 F	*75.50 FL
5	1		*REAR BUMPER PDC SENSOR	Serviceable	265.00 F	*- FL
6	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,633.90	858.82
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	81.88
Total Parts (\$\$)	3,633.90	776.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	20.00
2	TO DISMANTLE & REFIX PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	380.00	250.00
5	TO PUTTY & SPRAY PAINTING	New	450.00	200.00
			Gross Labour Cost (\$)	520.00
			1,060.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >