



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2003152
INV Date 14/04/2020
Reference CC4/LPC19020150/Uea3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBA 863Y
Insured Veh. YN 7573Y
Claim No. 19/19/19/VC05/022632
Policy No. Z19VC05001738
Accident Date 21/10/2019
Inspection Date 13/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19020150/Uea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-04-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7573Y	Veh. Inspected	GBA 863Y
Policy No.	Z19VC05001738	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022632	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	12/11/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JTFAT35Y703000353	Colour	BLUE
Odometer	727643	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	155 R12	RADIAL	5 mm
L/H Front Tyre	155 R12	RADIAL	5 mm
R/H Rear Tyre	155 R12 (D)	RADIAL	5/5 mm
L/H Rear Tyre	155 R12 (D)	RADIAL	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/10/2019	Inspection Date	13/11/2019
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 863Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL GATE	TO REPAIR SEE LABOUR	1,237.20	-
1	REAR TAIL GATE SIDE LOCK -RH	NOT NECESSARY	78.20	-
1	REAR TAIL GATE EMBLEM (TOYOTA)	NOT NECESSARY	120.20	-
1	REAR SIDE GATE -RH	BADLY DENTED / CRACKED	2,346.20	1,685.10
	LESS 25% DISCOUNT		-945.45	-421.28
			2,836.35	1,263.82
SPECIAL NETT ITEMS				
1	REAR TAIL GATE STICKER 70KM/H (SN)	NOT NECESSARY	20.00	-
1	REAR TAIL GATE STICKER -13 PAX (SN)	NOT NECESSARY	20.00	-
1	REAR TAIL GATE ALUMINIUM PLATE (SN)	NOT NECESSARY	650.00	-
			690.00	-
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL GATE .		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
			1,600.00	800.00
GRAND TOTAL			5,126.35	2,063.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CC4/LPC19020150/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 863Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 863Y

RE-INSPECTION

