



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004413
INV Date 22/06/2020
Reference CC3/CTI19020160/Qka3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 4165X
Insured Veh. CB 9888A
Claim No. SNM19D205349C02/8(tkl)
Policy No. DMB1SN1664221903
Accident Date 08/11/2019
Inspection Date 11/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CC3/CTI19020160/Qka3s2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 22-06-2020
	Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 9888A	Veh. Inspected	SHC 4165X
Policy No.	DMB1SN1664221903	Coverage (\$)	0.00
Claim No.	SNM19D205349C02/8(tkl)	Excess (\$)	0.00
Assign From		Assign Date	11/11/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1795
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U505706910	Colour	MAROON
Odometer	687843	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEUTON	5 mm
L/H Front Tyre	195/65 R15	NEUTON	5 mm
R/H Rear Tyre	195/65 R15	NEUTON	5 mm
L/H Rear Tyre	195/65 R15	NEUTON	5 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	08/11/2019	Inspection Date	11/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4165X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	MIRROR ASSY, LH (DISC 25%)	JAMMED	1,224.90	918.68
1	COVER, OUTER MIRROR, LH (DISC 25%)	SCRATCHED	107.40	80.55
1	FENDER RR/LH (DISC 25%)	DENTED	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%)	NECESSARY	168.10	126.08
1	BUMPER FRT (DISC 25%)	CRUSHED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	COVER, FR BUMPER HOLE LH (DISC 25%)	SCRATCHED	18.50	13.88
1	FENDER FRT/LH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	MIRROR LAMP LH (DISC 10%)	SCRATCHED	65.30	58.77
1	HEAD LAMP LH (DISC 10%)	SCRATCHED	945.20	850.68
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	HINGE UPPER LHF, DOOR	SERVICEABLE	80.50	-
1	HINGE LOWER LHF, DOOR	SERVICEABLE	90.10	-
1	CHECK ASSY, FR DOOR,	SERVICEABLE	150.30	-
1	MOULDING BODY, LH	SERVICEABLE	673.60	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SIDE RETAINER	SERVICEABLE	94.80	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-

Report Ref No. CC3/CTI19020160/Qka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GRILLE RADIATOR LOWER NO.2	SERVICEABLE	94.60	-
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	-
1	BRACKET, FR TURN CENTER LH	SERVICEABLE	58.20	-
1	BRACKET, FR TURN LOWER LH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN UPPER LH	SERVICEABLE	24.40	-
1	LENS & BODY, FR TURN LH	SERVICEABLE	511.80	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	FENDER PROTECTOR FRT/LH UPPER	SERVICEABLE	46.10	-
1	PROTECTOR, FRONT FENDER SIDE PANEL LH	SERVICEABLE	114.50	-
1	TYRE	SERVICEABLE	126.74	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	-
1	FENDER LINER PAD, FR WHEEL, LH	NOT NECESSARY	49.30	-
1	DOOR FRT/LH	TO REPAIR SEE LABOUR	894.40	-
1	DOOR RR/LH	TO REPAIR SEE LABOUR	954.50	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	WHEEL DISC, FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	SOLAR FILM (SN)	NECESSARY	125.00	125.00
1	BUMPER SUPPORT F/LH (DISC 25%) (ADDITIONAL)	CRUSHED	78.40	57.30
1	BUMPER LIP FRT (DISC 25%) (ADDITIONAL)	CRACKED	139.60	104.70
1	BUMPER FRT ABSORBER LOWER (DISC 25%) (ADDITIONAL)	CRUSHED	127.70	95.78
1	FENDER LINER FRT/LH (NOT NECESSARY) (ADDITIONAL)	OLD DAMAGE	171.70	-
1	FENDER LINER PAD, FR WHEEL, LH (NOT NECESSARY) (ADDITIONAL)	OLD DAMAGE	49.30	-
			15,307.14	4,207.98
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF DOOR FRT/LH; DOOR RR/LH; BUMPER REAR AND WHEEL DISC, FRONT.		1,014.00	800.00
	SPRAY PAINT.		3,168.00	1,290.00

Report Ref No. CC3/CTI19020160/Qka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO TRANSFER DOOR MECHANISM.		240.00	80.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	50.00
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	80.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT FUEL TANK.		120.00	80.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,782.00	2,500.00
	GRAND TOTAL		21,089.14	6,707.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00

Report Ref No. CC3/CT119020160/Qka3s2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.